FINDING OF NECESSITY



University Blvd/Merrill/Arlington Rd Redevelopment Area

August 3, 2015



> Ava Dr

FINDING OF NECESSITY

for the creation of the

University Blvd/Merrill/Arlington Rd Redevelopment Area

Prepared for: The City of Jacksonville



Prepared by:



830 North, Suite 402 Ponte Vedra Beach, FL, 32082

In association with:



TABLE OF CONTENTS

E	(ECUTIVE SUMMARY	1
1.	OVERVIEW AND PURPOSE	2
	1.1 BACKGROUND	2
	1.2 THE COMMUNITY REDEVELOPMENT ACT	2
	1.3 FINDINGS OF NECESSITY	3
	1.4 REDEVELOPMENT PROCEDURES	4
2.	UNIVERSITY BLVD/MERRILL/ARLINGTON REDEVELOPMENT AREA	6
	2.1. EXISTING CONDITIONS	6
	2.2 STUDY AREA DESCRIPTION	7
	2.3 BOUNDARY	7
	2.4 RDA EXISTING LAND USE	9
	2.5 RDA FUTURE LAND USE (2030 COMPREHENSIVE PLAN)	12
	2.6 CONDITIONS OF STRUCTURES	14
	2.7 LAND USES	16
	2.8 BICYCLE AND PEDESTRIAN FACILITIES	21
	2.9 STORMWATER FACILITIES	22
	2.10 OVERHEAD UTILITIES	24
	2.11 POTABLE WATER AND SANITARY SEWER FACILITIES	25
	2.12 OCCURRENCES OF CRIME	27
3.	BLIGHTED AREA CONDITIONS ANALYSIS	29
Αl	PPENDIX A: DETAILED BOUNDARY MAPS	32
ΑI	PPENDIX B: RDA SURVEY	42

EXECUTIVE SUMMARY

The City of Jacksonville, as part of its Renew Jacksonville campaign, desires to create a Community Redevelopment Area and Master Plan for three major commercial corridors University Boulevard, Merrill and Arlington Roads, within the Arlington community. The overall area has been subject to several recent redevelopment planning efforts including:

- ✓ Arlington Town Center Vision Plan 2005
- ✓ Old Arlington Neighborhood Action Plan 2007
- ✓ Greater Arlington/Beaches Vision Plan 2010,
- ✓ Ongoing Jacksonville Electric Authority (JEA), Jacksonville Transportation Authority and Florida Department of Transportation studies,
- ✓ The area has been designated an Urban Priority Area in the City's 2030 Comprehensive Plan which designates areas in need of redevelopment.

Per Florida Statute, Chapter 163, Part III, before the City can create a Community Redevelopment Area, Community Redevelopment Plan and Redevelopment Trust Fund; it must first determine that the proposed Redevelopment Area (RDA) shows evidence of slum or blight as defined by the Statute. The means of providing such evidence is Finding of Necessity (FoN) Report. The Finding of Necessity is the first of several steps that must be undertaken before the proposed RDA is approved as a Community Redevelopment Area.

Chapter 163, Part III, lists a number of criteria that must be met in order for an area to be designated as "Slum or Blighted". To be defined as "Slum" an area needs to meet one or more of the three definitions of Slum; or meet two or more of the fourteen (14) conditions of "Blight". The Statute also states that in the case that all taxing districts that are subject to the Statute are in agreement that the area is blighted, only one blight criteria needs to be met. The fact that the City of Jacksonville is a consolidated City/County and that it is the only Taxing Authority subject to this effort; then only one condition of blight needs to be defined. That said, this Finding of Necessity Report while not finding "Slum" conditions, has identified a minimum of six (6) of the 14 conditions necessity to define the proposed RDA as "Blighted".

The six (6) conditions of blight are:

- 1) Predominance of defective or inadequate street layout, parking facilities, roadways, bridges, or public transportation facilities. (Section 163.340 [8] a., F.S.)
- 2) Faulty lot layout in relationship to size, adequacy, accessibility, or usefulness. (Section 163.340 [8] c, F.S.)
- 3) Unsanitary or unsafe conditions. (Section 163.340 [8] d, F.S.)
- 4) Deterioration of site or other improvements. (Section 163.340 [8] e, F.S.)
- 5) Inadequate or outdated building patterns (Section 163.340 [8] f, F.S.)
- 6) Incidents of Crime. (Section 163.340 [8] j, F.S.)

1. OVERVIEW AND PURPOSE

The purpose of this report is document blight conditions that exist within the proposed Redevelopment Area to comply with **Sections 163.335**, **163.340**, **and 163.355**, **F.S.** The study focuses on existing conditions and regulatory constraints to development within the Redevelopment Area and its ability to eliminate or prevent the development or spread of blight within the Arlington; specifically the University Blvd, Merrill Road and Arlington Road commercial corridors.

1.1 BACKGROUND

This analysis focuses on the existing physical characteristics and support infrastructure of the Redevelopment Area and its ability to generate economic return and local tax revenues. As a general matter, areas that are in a state of physical decline, are underutilized, or are improperly deployed, limit the City's ability to remain competitive in a larger economic context, ultimately affecting its financial condition and its level of services.

Real property assets and the supportive infrastructure that are physically or functionally deteriorated or do not meet contemporary development standards are constrained in their ability to generate adequate tax revenues necessary to improve these conditions. As such, their physical character and utility are key factors in determining a community's economic health. The lack of real property value in these areas result in insufficient ad valorem revenue to improve these areas and necessary improvements are essentially subsidized by other areas of the City. This inequity and shift in the tax burden requires the City to consider additional tax revenues to improve these declining areas, with those revenues being generated in the area which requires improvement.

This analysis relies substantially on interpretations of government data, visual inspections of properties, and geographic information system data. While the County's tax roll data is assumed to be reliable, this analysis cannot guarantee its accuracy.

The State of Florida recognizes the potentially negative impacts to cities created by areas that may be inferior to community standards and quantitative and value-based expectations. These areas tend to be unsustainable and, ultimately, may become a burden on the jurisdiction in which they exist. The Act was created and adopted through Chapter 163, Part III, F.S. (Community Redevelopment Act of 1969), as a tool to assist in remedying areas to improve the general public welfare and local tax base and for redevelopment of specific geographic areas. The Act declares that the rehabilitation, conservation, or redevelopment of deteriorated and distressed areas are necessary in the interest of public health, safety, morals, and welfare.

To qualify for establishment under the provisions of the Act, a City must prepare a "Finding of Necessity" to determine that the rehabilitation, conservation, or redevelopment of an area meets criteria broadly described as "slum" or "blighted" and is necessary in the interest of the health, safety, morals, or welfare of the residents of the community. These terms carry specific statutory references and qualifiers distinct from their common understanding and use.

This Finding Report is intended to be consistent with the statutory requirements for establishing the Redevelopment Area pursuant to Chapter 163, Part III, F.S. Generally, this Redevelopment Area appears to contain similar conditions—infrastructure deficiencies, development hardships, and stunted investment—as those found in other existing community redevelopment areas within Florida.

1.2 THE COMMUNITY REDEVELOPMENT ACT

The purpose of the Community Redevelopment Act of 1969 (the "Act") is to assist local governments in preventing and/or eliminating blighted conditions detrimental to the sustainability of economically and socially vibrant communities. The following paragraphs describe those blighting conditions, their specific effects and the intentions of the community redevelopment system as a tool for implementing policy and programs as they apply to the Study Area.

Section 163.335(1), F.S. ...slum and blighted areas which constitute a serious and growing menace, injurious to the public health, safety, morals, and welfare of the residents of the state; that the existence of such areas contributes substantially and increasingly to the spread of disease and crime, constitutes an economic and social liability imposing onerous burdens which decrease the tax base and reduce tax revenues, substantially impairs or arrests sound growth, retards the provision of housing accommodations, aggravates traffic problems, and substantially hampers the elimination of traffic hazards and the improvement of traffic facilities; and that the prevention and elimination of slums and blight is a matter of state policy and state concern in order that the state and it counties and municipalities shall not continue to be endangered by areas which are focal centers of disease, promote juvenile delinquency, and consume an excessive proportion of its revenues because of the extra services required for police, fire, accident, hospitalization, and other forms of public protection, services, and facilities.

Section 163.335(2), F.S....slum or blighted areas, or portions thereof, may require acquisition, clearance, and disposition subject to use restrictions, as provided in this part, since the prevailing condition of decay may make impracticable the reclamation of the area by conservation or rehabilitation; that other areas or portions thereof may, through the means provided in this part, be susceptible of conservation or rehabilitation in such a manner that the conditions and evils enumerated may be eliminated, remedied, or prevented; and that salvageable slum and blighted areas can be conserved and rehabilitated through appropriate public action as herein authorized and the cooperation and voluntary action of the owners and tenants of property in such areas.

Section 163.335(3), F.S. ...the powers conferred by this part are for public uses and purposes for which public money may be expended and police power exercised, and the necessity in the public interest for the provisions herein enacted is declared as a matter of legislative determination.

Section 163.335(5), **F.S.** ...the preservation or enhancement of the tax base from which a taxing authority realizes tax revenues is essential to its existence and financial health; that the preservation and enhancement of such tax base is implicit in the purposes for which a taxing authority is established; that tax increment financing is

an effective method of achieving such preservation and enhancement in areas in which such tax base is declining; that community redevelopment in such areas, when complete, will enhance such tax base and provide increased tax revenues to all affected taxing authorities, increasing their ability to accomplish their other respective purposes; and that the preservation and enhancement of the tax base in such areas through tax increment financing and the levying of taxes by such taxing authorities therefore and the appropriation of funds to a redevelopment trust fund bears a substantial relation to the purposes of such taxing authorities and is for their respective purposes and concerns.

1.3 FINDINGS OF NECESSITY

The Finding of Necessity, as set forth in **Section 163.355**, **F.S.** is an assessment of the Study Area that provides the evidence of blight and need for redevelopment due to the area's deficiencies in attracting market-based investment of the same rate and quality as surrounding areas and the City as a whole. The analysis relies upon a variety of empirical data and observations by the City of all the parcels within the Study Area in determining the existence of slum or blighted conditions as defined by criteria outlined in **Section 163.340**, **F.S.**

If an area is deemed blighted under the Act, a resolution may be adopted by the City Council finding that there are indeed such conditions within the defined study area, and that the repair, rehabilitation, and/or redevelopment of such areas is in the interest

To qualify for establishment under the provisions of the Act, a City must prepare a "Finding of Necessity" to determine that the rehabilitation, conservation, or redevelopment of an area meets criteria broadly described as "slum" or "blighted" and is necessary in the interest of the health, safety, morals, or welfare of the residents of the community. As defined by **Section 163.340**, **F.S.**, these terms carry specific statutory references and qualifiers distinct from their common understanding and use.

Section 163.340 (7) "slum area" means an area having physical or economic conditions conducive to disease, infant mortality, juvenile delinquency, poverty, or crime because there is a predominance of buildings or improvements, whether residential or non-residential, that are impaired by reason of dilapidation, deterioration, age, or obsolescence, and exhibiting one or more of the following factors:

- a) Inadequate provision for ventilation, light, air, sanitation, or open spaces;
- b) High density of population, compared to the population density of adjacent areas within the county or municipality, and overcrowding, as indicated by government-maintained statistics or other studies and the requirements of the Florida Building Code; or
- c) The existence of conditions that endanger life or property by fire or other causes.

Section 163.340 (8) "Blighted area" means an area in which there are a substantial number of deteriorated, or deteriorating structures, in which conditions, as indicated by government-maintained statistics or other studies, are leading to economic distress or endanger life or property, and in which two or more of the following factors are present:

- a) Predominance of defective or inadequate street layout, parking facilities, roadways, bridges, or public transportation facilities:
- b) Aggregate assessed values of real property in the area for ad valorem tax purposes have failed to show any appreciable increase over the 5 years prior to the finding of such conditions;
- c) Faulty lot layout in relation to size, adequacy, accessibility, or usefulness;
- d) Unsanitary or unsafe conditions;
- e) Deterioration of site or other improvements;
- f) Inadequate and outdated building density patterns;
- g) Falling lease rates per square foot of office, commercial, or industrial space compared to the remainder of the county or municipality;

- h) Tax or special assessment delinquency exceeding the fair value of the land:
- i) Residential and commercial vacancy rates higher in the area than in the remainder of the county or municipality;
- i) Incidence of crime in the area higher than in the remainder of the county or municipality;
- Fire and emergency medical service calls to the area proportionately higher than in the remainder of the county or municipality;
- A greater number of violations of the Florida Building Code in the area than the number of violations recorded in the remainder of the county or municipality;
- m) Diversity of ownership or defective or unusual conditions of title which prevent the free inalienability of land within the deteriorated or hazardous area; or
- n) Governmentally owned property with adverse environmental conditions caused by a public or private entity.

However, the term "blighted area" also means any area in which at least one of the factors identified in (a) through (n) are present and all taxing authorities subject to Section 163.387(2) (a), F.S., agree, either by Interlocal agreement or agreements with the agency or by resolution, that the area is blighted. Such agreement or resolution should determine only that the area is blighted. For purposes of qualifying for the tax credits authorized in Chapter 220, F.S., "blighted area" means an area as defined in this subsection.

The statutes further provide that a "community redevelopment area" is defined as "...a slum area, a blighted area, or an area in which there is a shortage of housing that is affordable to residents of low or moderate income, including the elderly, or a coastal and tourist area that is deteriorating and economically distressed due to outdated building density patterns, inadequate transportation and parking facilities, faulty lot layout or inadequate street layout, or a combination thereof which the governing body designates as appropriate for community redevelopment. For community redevelopment agencies created after July 1, 2006, a community redevelopment area may not consist of more than 80 percent of a municipality." (Sec. 163.340 [10], F.S.)

1.4 REDEVELOPMENT PROCEDURES

If the City Council accepts this report and adopts the Finding of Necessity Resolution, they must then comply pursuant to **Section 163.356** to prepare a Redevelopment Plan for the Area. The Redevelopment Plan must provide physical information on the redevelopment area and identify potential project types that can diminish or eradicate the specified blighted conditions.

Per Statute, before the City Commission Council can adopt any resolution or enact any ordinance to approve a Redevelopment Plan or establish a Redevelopment Trust Fund, the City Council must provide public notice of proposed actions to each taxing authority which as the power to levy ad valorem taxes within the RDA boundaries, pursuant to Section 163.346, which states that before the governing body adopts any resolution or enacts any ordinance required under Section 163.355, Section 163.356, Section 163.357, or Section 163.387; creates a community redevelopment agency; approves, adopts, or amends a community redevelopment plan: or issues redevelopment revenue bonds under Section 163.385, the governing body must provide public notice of such proposed action pursuant to Section 125.66(2) or Section 166.041(3)(a) and, at least 15 days before such proposed action, mail by registered mail a notice to each taxing authority which levies ad valorem taxes on taxable real property contained within the geographic boundaries of the redevelopment area.

Such notice alerts these taxing authorities to any possible changes in their budgets as a result of a redevelopment action. As a policy matter, it is assumed that the entities listed within Table 1 will receive notice of any actions stemming from either this analysis or subsequent initiatives should they be authorized under the terms of the Act. Some of these entities may be exempt pursuant to **Section 163.387(2)** (c),F.S. Should the FoN be approved, the CRA is not requesting any contribution from the Duval County School Board, Florida Inland Navigation nor St. Johns River Water Management District.

Table 1. Duval County Taxing Authorities

Duval County Taxing Authorities

City of Jacksonville
Duval County General Government
Duval County School Board
Florida Inland Navigation District
St. Johns River Water Management District

Under the Act, a Redevelopment Plan is subjected to a compliance review conducted by the Planning Commission before it can be submitted to the City Council for approval. The Commission has up to sixty (60) days to review the Redevelopment Plan as to its conformity with the City's 2030 Comprehensive Plan and provide comments to the Community Redevelopment Agency. After receiving recommendations from the Planning Commission, the City Council, as the governing body, shall hold a public hearing on the approval of a Redevelopment Plan.

The next step under the Act is the creation of a **Redevelopment Trust Fund for the University Blvd/Merrill/Arlington Rd CRA**. The most recent certified real property tax roll prior to the effective date of the ordinance will be used to establish the tax base (the "Base Year") in order to calculate the tax increment. In the present case, the assumed timetable to move forward suggests that the calculation of the tax increment will rely on the 2014 certified rolls.

After implementation of the redevelopment procedures described above, the Redevelopment Trust Fund becomes funded upon the availability of tax increment revenues. Tax increment revenues become available as the result of increased property assessments associated with new development and redevelopment within the RDA beyond those of the Base Year. Funds allocated to and deposited into the trust account are used by the Community Redevelopment Agency to finance or refinance any community redevelopment it undertakes pursuant to the approved Redevelopment Plan.

2. UNIVERSITY BLVD/MERRILL/ ARLINGTON REDEVELOPMENT AREA

2.1. EXISTING CONDITIONS

The Redevelopment Area (RDA) is confined to a specific area along and adjacent to University Boulevard, Merrill and Arlington Road corridors within the greater Arlington Community of the City of Jacksonville/Duval County, Florida. The Redevelopment Area is approximately 1,242 acres consisting of 1,302 parcels, which is 0.2 percent (.0023) of the total city area of 840 square miles. The Redevelopment Area is comprised of three major corridors located within the larger Arlington area whose boundaries are the St. Johns River to the West, Arlington Expressway to the South, Ft. Carolina Road to the North, and I-295 to the east (see Figure 1 and Figure 2, and Appendix B for legal description).

There have been numerous previous studies of this overall study area including:

- ✓ Town Center Vision Plan 2005
- ✓ Old Arlington Neighborhood Action Plan 2007
- ✓ Greater Arlington/Beaches Vision Plan 2010
- ✓ Ongoing JEA and JTA studies

The 2005 Town Center Vision Plan whose focus was largely on University Boulevard. The Plan noted that University Boulevard:

- √ "Is rapidly decaying and property values are declining"
- ✓ "Is facing economic and social degradation"
- ✓ "Is unsafe for pedestrians and schoolchildren"
- √ "Is blighted and needs trash removed"

The 2007 Old Arlington Neighborhood Action Plan also noted many concerns of blight related issues including²:

- ✓ Aesthetics concerns: "debris along roadways, unkempt homes needing repair, telephone poles and overhead power lines, vacant homes"
- ✓ "Lack of investment"
- √ "Vacant commercial properties"
- √ "Adequate drainage is missing"
- ✓ "Adequate water and sewer is missing ...deteriorating septic systems"

The 2010 Greater Arlington/Beaches Vision Plan noted:3

- ✓ The need for median landscaping along corridors
- ✓ "Create more crime free multi-family housing"
- ✓ "Town and Country Shopping Center needs to be redeveloped"
- ✓ "Abandoned and underutilized commercial areas need to be improved"
- ✓ "Create better bike and pedestrian connections"

Based in part by these past studies, the Redevelopment Area boundary was delineated due to blighted conditions, such as underutilized land uses, faulty lot layout, deteriorating building and site conditions, vacant commercial buildings, congested and unsafe roadways, lack of investment, inadequate and deteriorating infrastructure, crime and safety conditions and overall aesthetic conditions. The declining nature of the business community along these corridors, as well as conflicting land uses, have contributed to the blight conditions within this area boundary.

- 1 Town Center Vision Plans, University Boulevard, page 7
- The Old Arlington Neighborhood Action Plan, page 38
- 3 Greater Arlington/Beaches Vision Plan, Appendix A

2.2 STUDY AREA DESCRIPTION

As discussed, the proposed RDA is primarily oriented to the three commercial corridors in the Greater Arlington area and while connect to various neighborhoods, it does not include the totality of any of the affected neighborhoods of: Monterey, Arlington, Lake Lucina, Arlington Minor, or University Park.

2.3 BOUNDARY

The following graphic shows the proposed boundaries for the University Blvd/Merrill/Arlington Rd RDA.




Figure 1: Proposed RDA Boundaries










Figure 2: Aerial of RDA Area - Parcels







2.4 RDA EXISTING LAND USE

Based on the 2030 City of Jacksonville Comprehensive Plan, the majority of the RDA falls within an Urban Priority Area (UPA) which is intended "to encourage revitalization and the use existing infrastructure through redevelopment and infill development". As shown in Table 2, the largest use of land is Institutional which comprise 33 parcels (the largest use is the campus of Jacksonville University). Residential use comprise the largest number of parcels (812) which account for 338 acres, followed by commercial parcels (260) or 206 acres, vacant parcels (174) or 111 acres, government parcels (8) accounting for 47 acres and 15 industrial parcels occupying 8.5 acres. As better shown in the detail maps contained within the Appendix, there is a lot of conflicting residential and commercial land uses within the RDA, primarily along Merrill Road.




Figure 3: Jacksonville Development Area










Figure 4: RDA Existing Land Use







As shown in Table 2, the largest use of land is Institutional which comprise 33 parcels (the largest use is the campus of Jacksonville University). Residential use comprise the largest number of parcels (812) which account for 338 acres, followed by commercial parcels (260) or 206 acres, vacant parcels (174) or 111 acres, government parcels (8) accounting for 47 acres and 15 industrial parcels occupying 8.5 acres. As better shown in the detail maps contained within the Appendix, there is a lot of conflicting residential and commercial land uses within the RDA, primarily along Merrill Road.

Table 2: Proposed RDA Existing Land Use

Type	Parcels	Acreage
Institutional	33	371.3
Residential	812	338.2
Commercial	260	205.8
Vacant	174	110.9
Government	8	47.1
Industrial	15	8.5

Source: (City of Jacksonville - May 2015)

2.5 RDA FUTURE LAND USE (2030 COMPREHENSIVE PLAN)

As shown in Figure 5, the City's 2030 Future Land Use Map designed nine (9) Future Land Use districts within the RDA.




Figure 5: RDA Future Land Use







As shown in Table 3, the four largest future land uses within the RDA are: RPI, CGC, PBF and MDR. Assuming that the FoN is approved and the future CRA Redevelopment Plan is adopted, the CRA will probably have a different Future Land Use Plan which would require an amendment to the City's 2030 Future Land Use Map.

Table 3: Proposed RDA Future Land Use

Future Land Use	Parcels	Acreage
BP - Business Park	1	7.2
CGC - Community/Gen. Commercial	307	281.7
CSV - Conservation	1	3
LDR - Low Density Residential	252	98.1
MDR - Medium Density Residential	486	214.6
NC - Neighborhood Commercial	30	48.4
PBF - Public Buildings and Facilities	3	231.3
ROS - Recreation and Open Space	1	6.5
RPI - Residential-Professional-Institutional	221	350.9

Source: City of Jacksonville Comprehensive Plan, May 2015

Having identified the Redevelopment Area as a unified and homogenous area, SPG reassessed and updated the blighted area conditions from the previous studies to consider the specific conditions that constitute slum or blight as indicated in the Community Redevelopment Act identified by the Florida Legislature, as described in **Section 163.340 (7) or (8), F.S.**, and described previously.

To determine whether there is sufficient evidence to prove and document slum and/or blighted conditions, existing conditions data from government statistics and other available data were collected and analyzed, together with field observations. The following describes the analysis of the existing conditions and finding of slum and/or blighted area conditions.

FINDING

Most of the RDA is contained within what the City's 2030 Comprehensive Plan states is an Urban Priority Area. Urban Priority Area designation is intended to identify and encourage areas in need of redevelopment and to employ urban development characteristics.



2.6 CONDITIONS OF STRUCTURES

To determine if there was a "substantial number of deteriorating or deteriorated structures" within the Redevelopment Area, involved an examination of code enforcement cases within the proposed RDA area. While some of the buildings are in sound condition with general maintenance of the structures, such as painting, pressure washing, landscaping, etc., being at issue, many of the buildings and sites are underused and discourage reinvestment in the community. Some of these conditions relate to improper or poor maintenance of yards and improvements and structural deterioration such as broken signs, and cracked driveways and sidewalks.











Code enforcement data is another good indicator of property/structure condition and ongoing maintenance. For the Redevelopment Area, five years of Code enforcement data were analyzed and are summarized in Table 4.

An inspection does not equal a violation. Inspection constitutes the code officer responding to a property. Once at the property, multiple violations can be cited on that property depending on the nature of the complaint. For example, a "regular" nuisance property can have one or two violations (overgrowth and/or trash & debris). A residential case can have 1-20 violations depending on the property.

Table 4: Code Inspections within Proposed RDA

Year	Code Inspections		
	RDA	Citywide	% RDA
2010	395	141,109	0.002799
2011	618	130,508	0.004735
2012	575	109,754	0.005239
2013	467	103,636	0.004506
2014	850	111,149	0.007647
2015 (thru May)	273	50,760	0.005378

RDA is equal to .00231 percent of the City's acreage

Source: City of Jacksonville Comprehensive Plan, May 2015

According to the City's Code Enforcement data, there was an increase in property deterioration, lack of maintenance, nuisances, and other physical decay between 2010 and 2014 within the Redevelopment Area. The City of Jacksonville is very conscious about enforcing Code violation issues and, to combat blight.

FINDING

This analysis demonstrates that there are "substantial number of deteriorating or deteriorated structures" within the Redevelopment Area ranging from improper or poor maintenance of yards and improvements and structural deterioration, such as broken signs, cracked driveways and sidewalks, and broken storm-water drainage systems, which also contribute to unsanitary or unsafe conditions.

These contributing factors serve as qualifying conditions for blighted area. Improper siting and placement of refuse collection creates unsanitary and unsafe conditions, which contribute to visual and physical blight. Lack of compliance with City regulatory and community design standards can contribute to the need for a focused community redevelopment emphasis. According to City staff, the only properties within the RDA that are currently in compliance with Zoning Code are "the CVS parcel located at the southeast corner of University and Merrill (at the JU entrance) and also those properties located on Merrill Road east of Townsend Boulevard. All other parcels in the study area that were developed prior to implementation of the revised development code in 1991 are substandard or deficient in relation to the current minimum landscape and/ or parking requirements, usually both".



2.7 LAND USES

The City of Jacksonville's existing land use, zoning, and future land use were used to reach a reasonable understanding of the pattern of development activity within the Redevelopment Area, identify whether existing land uses are permitted under current zoning regulations, assess whether neighboring uses are compatible with each other, and determine whether certain uses assist or deter development activity.

The existing land use and future land use within the Redevelopment Area are shown in Figure 1 and 2 and within Tables 2 and 3. A sustainable commercial development requires more than one acre to be viable. As shown most of the parcels within the RDA is less than one (1) acre in size.

Many of the land uses that once thrived have given way to uses that under-use existing sites. Some businesses have relocated, and buildings remain empty particularly in the older shopping center properties. There is a lack of a substantial commercial investment along all three corridors within the Redevelopment Area as witnessed by the amount of for sale or lease properties.







Residences still occupy commercially-zoned lands, creating non-conformities.









University Blvd/Merrill/Arlington Rd Findings of Necessity | 17 REVISED EXHIBIT 2 PAGE 20 OF 65

Changes to the land development regulations will be needed to address these issues; creating a new plan and zoning and urban design framework in the area will aid in attracting new development.





Most residentially-used lands have been zoned for other uses, such as commercial, professional, or office for many years, and a few conversions have occurred along all three corridors. In addition to the existing conflicts between residential and nonresidential uses, is increased vehicular traffic using the old residential curb cuts, which is a safety issue, as some vehicles are forced to back into traffic on all three corridors.







Another issue with the current parcel inventory is the number of County, City, institutional, and other land uses that are off the tax rolls in the Redevelopment Area.

FINDING

Even though the City's future land use and zoning are consistent and satisfy State of Florida's requirements, the parcels designated as commercial are inadequate in size and cannot accommodate the maximum allowable density/intensity under the present designations without property aggregation or variances. These old platted lands provide a parcel system that fosters outdated building patterns and inappropriate accessibility, contributes to poor drainage, and negates development of a sufficient size and type to produce overall community benefits.

FINDING

2.8 BICYCLE AND PEDESTRIAN FACILITIES

Field observations identified that many of the pedestrian and bicycle routes within the Redevelopment Area are defective or inadequate. There is limited formal pedestrian connection to city amenities, schools, or shopping and existing sidewalks are substandard with respect to current design and accessibility requirements. Few interior sites have a pedestrian connection to the commercial areas, and most residential neighborhoods are devoid of sidewalks.

There is also a lack of median landscaping (Arlington Road has the most landscaped medians which are east of Cesery Blvd), street trees, safe crosswalks, bikeways, and wayfinding signs, within the Redevelopment Area.

FINDING

The lack of a viable, comprehensive system of accessible sidewalks, bicycle facilities, and dedicated multimodal facilities, and the absence of streetscaping, pedestrian lighting, traffic calming devices, and wayfinding signage creates additional support for defective or inadequate street layout and roadways as well as unsafe conditions that contribute to physical and visual blight. This may hamper new investment opportunities and may contribute to further deterioration of the Redevelopment Area.







2.9 STORMWATER FACILITIES

A substantial portion of the Redevelopment Area exhibits poor drainage conditions as a result of outdated platted lands, historic construction techniques, and lack of sufficient stormwater management facilities and conveyances. Many of the existing developed sites pre-date current environmental and stormwater management requirements. Redevelopment of these sites will likely trigger some level of compliance with new stormwater treatment standards..




Figure 6: RDA Stormwater







PAGE 25 OF 65

FINDING

The poor drainage conditions as a result of outdated platted lands, historic construction techniques, and insufficient stormwater management facilities and conveyances all contribute to defective or inadequate infrastructure, and unsafe or unsanitary conditions, and inadequate or outdated building patterns serve as qualifying conditions for blighted area. Evaluation of an area-wide, comprehensive stormwater management strategy is an appropriate effort in support of economic revitalization of the Redevelopment Area. The City has identified projects within the Redevelopment Area as part of the stormwater master plan that are in need of improvement. Additional programs are necessary to reduce stormwater discharge into the various streams, creeks and St. Johns River, such as shared stormwater facilities, property assemblage, property redevelopment, dual purpose stormwater ponds/parks, etc.



2.10 OVERHEAD UTILITIES

The majority of the corridors consist of overhead utilities to provide electricity and telecommunication. These wooden utility poles also double as light poles for roadway lights along arterial and collector roads. Overhead utilities create fire hazards, accidents, and safety risks from power outages due to downed lines.

Overhead utilities also cause visual blight with dangling wires traversing the roadways and limit streetscaping efforts, which may hamper new investment opportunities and may contribute to further deterioration of the Redevelopment Area. The Merrill Road corridor has overhead utility lines on both sides of the corridor. JEA is currently studying the possibility of relocating or burying the overhead utilities along one side of the Merrill Road corridor.



The existing overhead utilities create additional support for unsafe conditions and defective roadways, which contributes to physical and visual blight. Undergrounding overhead utilities improves roadway safety by preventing roadway obstacles during hurricanes and reducing the chance of motorists striking poles, and fire hazards due to downed lines.

The appearance of an area can be greatly improved by reducing the visual clutter of overhead utility wires. Undergrounding overhead utilities allows the City to highlight the Redevelopment Area without a maze of poles and wires in the way. Without overhead utilities, the Redevelopment Area can more readily undertake improvement projects such as sidewalk widening and tree planting without having to snake around poles or trim vegetation to make way for power lines, thus providing more attractive, efficient, and safer redevelopment.

FINDING







2.11 POTABLE WATER AND SANITARY SEWER FACILITIES

City staff identified general areas within the Redevelopment Area that have limited potable water or sewer lines (see Figure 7).




Figure 7: RDA Water/Sewer Availability







The City has also documented that the overall study (areas adjacent to the corridors) have a significant amount of failing septic tanks (Figure 8). Study Area :: HOLL SW CREEK OAKWOOD VILLA ESTATES **FINDINGS** The RDA and surrounding land use reliance on well water and lack of storm water management all represent significant health safety concerns. Legend **Sub Basins** Streams Little Pottsburg Creek Major Roads Water Body Pottsburg Creek Silversmith Creek Septic Tank Failure Areas Strawberry Creek

Figure 8. Failing Septic Tanks - Source: City of Jacksonville Comprehensive Plan, May 2015

2.12 OCCURRENCES OF CRIME

As shown in Figure 9, most of the City's crime is committed in a rather small area. Compared to the City as a whole, the RDA does have a higher degree of crime overall. While it is does not contain the highest number of "hot spots", it does contain a number of "hot spots" as shown in Figure 9.




Figure 9: Citywide Occurrence of Crime (2010 to present)- Source: Sheriff's Department, June 2015



Citywide Incident Density (Robbery/Aggravated Battery/Burglary) 2010-YTD2015






Figure 10: Citywide Incident of Crime (2010 to present) - Source: Sheriff's Department, June 2015

3. BLIGHTED AREA CONDITIONS ANALYSIS

Determining if slum or blight conditions exist within the proposed Redevelopment Area is an initial step in ascertaining an area's appropriateness for designation as a Redevelopment Area. This Finding Report concludes the following based on the physical, economic, and regulatory conditions, as well as government-maintained statistics.

Based on the definition and criteria for determining "Slum Area" as specified in **Section163.340** (7), F.S. (see Section 1.3.2 of this report) and the findings concluded in this report, the proposed Redevelopment Area is not considered a "Slum Area."

However, the proposed Redevelopment Area is considered a "Blighted Area" as specified in Section 163.340 (8), F.S. (see Section 1.3 of this report) based on the findings concluded in this report. From the 14 criteria, of which 2 or more conditions are required to be considered a "Blight Area," at least six (6) conditions exists in the proposed Redevelopment Area, as follows.

1. Predominance of defective or inadequate street layout, parking facilities, roadways, bridges, or public transportation facilities (Section 163.340 [8]a, F.S.)

There is a predominance of defective or inadequate street layout from years of FDOT and City widening of each of the Corridors, leaving smaller and smaller parcels on which to make investment. In addition, early platting of the city also left lots that are generally undersized or lack the desired lot widths or depths to accommodate current parking, stormwater, and land development requirements, and other regulations.

Multiple driveway connections along the corridors do not meet current driveway or intersection separation criteria, which contributes to poor traffic circulation by creating potential vehicle and pedestrian or bicycle conflicts, poor sight triangle visibility, or difficulty in achieving accessible routes. Lack of inter-connectivity between existing developed sites also contributes to traffic congestion.

There is a lack of available, comprehensive system of accessible sidewalks, bicycle facilities, and dedicated multimodal facilities. There is limited and no formal pedestrian connection to city amenities, schools, and shopping. Existing sidewalks are substandard with respect to current design and accessibility requirements. Few interior sites have a pedestrian connection to commercial areas. Public transportation facilities along the corridors generally reflect deteriorating conditions, poor physical placement, or lack of appropriate facilities.

Uncontrolled access points, lack of parking, poor signage, and poor or nonexistent drainage, faulty street lay-out, no curb and gutter in many places, and other factors are detrimental to private reinvestment and a successful economic development environment.

Overhead utilities hamper streetscaping efforts and create inadequate roadways by preventing sidewalk widening and tree planting and having to snake around poles or trim vegetation to make way for power lines, which may hamper new investment opportunities and may contribute to further deterioration of the Redevelopment Area.

2. Faulty lot layout in relation to size, adequacy, accessibility, or usefulness (Section 163.340 [8] c, F.S.)

Due to early platting of the city and widening of University Boulevard by FDOT, and the City's widening of Merrill and Arlington Roads, many of the properties within the Redevelopment Area have irregular dimensions that create lot sizes and shapes and make compliance with current building, zoning, parking, stormwater, and other land development regulations difficult. Majority of blocks reflect a high proportion of owners, with few adjoining parcels or aggregated parcels under single ownership. In terms of reinvestment, the properties in the area may be difficult to consolidate property for redevelopment purposes. A sustainable commercial development requires more than one acre to be viable. Most of the land parcels are less than an acre in size.

3. Unsanitary or unsafe conditions (Section 163.340 [8]d, F.S.)

The multiple driveway connections that create poor traffic circulation, inadequate parking facilities, and lack of viable, comprehensive system of accessible sidewalks and bicycle facilities create unsafe conditions within the Redevelopment Area.

Substantial numbers of buildings are substandard, with many reaching toward a state of dilapidation and clear underutilization.

According to the City's Code Enforcement data, there was an increase in property deterioration, lack of maintenance, nuisances, and other physical decay between 2010 and 2014.

Sanitary conditions, in particular, siting and placement of refuse collection consistent with City design standards, was noted as lacking in a majority of existing facilities and sites, such as placement of additional dumpster facilities within designated parking or landscape areas, placement of dumpsters that block potential emergency access routes, and damaged or deteriorating enclosures.

A significant portion of the corridor and surround land uses rely on wells for water and lack sanitary sewer facilities. The City has documented that much of the overall study area south of Merrill Road have failing septic tanks. The Redevelopment Area exhibits poor drainage conditions as a result of historic construction techniques and lack of sufficient stormwater management facilities and conveyances. Many of the existing developed sites pre-date current environmental and stormwater management requirements.

Many existing stormwater management facilities are not under proper maintenance and exhibit conditions that contribute to onstreet and adjoining property ponding or flooding, such as standing water, damaged inlet structures, clogged piping, and inappropriate use of facilities (parking, storage, etc.), which may cause stormwater runoff into the Arlington and St. Johns Rivers, polluting the water and ecosystem.

The existing overhead utilities create unsafe conditions due to the potential for downed lines to cause fire hazards and obstruct the roadways and increasing the chance of motorists striking the poles.

Overhead utility lines can be found on both side of the Merrill Road corridor also degrade the aesthetics of the corridor and its adjoining neighborhoods.

The absence of sanitary sewer lines within portions of the Redevelopment Area creates unsanitary and unsafe conditions and limits redevelopment efforts. To meet current and future development within the Redevelopment Area, the City/CRA should add sanitary sewer lines and extend central sanitary sewer service to all developed properties to protect the public health and environment.

4. Deterioration of site or other improvements (Section 163.340 [8]e, F.S.)

Some of these conditions relate to improper or poor maintenance of yards and improvements, structural deterioration, or unrepaired storm damage. In all land use categories, there are substantial numbers of deteriorating structures and underused properties that are contributing to conditions that are not supportive of redevelopment and private investment within the Redevelopment Area. Some of the structures also reflect conditions relating from prior right-of-way acquisitions and impacts from the widen of University Boulevard and Merrill/Arlington Roads widening that have rendered some of the properties functionally obsolete.

5. Inadequate or outdated building patterns (Section 163.340 [8] f, F.S.)

The Redevelopment Area contains a mix of land uses—commercial, industrial, single-family, and multi-family residential. Most of the residentially-used lands have been zoned for other uses, such as commercial, professional, or office for many years, and a few conversions have occurred along all three corridors. One problem with the current system of lots is the number of County/City, institutional, and other lands that are off the tax rolls in Redevelopment Area.

The Redevelopment Area is affected by a lack of parking and stormwater management, small buildable areas, insufficient land to expand, incompatible adjacent uses, and problematic access due to archaic rights-of-ways. Residences still occupy commercially-zoned lands, creating non-conformities. Changing the land development regulations will be needed to address these issues, creating a new plan, and zoning and design system in the area will aid in attracting new development.


University Boulevard and Arlington Road served as the historical commercial center of the area. The nature of retail and business along this corridor has changed dramatically. With the exception of the Southern Boundary areas, small-scale sites are sometimes at a disadvantage. The original platted lots have insufficient area to meet standard development requirements desired for today's commerce. There is a lack of a substantial commercial investment along the corridors within the Redevelopment Area.


Many of the residential structures appear to be substandard and reflect conditions inconsistent with current zoning. This area is devoid of sidewalks and good drainage, and many Code violations exist.

Faulty lot sizes and shapes, poor locations, and problematic title situations offer little if any value to a community. Lots and buildings may be left vacant, leaving them subject to physical deterioration. These conditions contribute to visual and physical blight.

6. Incidents of Crime in the area higher than in the remainder of the county or municipality (Section 163.340 [8]j, F.S.)


The RDA contains numerous "hot spots" for Robbery/Aggravated that exceeds most areas of the City: the southern part of the RDA around the Town and Country Shopping Center; the Justina/Merrill Road area; and to the north at the western end of Ft. Caroline Road as shown in Figure 8.







Detailed Boundary Map Key




















University Blvd/Merrill/Arlington Rd Findings of Necessity | 41 REVISED EXHIBIT 2 PAGE 44 OF 65

APPENDIX B: RDA SURVEY

LEGAL DESCRIPTION UNIVERSITY BOULEVARD/MERRILL ROAD CORRIDOR REDEVELOPMENT AREA CITY OF JACKSONVILLE, DUVAL COUNTY, FLORIDA

A part of the City of Jacksonville, being located in Townships 1 and 2 South, Range 27 East, Duval County, Florida, being more particularly described as follows:

Begin at the southwest corner of Tract "C", being on the easterly right of way line of Arco Drive, per Arlington Commercial Center as recorded in Plat Book 28, Page 55 of the Public Records of Duval County, Florida; Thence northerly along said easterly right of way line of Arco Drive to the southerly line of Lot 10, Block 13 per Arlington Heights Second Subdivision of Alderman Realty Co. as recorded in Plat Book 5, Page 83 of said Public Records; Thence westerly along said southerly line to the easterly right of way line of Bretta Street (Hickory per said plat of Arlington Heights); Thence northerly along said easterly right of way line of Bretta Street to the southerly right of way line of Arlington Road (St. John's Street per said plat of Arlington Heights); Thence easterly along said southerly right of way line of said Arlington Road to the northwest corner of Block 17 per said plat of Arlington Heights and easterly right of way line of Easter Street (Hemlock per said plat of Arlington Heights); Thence north along said easterly right of way line of Easter Street to the northwest corner of Block 19 per said plat of Arlington Heights and the southerly right of way line of Macy Avenue (Arlington per said plat of Arlington Heights); Thence easterly along said southerly right of way line of Macy Avenue to the southerly prolongation of the westerly line of Lot 5, Block 22 per said plat of Arlington Heights; Thence northerly along said prolongation and the westerly line of said Lot 5 to the southerly line of Block 1 per River Forest Unit No. 1 as recorded in Plat Book 21, Page 47 of said Public Records; Thence easterly along said southerly line of Block 1 per said plat of River Forest Unit No. 1 and the southerly line of Block 1 per River Forest Unit No. 1 Addition as recorded in Plat Book 23, Page 74 of said Public Records to the westerly line of Lot 13 per said plat of River Forest Unit No. 1 Addition; Thence northerly along said westerly line of Lot 13 to the southerly right of way line of River Forest Drive per said plat of River Forest Unit No. 1 Addition; Thence northerly across said River Forest Drive to the northerly right of way line of said River Forest Drive and the westerly line of Lot 30 per said plat of River Forest Unit No. 1 Addition; Thence northerly along said westerly line of Lot 30 to the southerly line of Lot 32 per said plat of River Forest Unit No. 1 Addition; Thence westerly along said southerly line of Lot 32 to the westerly line of said Lot 32; Thence northerly along said westerly line of Lot 32 to the southerly line of Block 3 per River Forest Unit No. 3 as recorded in Plat Book 21, Page 68 of said Public Records; Thence easterly along said southerly line of Block 3 per said plat of River Forest Unit No. 3 to the westerly line of Lot 1, Block 3 per said plat of River Forest Unit No. 3; Thence northerly along said westerly line of Lot 1 to the southerly right of way line of Windermere Drive per said plat of River Forest Unit No. 3; Thence northerly across said Windermere Drive to the northerly right of way line of said Windermere Drive and the westerly line of Lot 3, Block 2 per said plat of River Forest Unit No. 3; Thence northerly along said westerly line of Lot 3, and the westerly line of Lot 2 and Lot 1, Block 2 per said plat of River Forest Unit No. 3 to the southerly right of way line of Gable Lane per said plat of River Forest Unit No. 3; Thence northerly across said Gable Lane to the northerly right of way line of said Gable Lane and the

westerly line of Lot 1, Block 1 per said plat of River Forest Unit No. 3; Thence northerly along said westerly line of Lot 1, Block 1 to the southerly line of Block 3 per River Forest Unit No. 6 as recorded in Plat Book 26, Page 89 of said Public Records; Thence westerly along said southerly line of Block 3 to the westerly line of the easterly 75.00 feet of Lot 14, Block 3 per said plat of River Forest Unit No. 6 per Official Records Book 12606, Page 2392 of said Public Records; Thence northerly along said westerly line of easterly 75.00 feet of Lot 14 to the northeasterly line of said Lot 14; Thence southeasterly along said the northeasterly line of 14 to the westerly line of Lot 17. Block 3 per said plat of River Forest Unit No. 6; Thence northerly along said westerly line of Lot 17 and the westerly line of Lot 16, Block 3 per said plat of River Forest Unit No. 6 to the southerly right of way line of Oliver Street per said plat of River Forest Unit No. 6; Thence northerly across said Oliver Street to the northerly right of way line of said Oliver Street and the westerly line of Lot 14, Block 1 per said plat of River Forest Unit No. 6; Thence northerly along said westerly line of Lot 14, and the westerly line of Lot 15 and Lot 16, Block 1 per said plat of River Forest Unit No. 6 to the southerly line of Block 4 per River Forest Unit No. 4 as recorded in Plat Book 22. Page 27 of said Public Records: Thence westerly along said southerly line of Block 4 to the westerly line of Lot 31, Block 4 per said plat of River Forest Unit No. 4; Thence northerly along said westerly line of Lot 31, and the westerly line of Lot 30, Lot 29, and a part of the westerly line of Lot 28, Block 4 to the southernmost point of Lot 26, Block 4 per said plat of River Forest Unit No. 4; Thence northwesterly along the southwesterly line of Lot 26 to the westerly line of Lot 26, Block 4 per said plat of River Forest Unit No. 4; Thence northerly along said westerly line of Lot 26 to the southerly right of way line of Dickson Road (North River Road per said plat of River Forest Unit No. 4); Thence northerly across said Dickson Road to the northerly right of way line of said Dickson Road and the westerly line of Lot 16, Block 2 per said plat of River Forest Unit No. 4; Thence northerly along said westerly line of Lot 16; Thence northeasterly along the northwesterly line of said Lot 16 to the westerly line of Lot 14, Block 2 per said plat of River Forest Unit No. 4; thence northerly along said westerly line of Lot 14, and the westerly line of Lot 13 and Lot 12, Block 2 per said plat of River Forest Unit No. 4 to the southwesterly line of Lot 11, Block 2 per said plat of River Forest Unit No. 4; Thence northwesterly along said southwesterly line of Lot 11 and the southwesterly line of Lot 9, Block 2 per said plat of River Forest Unit No. 4 to the westerly line of said Lot 9; Thence northerly along said westerly line of Lot 9 to the southerly right of way line of Floral Bluff Road (Floral Bluff Avenue per said plat of River Forest Unit No. 4); Thence northerly across said Floral Bluff Road per said plat of River Forest Unit No. 4, and per plat of Floral Bluff as recorded in Plat Book 1, Page 92 of said Public Records to the northerly right of way line of said Floral Bluff Road and the westerly line of Lot 7, Block A per said plat of Floral Bluff; Thence northerly along said westerly line of Lot 7 to the southerly line of Lot 10, Block A per said plat of Floral Bluff: Thence westerly along said southerly line of Lot 10 to the easterly right of way line of Harvey Street per said plat of Floral Bluff; Thence northerly along said easterly right of way line of Harvey Street to the southerly right of way line of Burdette Road (Burdette Avenue per Official Records Book 8063, Page 1438 of said Public Records); Thence westerly along said southerly right of way line of Burdette Road to the west right of way line of Harvey Street per Official Records Book 10069, Page 1353 of said Public Records; Thence northerly across said Burdette Road to the northerly right of way line of said Burdette Road and the westerly line of land per Official Records Book 15384, Page 1960 of said Public Records; Thence northerly along said westerly line of land per Official Records Book 15384, Page 1960 to the southerly line of Parcel 1 per Official Records Book 16555, Page 883 of said Public Records; Thence westerly along said southerly line of Parcel 1 to the easterly right of way line of Shepard Street per said Official Records Book 16555, Page 883 of said Public Records; Thence westerly across said Shepard Street to the westerly right of way line of said Shepard Street and the southerly line of the Common Area of Arlington By The River Condominium Association Inc. per Official Records Book 5670, Page 334 of said Public Records; Thence westerly along said southerly line of the Common Area to the St. Johns River: Thence northerly along the St. Johns River to the southerly line of land per Official Records Book 9415, Page 2339 of said Public Records; Thence westerly along said southerly line per Official Records Book 9415, Page 2339 to the Bulkhead Line per said Official Records Book 9415. Page 2339; Thence northerly along said Bulkhead Line to the southerly line of land per Official Records Book 13972, Page 2322 of said Public Records; Thence northerly along the westerly line of land per said Official Records Book 13972, Page 2322 to the northerly line of land per said Official Records Book 13972, Page 2322; Thence easterly along said northerly line of land per Official Records Book 13972. Page 2322 to the easterly line of land per said Official Records Book 13972, Page 2322; Thence southerly along said easterly line of land per Official Records Book 13972, Page 2322 to the northerly line of land per said Official Records Book 9415, Page 2339; Thence easterly along said northerly line of land per said Official Records Book 9415, Page 2339 to the southwest corner of Tract 171 Recreation Area per plat of Marsh Creek as recorded in Plat Book 38, Page 58 of said Public Records; Thence easterly along the southerly line of said plat of Marsh Creek, also being the northerly line of said Official Records Book 9415, Page 2339 to the southeast corner of Lot 75 per said plat of Marsh Creek; Thence northerly along the easterly line of said Lot 75 and the easterly line of Lot 74 per said plat of Marsh Creek to the southwest corner of Lot 64 per said plat of Marsh Creek; Thence Northerly along the westerly line of said Lot 64 to the southerly right of way line of Fort Caroline Road per said plat of Marsh Creek; Thence northerly across said Fort Caroline Road to the northerly right of way line of said Fort Caroline Road and the westerly line of Lot 63 per said plat of Marsh Creek; Thence northerly along said westerly line of Lot 63 per said plat of Marsh Creek to the northerly line of said Lot 63 per said plat of Marsh Creek; Thence easterly along said northerly line of Lot 63 per said plat of Marsh Creek to the westerly right of way line of University Boulevard; Thence easterly along a prolongation of said northerly line of Lot 63 per said plat of Marsh Creek to the easterly right of way line of said University Boulevard; Thence northerly along said easterly right of way line of University Boulevard to the southerly line of the plat of University Park Unit No. 2 as recorded in Plat Book 28, Page 48 of said Public Records; Thence easterly along said southerly line of University Park Unit No. 2 to the southeast corner of said plat of University Park Unit No. 2; Thence easterly along the northerly line of the F. Richard Grant, Section 52, Township 1 South, Range 27 East to the easterly line of Official Records Book 4923, Page 576 of said Public Records; Thence northerly along said easterly line of Official Records Book 4923, Page 576 to the westerly prolongation of the northerly line of land per Official Records Book 15785, Page 1567 of said Public Records; Thence easterly along said prolongation of the northerly line of Official Records Book 15785, Page 1567 and also said northerly line of Official Records Book 15785, Page 1567 to its easterly termination; Thence southerly along an easterly line of said land per Official Records Book 15785, Page 1567 to the north line of Parcel Number 2 per Official Record Book 14479, Page 1478; Thence easterly along said northerly line of Parcel Number 2 per Official Record Book 14479, Page 1478 and the northerly line of Parcel Number 1 per Official Record Book 14479, Page 1478 to the easterly line of said Parcel Number 1 per Official Record Book 14479, Page 1478; Thence southerly along said easterly line of Parcel Number 1 per Official Record Book 14479, Page 1478 to the northerly line of Section 52, Township 1 South, Range 27 East per Official Records Book 15785, Page 1567; Thence easterly along said northerly line of Section 52 per Official Records Book 15785, Page 1567 to the northeasterly corner of said Section 52 per Official Records Book 15785, Page 1567 and the westerly line of land per Official Records Book 2531, Page 522; Thence southerly along said westerly line of land per Official Records Book 2531, Page 522 to the southerly line of land per said Official Records Book 2531, Page 522; Thence easterly along said southerly line of land per said Official Records Book 2531, Page 522 to the westerly right of way line of University Club Boulevard; Thence southerly along said westerly right of way line of University Club Boulevard and its southerly prolongation across Fort Caroline Road to the southerly right of way line of said Fort Caroline Road; Thence westerly along said southerly right of way line of Fort Caroline Road to the easterly line of land per Official Records Book 15061. Page 367 of said Public Records; Thence southerly along said easterly line of land per Official Records Book 15061, Page 367 to the southerly line of land per said Official Records Book 15061, Page 367; Thence westerly along said southerly line of land per Official Records Book 15061, Page 367 to the easterly right of way line of Peeler Road; Thence westerly across said Peeler Road to the westerly right of way line of said Peeler Road; Thence southerly along said westerly right of way line of Peeler Road to the northerly line of Colonial Heights as recorded in Plat Book 30, Page 77 of said Public Records; Thence westerly along said northerly line of Colonial Heights to the easterly line of Block 22 Arlington Hills Unit No. Seven-A as recorded in Plat Book 28, Page 17 of said Public Records; Thence northerly along said easterly line of Arlington Hills Unit No. Seven-A to the northerly line of Lot 3, Block 22 per said plat of Arlington Hills Unit No. Seven-A: Thence westerly along said northerly line of Lot 3. Block 22 to the easterly right of way line of Cesery Boulevard; Thence westerly across said Cesery Boulevard to the westerly right of way line of said Cesery Boulevard and the northerly line of Lot 62, Block 1 per said plat of Arlington Hills Unit No. Seven-A; Thence westerly along said northerly line of Lot 62, Block 1 to the westerly line of Block 1 of said plat of Arlington Hills Unit No. Seven-A; Thence southerly along said westerly line of Block 1 Arlington Hills Unit No. Seven-A and the westerly line of Block 1 Arlington Hills Unit No. Seven as recorded in Plat Book 27, Page 99 of said Public Records to the southerly line of Lot 1 of said Block 1 Arlington Hills Unit No. Seven: Thence easterly along said southerly line of Block 1 Arlington Hills Unit No. Seven to the westerly right of way line of Cesery Boulevard; Thence easterly across said Cesery Boulevard to the easterly right of way line of said Cesery Boulevard and the southerly line of Block 2 of said Arlington Hills Unit No. Seven; Thence easterly along said southerly line of Block 2 Arlington Hills Unit No. Seven to the westerly right of way line of Searchwood Drive per said plat of Arlington Hills Unit No. Seven; Thence easterly across said Searchwood Drive to the easterly right of way line of said Searchwood Drive and the southerly line of Block 5 of said Arlington Hills Unit No. Seven; Thence southerly along the easterly right of way line Searchwood Drive to the northerly line of land per Official Records Book 16393, Page 1460 of said Public Records; Thence easterly along said northerly line of land per Official Records Book 16393 to the westerly line of Block 19 Lake Lucina Unit No. 8 as recorded in Plat Book 26, Page 55 of said Public Records; Thence southerly

along said westerly line of Block 19 Lake Lucina Unit No. 8 to the northerly line of Tract "A" per said plat of Lake Lucina Unit No. 8; Thence easterly along said the northerly line of Tract "A" per said plat of Lake Lucina Unit No. 8 to the westerly right of way line of Red Oak Drive per said plat of Lake Lucina Unit No. 8; Thence easterly across said Red Oak Drive to the easterly right of way line of said Red Oak Drive and the northerly line of Tract "B", Block 24 of said plat of Lake Lucina Unit No. 8; Thence easterly along said northerly line of Tract "B", Block 24 of said plat of Lake Lucina Unit No. 8 and along the northerly line of Lot 14 through Lot 9, inclusive, Block 24 of said plat of Lake Lucina Unit No. 8 to the westerly right of way line of Holly Point Drive per said plat of Lake Lucina Unit No. 8; Thence northerly along said westerly right of way line of Holly Point Drive to a westerly prolongation of the northerly line of Lot 12, Block 25 of said plat of Lake Lucina Unit No. 8; Thence easterly along said northerly line of Lot 12, Block 25 of said plat of Lake Lucina Unit No. 8 to the westerly line of a 40 foot Right of Way For Drainage and Utilities per said plat of Lake Lucina Unit No. 8; Thence across said 40 foot Right of Way For Drainage and Utilities to the easterly line of said 40 foot Right of Way For Drainage and Utilities and the northerly line of Lot 15, Block 25 of said plat of Lake Lucina Unit No. 8; Thence easterly along said northerly line of Lot 15, Block 25 of said plat of Lake Lucina Unit No. 8 to the westerly right of way line of Oakcove Lane per said plat of Lake Lucina Unit No. 8: Thence across said Oakcove Lane to the easterly right of way line of said Oakcove Lane and the northerly line of Lot 12, Block 26 per said plat of Lake Lucina Unit No. 8; Thence easterly along said northerly line of Lot 12 and the northerly line of Lot 15, Block 26 per said plat of Lake Lucina Unit No. 8 to the westerly right of way line of Rogero Road per said plat of Lake Lucina Unit No. 8; Thence southerly along said westerly right of way line of Rogero Road per said plat of Lake Lucina Unit No. 8 to the northerly right of way line of Merrill Road; Thence easterly along said northerly right of way line of Merrill Road to the westerly line Lot 29, Block 40 Lake Lucina Unit No. 12 as recorded in Plat Book 29, Page 35 of said Public Records; Thence northerly along said westerly line of said Lot 29, Block 40 and the westerly line of Lot 15, Block 40 of said Lake Lucina Unit No. 12; to the northwesterly line of said Lot 15, Block 40; Thence northeasterly along said northwesterly line of said Lot 15, Block 40 to the southwesterly right of way line of Corkwood Road per said plat of Lake Lucina Unit No. 12; Thence southeasterly and easterly along the southwesterly and southerly right of way line of said Corkwood Road and the easterly prolongation of said southerly right of way line of Corkwood Road to the easterly right of way line of Woodtop Drive per Lake Lucina Unit No. 13 as recorded in Plat Book 30, Page 67; Thence northerly along said easterly right of way line of Woodtop Drive to the northerly line of Lot 3, Block 43 of said plat of Lake Lucina Unit No. 13; Thence easterly along said northerly line of Lot 3, Block 43 to the easterly line of said Lot 3, Block 43; Thence northerly along the easterly line of Lots 4 through Lot 8, inclusive, Block 43 of said plat of Lake Lucina Unit No. 13 to the southerly line of Lot 10, Block 43 of said plat of Lake Lucina Unit No. 13; Thence easterly along said southerly line of Lot 10, Block 43, the southerly line of Lot 11 through Lot 21, inclusive, Block 43 and the southerly line of a 35 foot Right of Way For Drainage and Utilities, Block 43, all per said plat of Lake Lucina Unit No. 13, and the southerly line of Lot 22, Block 43 Colonial Park Unit No. 1 as recorded in Plat Book 32, Page 68 of said Public Records to the westerly right of way line of Townsend Boulevard per said plat of Colonial Park Unit No. 1; Thence southerly along said westerly right of way line of Townsend Boulevard to a westerly prolongation of the southerly right of way line of Sandhurst Road South per Arlington Hills Unit No. 8-B as recorded in Plat Book 30, Page

21 of said Public Records; Thence easterly along said westerly prolongation of the southerly right of way line of Sandhurst Road South and the southerly right of way line of said Sandhurst Road per Arlington Hills Unit No. 8-B to the westerly right of way line of Provident Road per Arlington Hills Unit Eight as recorded in Plat Book 29, Page 4 of said Public Records; Thence easterly across said Provident Road per Arlington Hills Unit Eight to the easterly right of way line of said Provident Road per Arlington Hills Unit Eight; Thence easterly along the southerly right of way line of Sandhurst Road per said Arlington Hills Unit Eight to the westerly right of way line of Landsdowne Drive per said Arlington Hills Unit Eight; Thence easterly across said Landsdowne Drive Arlington Hills Unit Eight to the easterly right of way line of Landsdowne Drive per said Arlington Hills Unit Eight; Thence easterly along the southerly right of way line of Sandhurst Road per said Arlington Hills Unit Eight to the westerly right of way line of Wycombe Drive West per said Arlington Hills Unit Eight; Thence southerly along said westerly right of way line of Wycombe Drive West Arlington Hills Unit Eight to the westerly prolongation of the southerly line of Lot 6, Block 6 per said Arlington Hills Unit Eight; Thence easterly along said westerly prolongation of the southerly line of Lot 6, Block 6 Arlington Hills Unit Eight to the easterly right of way line of said Wycombe Drive West Arlington Hills Unit Eight and the southerly line of said Lot 6, Block 6 Arlington Hills Unit Eight; Thence easterly along said southerly line of said Lot 6, Block 6 Arlington Hills Unit Eight, the southerly line of Lot 7 through Lot 13, inclusive, Block 6 per said Arlington Hills Unit Eight, and the southerly line of Lot 1, Block 1 Arlington Hills Unit No. Ten as recorded in Plat Book 31, Page 37 of said Public Records to the westerly right of way line of Wedgefield Boulevard per said Arlington Hills Unit No. Ten; Thence easterly across said Wedgefield Boulevard per said Arlington Hills Unit No. Ten to the easterly right of way line of said Wedgefield Boulevard and the southerly line of Lot 1, Block 4 per said Arlington Hills Unit No. Ten; Thence easterly along said southerly line of Lot 1, Block 4 Arlington Hills Unit No. Ten and the southerly line of Lot 2 through Lot 6, inclusive, Block 4 Arlington Hills Unit No. Ten to the westerly right of way line of Lauderdale Drive East per said Arlington Hills Unit No. Ten: Thence southeasterly across said Lauderdale Drive East Arlington Hills Unit No. Ten to the easterly right of way line of Lauderdale Drive East per said Arlington Hills Unit No. Ten and the northerly line of Lot 18, Block 5 per said Arlington Hills Unit No. Ten; Thence easterly along said northerly line of Lot 18, Block 5 Arlington Hills Unit No. Ten to the westerly line of Lot 3 Fort Hammock as recorded in Plat Book 44, Page 50 of said Public Records; Thence northerly along said westerly line of Lot 3 Fort Hammock to the northerly line of said Lot 3 Fort Hammock; Thence easterly along said northerly line of said Lot 3 Fort Hammock to the westerly right of way line of Fort Wilderness Trail per said Fort Hammock; Thence easterly across said Fort Wilderness Trail Fort Hammock to the easterly right of way line of Fort Wilderness Trail per said Fort Hammock and the southerly right of way line of Rocky Fort Trail per said Fort Hammock; Thence easterly along said southerly right of way line of Rocky Fort Trail Fort Hammock to the westerly line of Lot 42 per said Fort Hammock; Thence southerly along said westerly line of Lot 42 Fort Hammock to the southerly line of said Lot 42 Fort Hammock; Thence easterly along the southerly line of said Lot 42 per Fort Hammock to the southeasterly line of Lot 41 Fort Hammock; Thence northeasterly along the southeasterly line of said Lot 41 Fort Hammock and the southeasterly line of Lot 40 per said Fort Hammock to the easterly line of Lot 40 Fort Hammock; Thence northerly along the easterly line of said Lot 40 Fort Hammock and the easterly line of Lot 39 per said Fort Hammock to the northeasterly line of Lot 39 Fort

Hammock, Thence northwesterly along said northeasterly line of Lot 39 Fort Hammock and the northeasterly line of Lot 38 per said Fort Hammock to the easterly line of Lot 29 per said Fort Hammock; Thence northerly along said easterly line of Lot 29 per Fort Hammock to the northeasterly line of Lot 28 per said Fort Hammock; Thence northwesterly along said northeasterly line of Lot 28 per Fort Hammock to the easterly line of Lot 26 line per said Fort Hammock; Thence northerly along said easterly line of Lot 26 and the easterly line of Lot 25 per said Fort Hammock to the southerly line of a 75 foot Duval County right of way for drainage purposes (Official Records Book 2716, Page 1108 Parcel 2) per said Fort Hammock; Thence continue northerly, along a prolongation of said easterly line of Lot 25 per Fort Hammock, across said 75 foot Duval County right of way for drainage purposes (Official Records Book 2716, Page 1108 Parcel 2) per Fort Hammock to the northerly right of way line of said 75 foot Duval County right of way for drainage purposes (Official Records Book 2716, Page 1108 Parcel 2) per Fort Hammock; Thence easterly along said northerly right of way line of 75 foot Duval County right of way for drainage purposes (Official Records Book 2716, Page 1108 Parcel 2) per Fort Hammock to the northeasterly line of said 75 foot Duval County right of way for drainage purposes (Official Records Book 2716, Page 1108 Parcel 2) per Fort Hammock; Thence southeasterly along said northeasterly right of way line of 75 foot Duval County right of way for drainage purposes (Official Records Book 2716, Page 1108 Parcel 2) per Fort Hammock to the northwest corner of land per Official Records Book 16064, Page 2460 of said Public Records; Thence easterly along the northerly line of said land per Official Records Book 16064, Page 2460 to the westerly right of way line of Hartsfield Road; Thence northerly along said westerly right of way line of Hartsfield Road to the westerly prolongation of the northerly line of land per Official Records Book 1616, Page 175; Thence easterly across said Hartsfield Road along said prolongation of the northerly line of land per Official Records Book 1616, Page 175 to the easterly right of way line of said Hartsfield Road; Thence easterly along said northerly line of land per Official Records Book 1616, Page 175 to the westerly line of Lot 8 Dames Point Crossing Unit Two as recorded in Plat Book 57, Page 15 of said Public Records; Thence northerly along said westerly line of Lot 8 Dames Point Crossing Unit Two to the northerly line of land per Official Records Book 15630, Page 938 of said Public Records; Thence easterly along said northerly line of land per Official Records Book 15630, Page 938 to the westerly right of way line of Dames Point Crossing Boulevard per said Dames Point Crossing Unit Two; Thence across said Dames Point Crossing Boulevard per Dames Point Crossing Unit Two to the easterly right of way line of said Dames Point Crossing Boulevard per Dames Point Crossing Unit Two and the northerly line of land per Official Records Book 13971, Page 52 of said Public Records; Thence easterly along said northerly line of land per Official Records Book 13971, Page 52 to the easterly line of said Dames Point Crossing Unit Two; Thence southerly along said easterly line of Dames Point Crossing Unit Two to the northerly line of Merrill Road at the southeast corner of Lot 1 Dames Point Crossing Unit Two; Thence southerly across Merrill Road to the southerly right of way line of Sunrise Ridge Lane and the northeast corner of Tract "B" per Lakeside At Merrill as recorded in Plat Book 67, Page 187 of said Pubic Records; Thence southeasterly along the southwesterly right of way line of Sunrise Ridge Lane to the southerly line of land per Official Records Book 8961, Page 1455 of said Pubic Records; Thence westerly along said southerly line of land per Official Records Book 8961, Page 1455 to the easterly line of said Lakeside At Merrill; Thence southerly along said easterly line of Lakeside At Merrill

and the easterly line of land per Official Records Book 6138, Page 2066 to the southerly line of said Official Records Book 6138, Page 2066; Thence westerly along said southerly line of Official Records Book 6138, Page 2066 to the westerly line of said Official Records Book 6138, Page 2066; Thence northerly along said westerly line of Official Records Book 6138, Page 2066 to the easterly prolongation of the southerly line of Merrill Pines, A Condominium per Official Records 13923, Page 1719; Thence westerly along said southerly line of Merrill Pines, A Condominium per Official Records 13923, Page 1719 to the westerly line of Merrill Pines, A Condominium per Official Records 13923, Page 1719; Thence northerly along said westerly line of Merrill Pines, A Condominium per Official Records 13923, Page 1719 to the northerly line of Lot 46 per Arlington Hills Unit 12-A as recorded in Plat Book 33, Page 78 of said Public Records; Thence westerly along said northerly line of Lot 46 per Arlington Hills Unit 12-A to the easterly right of way line of Woolery Drive per said Arlington Hills Unit 12-A; Thence across said Woolery Drive to the westerly right of way line of said Woolery Drive per Arlington Hills Unit 12-A and the northerly line of Lot 1 per said Arlington Hills Unit 12-A; Thence westerly along said northerly line of Lot 1 per Arlington Hills Unit 12-A to the westerly line of said Arlington Hills Unit 12-A; Thence southerly along said westerly line of Arlington Hills Unit 12-A to the easterly prolongation of the northerly line of Block 1 per Arlington Hills Unit No. 9-C as recorded in Plat Book 30, Page 50 of said Public Records; Thence westerly along said northerly line of Block 1 per Arlington Hills Unit No. 9-C and the northerly line of Block 1 per Arlington Hills Unit No. 9-A as recorded in Plat Book 30, Page 2 of said Public Records to the easterly right of way line of Wedgefield Boulevard per said Arlington Hills Unit No. 9-A; Thence westerly across said Wedgefield Boulevard per said Arlington Hills Unit No. 9-A to the westerly right of way line of Wedgefield Boulevard per said Arlington Hills Unit No. 9-A and the northerly line of Lot 1-A per said Arlington Hills Unit No. 9-A; Thence westerly along said northerly line of Lot 1-A per said Arlington Hills Unit No. 9-A and the northerly line of Block 2 per Arlington Hills Unit No. 6-D as recorded in Plat Book 28, Page 97 of said Public Records to the easterly right of way line of Kingstree Drive West per said Arlington Hills Unit No. 6-D; Thence westerly across said Kingstree Drive West per said Arlington Hills Unit No. 6-D to the westerly right of way line of Kingstree Drive West per said Arlington Hills Unit No. 6-D and the northerly line of Lot 1, Block 1 per said Arlington Hills Unit No. 6-D; Thence westerly along said northerly line of Lot 1, Block 1 per Arlington Hills Unit No. 6-D, the northerly line of a 50 foot right of way for drainage and utilities, and the northerly line of Block 1 per Arlington Hills Unit No. Six-A as recorded in Plat Book 28, Page 26 of said Public Records to the easterly line of Block 2 per Arlington Hills Unit No. Six as recorded in Plat Book 27, Page 85 of said Public Records; Thence northerly along said easterly line of Block 2 per Arlington Hills Unit No. Six to the northerly line of Lot 5, of said Block 2 per Arlington Hills Unit No. Six; Thence westerly along said northerly line of Lot 5, Block 2 per Arlington Hills Unit No. Six to the easterly right of way line of Landsdowne Drive per said Arlington Hills Unit No. Six; Thence westerly, along a westerly prolongation of said northerly line of Lot 5, Block 2 per Arlington Hills Unit No. Six, across said Landsdowne Drive per Arlington Hills Unit No. Six to the westerly right of way line of Landsdowne Drive per said Arlington Hills Unit No. Six; Thence northerly along said westerly right of way line of Landsdowne Drive per Arlington Hills Unit No. Six to the southerly right of way line of Elvia Drive, being the northeast corner of Block 4 per said Arlington Hills Unit No. Six; Thence northerly to the northerly right of way line of said Elvia Drive at said westerly right of way line of Landsdowne Drive, being the southeast corner of Block 1 per said Arlington Hills Unit No. Six; Thence westerly along said northerly right of way line of said Elvia Drive, Block 1 per Arlington Hills Unit No. Six to the easterly right of way line of Townsend Boulevard (Malinda Boulevard per said Arlington Hills Unit No. Six), being the southwest corner of Tract "A", Block 1 per said Arlington Hills Unit No. Six; Thence westerly, along a westerly prolongation of said northerly right of way line of Elvia Drive per Arlington Hills Unit No. Six, across said Townsend Boulevard (Malinda Boulevard per said Arlington Hills Unit No. Six) to the westerly right of way line of Townsend Boulevard (Malinda Boulevard, Block 1 per Arlington Hills Unit Five as recorded in Plat Book 26, Page 93 of said Public Records; Thence northerly along said westerly right of way line of Townsend Boulevard (Malinda Boulevard, Block 1 per Arlington Hills Unit Five) to the southerly line of Lot 4, said Block 1 Arlington Hills Unit Five; Thence westerly along said southerly line of Lot 4, Block 1 and the southerly line of Lot 30 per said Arlington Hills Unit Five to the westerly line of land per Official Records Book 9016, Page 2210 of said Public Records; Thence northerly along said westerly line of land per Official Records Book 9016, Page 2210 to the southerly line of Lot 2, Block 1 per said Arlington Hills Unit Five: Thence westerly along said southerly line of Lot 2. Block 1 per Arlington Hills Unit Five and the southerly line of Lot 1, Block 1 per said Arlington Hills Unit Five to the easterly right of way line of Charbray Drive per said Arlington Hills Unit Five; Thence northwesterly across said Charbray Drive per Arlington Hills Unit Five to the westerly right of way line of Charbray Drive per Arlington Hills Unit Five and the southerly line of Lot 1, Block 2 per said Arlington Hills Unit Five; Thence westerly along said southerly line of Lot 1, Block 2 per Arlington Hills Unit Five and the southerly line of Lot 20, Block 2 per said Arlington Hills Unit Five to the westerly right of way line of Herrick Drive per Arlington Hills Unit Five and the southerly line of Lot 1 per Arlington Hills Unit Five-A as recorded in Plat Book 27, Page 29 of said Public Records; Thence southwesterly along said southerly line of Lot 1 per Arlington Hills Unit Five-A and its westerly prolongation to the easterly line of Tract "A" per said Arlington Hills Unit Five-A; Thence southerly along said easterly line of Tract "A" per Arlington Hills Unit Five-A to the northerly line of Block 3 per said Arlington Hills Unit Five; Thence westerly along said northerly line of Block 3 per Arlington Hills Unit Five to the easterly line of Arlington Hills Annex as recorded in Plat Book 29, Page 13 of said Public Records; Thence northerly along said easterly line of Arlington Hills Annex to the southerly line of Lot 34 per said Arlington Hills Annex; Thence westerly along said southerly line of Lot 34 per Arlington Hills Annex to the easterly right of way line of Arlex Drive East per said Arlington Hills Annex; Thence westerly across said Arlex Drive East to the westerly right of way line of said Arlex Drive East per said Arlington Hills Annex and the southerly line of Lot 35 per said Arlington Hills Annex; Thence westerly along said southerly line of Lot 35 per Arlington Hills Annex and the southerly line of Lot 60 per said Arlington Hills Annex to the easterly right of way line of said Arlex Drive West per said Arlington Hills Annex: Thence westerly across said Arlex Drive West per Arlington Hills Annex to the westerly right of way line of said Arlex Drive West per Arlington Hills Annex and the southerly line of Lot 1 per said Arlington Hills Annex; Thence westerly along said southerly line of Lot 1 per Arlington Hills Annex to the easterly line of Block Four, Arlington Hill Unit 3-A as recorded in Plat Book 25, Page 24 of said Public Records; Thence northerly along said easterly line of Block Four, Arlington Hill Unit 3-A to the southerly line of Lot 1, Block Four per said Arlington Hill Unit 3-A; Thence westerly along said southerly line of Lot 1, Block Four per Arlington Hill Unit 3-A to the easterly right of way line of Columbine Drive North (Columbine Street East per said Arlington Hill Unit 3-A); Thence

westerly across said Columbine Drive North (Columbine Street East per said Arlington Hill Unit 3-A) to the westerly right of way line of said Columbine Drive North (Columbine Street East per said Arlington Hill Unit 3-A) and the southerly line of Lot 1, Block Two per said Arlington Hill Unit 3-A; Thence westerly along said southerly line of Lot 1, Block Two per Arlington Hill Unit 3-A and the southerly line of Lot 2 and Lot 3, Block Two per said Arlington Hill Unit 3-A to the easterly right of way line of Pine Summit Drive East (Gaillardia Road East per said Arlington Hill Unit 3-A); Thence westerly across said Pine Summit Drive East (Gaillardia Road East per said Arlington Hill Unit 3-A) to the westerly right of way line of said Pine Summit Drive East (Gaillardia Road East per said Arlington Hill Unit 3-A) and the southerly line of Lot 1, Block One per said Arlington Hill Unit 3-A; Thence westerly along said southerly line of Lot 1, Block One per said Arlington Hill Unit 3-A to the easterly line of Arlington Hills No. 3 as recorded in Plat Book 24, Page 89 of said Public Records; Thence westerly along a westerly prolongation of said southerly line of Lot 1, Block One per Arlington Hill Unit 3-A to the easterly line of Block 3 per said Arlington Hills No. 3; Thence southerly along said easterly line of Block 3 per Arlington Hills No. 3 to the southerly line of Lot 1, Block 3 per said Arlington Hills No. 3; Thence westerly along said southerly line of Lot 1, Block 3 per said Arlington Hills No. 3 to the easterly right of way line of Gaillardia Road per said Arlington Hills No. 3 and the southerly line of Lot 12, Block 2 per said Arlington Hills No. 3; Thence westerly along said southerly line of Lot 12, Block 2 per said Arlington Hills No. 3 and Lot 11 through Lot 1, inclusive, Block 2 per said Arlington Hills No. 3 to the easterly right of way line of Rogero Road per said Arlington Hills No. 3; Thence westerly across said Rogero Road per said Arlington Hills No. 3 to the westerly right of way line of said Rogero Road per said Arlington Hills No. 3 and the southerly line of land per Official Records Book 13406, Page 966 of said Public Records; Thence westerly along said southerly line of land per Official Records Book 13406, Page 966 to the westerly line of Block 1 per said Arlington Hills No. 3; Thence southerly along said westerly line of Block 1 per Arlington Hills No. 3 to the easterly prolongation of the southerly line of Lot 38, Block One Arlington Hills Unit 3-B as recorded in Plat Book 26, Page 22 of said Public Records;

Thence westerly along said easterly prolongation of the southerly line of Lot 38, Block One Arlington Hills Unit 3-B and the southerly line of Lot 38 through Lot 35, inclusive, Block One per said Arlington Hills Unit 3-B to the easterly line of Lot 34, Block One per said Arlington Hills Unit 3-B; Thence southerly along said easterly line of Lot 34, Block One per said Arlington Hills Unit 3-B to Philips Lake; Thence southerly, westerly, and northerly along said Philips Lake to the southerly line of Lot 27, Block One per said Arlington Hills Unit 3-B; Thence westerly along said southerly line of Lot 27, Block One per Arlington Hills Unit 3-B to the easterly right of way line of Ector Road North per said Arlington Hills Unit 3-B; Thence southerly along said easterly right of way line of Ector Road North per Arlington Hills Unit 3-B to the southerly line of Lot 26, Block One per said Arlington Hills Unit 3-B; Thence westerly, along a westerly prolongation of the southerly line of said Lot 26, Block One per said Arlington Hills Unit 3-B, across said Ector Road North per Arlington Hills Unit 3-B to the westerly right of way line of Ector Road North per said Arlington Hills Unit 3-B; Thence northerly along said the westerly right of way line of Ector Road North per Arlington Hills Unit 3-B to the southerly line of Lot 13, Block Four per said Arlington Hills Unit 3-B; Thence westerly along said southerly line of Lot 13, Block Four per Arlington Hills Unit 3-B to the easterly line of Lake Lucina Unit No. 7 as recorded in Plat Book 25, Page 85 of said Public Records; Thence southerly along said easterly line of Lake Lucina

Unit No. 7 to the easterly prolongation of the northerly line of Lot 1, Block 12 per said Lake Lucina Unit No. 7; Thence westerly along said easterly prolongation of the northerly line of Lot 1, Block 12 per Lake Lucina Unit No. 7 to the easterly right of way line of Red Oak Drive per said Lake Lucina Unit No. 7; Thence southerly along said easterly right of way line of Red Oak Drive per Lake Lucina Unit No. 7 to the easterly prolongation of the northerly line of Block 18 per said Lake Lucina Unit No. 7; Thence westerly along said prolongation of the northerly line of Block 18 per said Lake Lucina Unit No. 7 and the northerly line of Block 18 per said Lake Lucina Unit No. 7 to the westerly line of Lot 9. Block 18 per said Lake Lucina Unit No. 7; Thence southerly along said westerly line of Lot 9, Block 18 per said Lake Lucina Unit No. 7 to the northerly right of way line of Greenberry Lane per said Lake Lucina Unit No. 7; Thence westerly along said northerly right of way line of Greenberry Lane per Lake Lucina Unit No. 7 to the easterly right of way line of said Cesery Boulevard per Lake Lucina Unit No. 7; Thence northerly along said easterly right of way line of Cesery Boulevard per Lake Lucina Unit No. 7 to the easterly prolongation of the southerly line of land per Official Records Book 14742, Page 1283 of said Public Records: Thence westerly, along said prolongation of the southerly line of land per Official Records Book 14742, Page 1283, across said Cesery Boulevard per Lake Lucina Unit No. 7 to the westerly right of way line of Cesery Boulevard per Lake Lucina Unit No. 7: Thence southerly along said westerly right of way line of Cesery Boulevard per Lake Lucina Unit No. 7 to the northerly line of Lot 1, Block 14 per said Lake Lucina Unit No. 7; Thence westerly along said northerly line of Lot 1, Block 14 per Lake Lucina Unit No. 7 to the westerly line of Lot 1, Block 14 per said Lake Lucina Unit No. 7; Thence southerly and westerly along said Block 14 per said Lake Lucina Unit No. 7 to the easterly line of land per Official Records Book 8368, Page 1362; Thence southerly along said easterly line of land per Official Records Book 8368, Page 1362 to the southerly line of land per said Official Records Book 8368, Page 1362; Thence westerly along said southerly line of land per Official Records Book 8368, Page 1362 to the easterly line of Lot 1, Block 3 per Lake Lucina Unit No. 1 as recorded in Plat Book 22, Page 35 of said Public Records; Thence southerly along said easterly line of Lot 1, Block 3 per Lake Lucina Unit No. 1 to the northerly right of way line of Liddell Lane per said Lake Lucina Unit No. 1; Thence southerly across said Liddell Lane per Lake Lucina Unit No. 1 to the northerly right of way line of said Liddell Lane per Lake Lucina Unit No. 1 and the easterly line of Lot 1, Block 1 per said Lake Lucina Unit No. 1; Thence southerly along said easterly line of Lot 1, Block 1 per Lake Lucina Unit No. 1 to the northerly line of Lot 25, Block 1 per said Lake Lucina Unit No. 1; Thence southerly along the easterly line of said Lot 25, Block 1 per Lake Lucina Unit No. 1 to the northerly line of Lot 24, Block 1 per said Lake Lucina Unit No. 1; Thence southerly along the easterly line of said Lot 24, Block 1 per Lake Lucina Unit No. 1 and the easterly line of Lot 23 through Lot 17, inclusive, Block 1 per said Lake Lucina Unit No. 1 to the northerly line of Lot 16, Block 1 per said Lake Lucina Unit No. 1; Thence southerly along the easterly line of said Lot 16, Block 1 per Lake Lucina Unit No. 1 to the northerly line of Lot 15, Block 1 per said Lake Lucina Unit No. 1; Thence southerly along the easterly line of said Lot 15, Block 1 per Lake Lucina Unit No. 1 to the northerly right of way line of Lake Lucina Drive per said Lake Lucina Unit No. 1; Thence southerly across said Lake Lucina Drive per Lake Lucina Unit No. 1 to the southerly right of way line of said Lake Lucina Drive per Lake Lucina Unit No. 1 and the easterly line of Lot 1, Block 5 per said Lake Lucina Unit No. 1; Thence easterly along said southerly right of way line of said Lake Lucina Drive per Lake Lucina Unit No. 1 to the northeasterly line of Lot 2, Block 5 per said

Lake Lucina Unit No. 1; Thence southeasterly along said northeasterly line of Lot 2, Block 5 per Lake Lucina Unit No. 1 to the southerly line of said Lot 2, Block 5 per Lake Lucina Unit No. 1, also being the southerly line of Lot 3, Block 5 per Lake Lucina Unit No. 2 as recorded in Plat Book 22, Page 49 of said Public Records; Thence easterly along said southerly line of Lot 3, Block 5 per Lake Lucina Unit No. 2 to Lake Lucina; Thence southerly along said Lake Lucina to the northerly line of land per Official Records Book 8865, Page 398 of said Public Records; Thence westerly along said northerly line of land per Official Records Book 8865, Page 398 to the easterly right of way line of Almira Street (Almira Avenue per Egleston Heights as recorded in Plat Book 1, Page 75 of said Public Records); Thence southerly along said easterly right of way line of Almira Street to the easterly prolongation of the southerly line of Lot 1, Block 5 per said Egleston Heights; Thence westerly, along said easterly prolongation of the southerly line of Lot 1, Block 5 per said Egleston Heights, across said Almira Street to the westerly right of way line of said Almira Street and the southerly line of Lot 1, Block 5 per said Egleston Heights; Thence westerly along said southerly line of Lot 1, Block 5 per Egleston Heights to the easterly line of Lot 4, Block 5 per Egleston Heights: Thence southerly along said easterly line of Lot 4, Block 5 per Egleston Heights and the easterly line of line Lot 6 and Lot 8, Block 5 per Egleston Heights to the northerly line of land per Official Records Book 12793, Page 1758 of said Public Records; Thence southerly along said easterly line of land per Official Records Book 12793, Page 1758 to the northerly right of way line of Floral Bluff Road (Floral Bluff Avenue per said Egleston Heights); Thence southerly across said Floral Bluff Road to the southerly right of way line of said Floral Bluff Road and the easterly line of Lot 2, Block 6 per said Egleston Heights; Thence southerly along said easterly line of Lot 2, Block 6 per Egleston Heights and the easterly line of Lot 4, Lot 6, Lot 8, Lot 10, Lot 12, and Lot 14, Block 6 per said Egleston Heights to the northerly line of land per Official Records Book 13060, Page 109 of said Public Records; Thence easterly along said northerly line of land per Official Records Book 13060, Page 109 to said westerly right of way line of Almira Street; Thence southerly along said westerly right of way line of Almira Street to the northerly right of way line of Dickson Road (Carl Street per said Egleston Heights); Thence westerly along said northerly right of way line of Dickson Road to the northerly prolongation of the easterly line of land per Official Records Book 6077, Page 156 of said Public Records; Thence southerly, along said northerly prolongation of the easterly line of land per Official Records Book 6077, Page 156, across said Dickson Road to the southerly right of way line of said Dickson Road and said easterly line of land per Official Records Book 6077, Page 156; Thence southerly along said easterly line of land per Official Records Book 6077, Page 156 to the northwesterly line of Lot 5, Block 1 per Jacqueline's Subdivision First Addition as recorded in Plat Book 24, Page 34 of said Public Records; Thence southwesterly along said northwesterly line of Lot 5, Block 1 per Jacqueline's Subdivision First Addition to the northeasterly line of Lot 4, Block 1 per Jacqueline's Subdivision First Addition; Thence westerly along the northerly line of said lot 4, Block 1 per Jacqueline's Subdivision First Addition to the easterly line of Lot 1, Block 1 per said Jacqueline's Subdivision First Addition; Thence southerly along said easterly line of Lot 1, Block 1 per Jacqueline's Subdivision First Addition to the northerly line of Lot 3. Block 1 per said Jacqueline's Subdivision First Addition; Thence southeasterly along the northeasterly line of said Lot 3, Block 1 per said Jacqueline's Subdivision First Addition to the northwesterly right of way line of Oliver Street per said Jacqueline's Subdivision First Addition; Thence southeasterly, along a southeasterly prolongation of said

northeasterly line of said Lot 3, Block 1 per said Jacqueline's Subdivision First Addition, across said Oliver Street to the southeasterly right of way line of said Oliver Street per Jacqueline's Subdivision First Addition; Thence southwesterly along said southeasterly right of way line of Oliver Street per Jacqueline's Subdivision First Addition to the northeasterly line of Lot 3, Block 2 per said Jacqueline's Subdivision First Addition; Thence southeasterly along said northeasterly line of Lot 3, Block 2 per said Jacqueline's Subdivision First Addition to the northerly line of land per Official Records Book 16579, Page 826 of said Public Records: Thence easterly along said northerly line of land per Official Records Book 16579, Page 826 to the easterly line of land per said Official Records Book 16579, Page 826; Thence southerly along said easterly line of land per Official Records Book 16579, Page 826 to the southerly line of land per said Official Records Book 16579, Page 826; Thence westerly along said southerly line of land per Official Records Book 16579, Page 826 to the northeasterly line of Lot 1, Block 3 per said Jacqueline's Subdivision First Addition; Thence southeasterly along said northeasterly line of Lot 1, Block 3 per Jacqueline's Subdivision First Addition to the northwesterly right of way line of Michigan Avenue per said Jacqueline's Subdivision First Addition; Thence southeasterly, along a southeasterly prolongation of said northeasterly line of Lot 1, Block 3 per Jacqueline's Subdivision First Addition, across said Michigan Avenue to a northerly prolongation of the easterly line of Lot 17, Block 16 per said Egleston Heights; Thence southerly, along said northerly prolongation of the easterly line of Lot 17, Block 16 per said Egleston Heights, across Wiltshire Street (Seminole Street per said Egleston Heights) to the northerly right of way line of said Wiltshire Street and said easterly line of Lot 17, Block 16 per said Egleston Heights; Thence southerly along said easterly line of Lot 17, Block 16 per Egleston Heights and the easterly line of Lot 18, Block 16 per said Egleston Heights to the northerly right of way line of Windermere Drive (Cherokee Street per said Egleston Heights); Thence easterly along said northerly right of way line of Windermere Drive to the northerly prolongation of the easterly line of Lot 17, Block 18 per said Egleston Heights; Thence southerly, along said northerly prolongation of the easterly line of Lot 17, Block 18 per Egleston Heights, across said Windermere Street to the southerly right of way line of said Windermere Street and said easterly line of Lot 17, Block 18 per Egleston Heights; Thence southerly along said easterly line of Lot 17, Block 18 per Egleston Heights to the northerly line of Lot 16, Block 18 per said Egleston Heights; Thence easterly along said northerly line of Lot 16, Block 18 per Egleston Heights to the easterly line of said Lot 16, Block 18 per Egleston Heights; Thence southerly along said easterly line of Lot 16, Block 18 per Egleston Heights to the northerly right of way line of Ansley Street (Osceola Street per said Egleston Heights): Thence easterly along said northerly right of way line of Ansley Street to the northerly prolongation of the easterly line of Lot 5 per Plat Of Karl L. Olsens Sub-Division as recorded in Plat Book 9, Page 2 of said Public Records; Thence southerly, along said northerly prolongation of the easterly line of Lot 5 per Plat Of Karl L. Olsens Sub-Division, across said Ansley Street to the southerly right of way line of said Ansley Street and said easterly line of Lot 5 per Plat Of Karl L. Olsens Sub-Division; Thence southerly along said easterly line of Lot 5 per Plat Of Karl L. Olsens Sub-Division to the northerly line of Lot 1, Block 8 per Arlington Heights as recorded in Plat Book 4, Page 19 of said Public Records; Thence easterly along said northerly line of Lot 1, Block 8 per Arlington Heights to the easterly line of Lot 1, Block 8 per Arlington Heights; Thence southerly along said easterly line of Lot 1, Block 8 per Arlington Heights and the easterly line of Lot 2 through Lot 5, Block 8 per said Arlington Heights to the northerly right of way line of Macy Avenue (Arlington Avenue per said Arlington Heights); Thence westerly along said northerly right of way line of Macy Avenue per Arlington Heights to the easterly right of way line of Marcheck Street (1st Street per said Arlington Heights), being the southwest corner of Block 8 per said Arlington Heights; Thence southerly across said Macy Avenue to the southerly right of way line of Macy Avenue per said Arlington Heights and said easterly right of way line of Marcheck Street per Arlington Heights, being the northwest corner of Block 7 per said Arlington Heights; Thence southerly along said easterly right of way line of Marcheck Street per Arlington Heights to the northerly right of way line of Commerce Street (Main Street per said Arlington Heights), being the southwest corner of Block 7 per said Arlington Heights; Thence southerly across said Commerce Street to the southerly right of way line of said Commerce Street per Arlington Heights and the easterly right of way line of said Marcheck Street per said Arlington Heights, being the northwest corner of Block 6 per said Arlington Heights; Thence easterly along said southerly right of way line of Commerce Street per Arlington Heights to the westerly right of way line of Rogero Road per State Of Florida State Road Department Right Of Way Map Duval County Section 72500-2615; Thence southerly along said westerly right of way line of Rogero Road per State Of Florida State Road Department Right Of Way Map Duval County Section 72500-2615 to the northerly right of way line of Arlington Road (Arlington Avenue per said State Of Florida State Road Department Right Of Way Map Duval County Section 72500-2615); Thence southerly, across said Arlington Road to the southerly right of way line of said Arlington Road; Thence southerly along said westerly right of way line of Arlington Road to the northerly right of way line of Groveland Drive; Thence westerly along said northerly right of way line of Groveland Drive (James Avenue per said Arlington Heights), to the easterly right of way line of Underhill Drive (14th Street per said Arlington Heights), being the southwest corner of Block 72 per said Arlington Heights; Thence northerly along said easterly right of way line of Underhill Drive per said Arlington Heights to the easterly prolongation of the southerly line of land per Official Records Book 16333, Page 2183 of said Public Records; Thence westerly, along said easterly prolongation of the southerly line of land per Official Records Book 16333, Page 2183, across said Underhill Drive per Arlington Heights to the westerly right of way line of said Underhill Drive per Arlington Heights and the southerly line of land per Official Records Book 16333, Page 2183; Thence westerly along said southerly line of land per Official Records Book 16333, Page 2183 and the southerly line of land per Official Records Book 11513, Page 2171 of said Public Records to the easterly right of way line of Mayer Drive (13th Street per said Arlington Heights); Thence westerly, along the westerly prolongation of said southerly line of land per Official Records Book 11513, Page 2171, across said Mayer Drive per Arlington Heights to the westerly right of way line of said Mayer Drive per Arlington Heights; Thence southerly along said westerly right of way line of Mayer Drive per Arlington Heights to the southerly line of Lot 11, Block 55 per said Arlington Heights; Thence westerly along said southerly line of Lot 11, Block 55 per said Arlington Heights to the easterly line of Lot 8, Block 55 per said Arlington Heights; Thence southerly along said easterly line of Lot 8, Block 55 per said Arlington Heights, the westerly line of Lot 9, Block 55 per said Arlington Heights, and the westerly line of Lot 1 through Lot 3, inclusive, Block 8 per Arlington Shores as recorded in Plat Book 23, Page 95 of said Public Records to the northerly line of Lot 4, Block 8 per said Arlington Shores; Thence westerly along said northerly line of Lot 4, Block 8 per Arlington Shores and the northerly line of Lot 5 and Lot 6, Block 8 per said Arlington Shores to the easterly line of Lot 8, Block 8 per said

Arlington Shores; Thence northerly along said easterly line of Lot 8, Block 8 per Arlington Shores and the easterly line of Lot 9 and Lot 10, Block 8 per said Arlington Shores and the easterly line of Lot 9, Block 46 per said Arlington Heights to the southerly line of Lot 10, Block 46 per Arlington Heights; thence westerly along said southerly line of Lot 10, Block 46 per Arlington Heights to the westerly line of Lot 10, Block 46 per said Arlington Heights; Thence northerly along said westerly line of Lot 10, Block 46 per Arlington Heights and the westerly line of Lot 11, Block 46 per Arlington Heights to the southerly line of Lot 6. Block 46 per said Arlington Heights: Thence westerly along said southerly line of Lot 6. Block 46 per Arlington Heights to the easterly right of way line of Westdale Drive (11th Street per said Arlington Heights); Thence westerly, along the westerly prolongation of said southerly line of Lot 6, Block 46 per Arlington Heights, across said Westdale Drive per Arlington Heights to the westerly right of way line of said Westdale Drive per Arlington Heights; Thence northerly along said westerly right of way line of said Westdale Drive per Arlington Heights to the southerly line of Lot 16, Block 45 per said Arlington Heights; Thence westerly along said southerly line of Lot 16, Block 45 per said Arlington Heights to the easterly line of Lot 4, Block 45 per said Arlington Heights; Thence southerly along said easterly line of Lot 4, Block 45 per said Arlington Heights to the southerly line of land per Official Records Book 8010, page 1983 of said Public Records; Thence westerly along said southerly line of land per Official Records Book 8010, page 1983 to the easterly right of way line of Maitland Avenue (10th Street per said Arlington Heights); Thence westerly, along the westerly prolongation of said southerly line of land per Official Records Book 8010, page 1983, across said Maitland Avenue per said Arlington Heights to the westerly right of way line of Maitland Avenue per said Arlington Heights; Thence northerly along said westerly right of way line of Maitland Avenue per Arlington Heights to the southerly line of Lot 16, Block 36 per said Arlington Heights; Thence westerly along said southerly line of Lot 16, Block 36 per Arlington Heights and the southerly line of Lot 3, Block 36 per said Arlington Heights to the easterly right of way line of Whitlock Avenue (9th Street per said Arlington Heights): Thence westerly, along the westerly prolongation of said southerly line of Lot 3, Block 36 per said Arlington Heights, across said Whitlock Avenue per said Arlington Heights To the westerly right of way line of said Whitlock Avenue per Arlington Heights; Thence southerly along said westerly right of way line of said Whitlock Avenue per Arlington Heights to the southerly line of Lot 14, Block 35 per said Arlington Heights; Thence westerly along said southerly line of Lot 14, Block 35 per said Arlington Heights and the southerly line of Lot 5, Block 35 per said Arlington Heights to the easterly right of way line of Douglas Street (8th Street per said Arlington Heights); Thence southerly along said easterly right of way line of Douglas Street per Arlington Heights to the southerly line of Block 35 per said Arlington Heights; Thence westerly across said Douglas Street to the westerly right of way line of said Douglas Street per said Arlington Heights and the southerly line of Lot 4, Block 29 per said Arlington Heights; Thence westerly along said southerly line of Lot 4, Block 29 per Arlington Heights and the southerly line of land per Official Records Book 13544, Page 290 of said Public Records to the easterly right of way line of Cesery Boulevard per State Of Florida State Road Department Right Of Way Map State Road No. (S-109)109 Duval County Section 72540-2602; Thence westerly, along the prolongation of said southerly line of land per Official Records Book 13544, Page 290, across said Cesery Boulevard per said State Of Florida State Road Department Right Of Way Map to the westerly right of way line of said Cesery Boulevard; Thence northerly along said westerly right of way line of said Cesery Boulevard per said State Of Florida

State Road Department Right Of Way Map to the southerly line of land per Official Records Book 13044, Page 812 of said Public Records; Thence westerly, southerly, and westerly again along line of land per said Official Records Book 13044, Page 812 to the easterly right of way line of Cesery Terrace per said Official Records Book 13044, Page 812; Thence northerly along said easterly right of way line of Cesery Terrace per said Official Records Book 13044, Page 812 to the southerly line of Arlington Heights per said Arlington Heights; Thence westerly along said southerly line of Arlington Heights per Arlington Heights to the northeast corner of land per Deed Book 1386, Page 252 of said Public Records; Thence westerly, southwesterly, westerly again, northwesterly, and westerly again along the northerly line of said land per Deed Book 1386, Page 252 and the northerly line of lands per Deed Book 210, Page 552 of said Public Records, less the road (being Arlington Elementary School parcel) to the easterly right of way line of University Boulevard per State Of Florida State Road Department Right Of Way Map Section 72110-2501 State Road No.109 Duval County; Thence southerly along said easterly right of way line of University Boulevard per State Of Florida State Road Department Right Of Way Map Section 72110-2501 to the northerly right of way line of Harris Avenue: Thence easterly along said northerly right of way line of Harris Avenue to a point of deflection to the left: Thence southerly across said Harris Avenue to the southerly right of way line of said Harris Avenue, also being a point of deflection to the left; Thence easterly along said southerly right of way line of Harris Avenue to the westerly line of Lot 29 per Harris Addition To Arlington, Florida as recorded in Plat Book 5, Page 88 and Plat Book 7, Page 9 of said Public Records; Thence southerly along said westerly line of Lot 29 per Harris Addition To Arlington, Florida to the southerly line of said Harris Addition To Arlington, Florida per Harris Addition To Arlington, Florida; Thence easterly along said southerly line of said Harris Addition To Arlington, Florida per Harris Addition To Arlington, Florida to the westerly line of land per Deed Book 1390, Page 486 of said Public Records; Thence southerly along said westerly line of Deed Book 1390, Page 486 to southerly line of land per said Deed Book 1390, Page 486; Thence easterly along said southerly line of land per Deed Book 1390, Page 486 to the westerly right of way line of Cesery Terrace; Thence southerly along said westerly right of way line of Cesery Terrace to the southerly right of way line of Ashite Street; Thence easterly, along the easterly projection of said southerly right of way line of Ashite Street, across said Cesery Terrace to the easterly right of way line of Cesery Terrace; Thence easterly along said southerly right of way line of Ashite Street to the westerly right of way line of said Cesery Boulevard per State Of Florida State Road Department Right Of Way Map State Road No. (S-109)109 Duval County Section 72540-2602: Thence southerly along said westerly right of way line of Cesery Boulevard per State Of Florida State Road Department Right Of Way Map State Road No. (S-109)109 Duval County Section 72540-2602 to the northerly right of way line of State Road No. 115 (Arlington Expressway) per State Of Florida State Road Department Right Of Way Map Section 7204-178 Road No. (A1A) 10 Duval County; Thence westerly along said northerly right of way line of State Road No. 115 (Arlington Expressway) per State Of Florida State Road Department Right Of Way Map Section 7204-178 Road No. (A1A) 10 Duval County to the southwest corner of land per Deed Book 1706, Page 369 of said Public Records: Thence westerly across University Boulevard to said northerly right of way line of State Road No. 115 (Arlington Expressway) per State Of Florida State Road Department Right Of Way Map Section 7204-178 Road No. (A1A) 10 Duval County; Thence westerly along said northerly right of way line of State Road No. 115 (Arlington

Expressway) per State Of Florida State Road Department Right Of Way Map Section 7204-178 Road No. (A1A) 10 Duval County to the southwest corner of land per Official Records Book 14661, Page 374 of said Public Records; Thence northerly along the westerly line of land per said Official Records Book 14661, Page 374, the westerly line of land per Official Records Book 659, Page 277 of said Public Records, and the westerly line of land per Official Records Book 313, Page 581 of said Public Records to the Point Of Beginning.


I Hereby Certify That To The Best Of My Knowledge And Belief This Legal Description Is True, Accurate, And Was Prepared Under My Direction. I Further Certify That Said Legal Description Is In Compliance With The Standards Of Practice As Set Forth By The Florida Board Of Professional Surveyors And Mappers, Pursuant To Section 472.027, Florida Statutes.

John A. Anderberg


Date

Florida Professional Surveyor And Mapper No. 5881 8001 Belfort Parkway, Suite 200 Jacksonville, Florida, 32256 (904) 641-0123

This Description And Copies Thereof Are Not Valid Without The Surveyor's Signature And Original Raised Seal.	



REVISED EXHIBIT 2 PAGE 64 OF 65



REVISED EXHIBIT 2 PAGE 65 OF 65