SUBJECT: **DEMO & SITE CLEARANCE OF (50) PROPERTIES**

BID# CF-0336-16 OPEN DATE: **2015-11-18**

GENERAL GOVERNMENT AWARDS COMMITTEE

KIND AND BASIS OF CONTRACT:
CONSTRUCTION FIXED

AGENCY: **MUNICIPAL CODE**

BASIS OF AWARD: **BY ITEM TO THE LOWEST RESPONSIVE, RESPONSIBLE BIDDER**

NUMBER OF BIDS INVITED 7 NUMBER RECEIVED 4 OTHER 0

SUMMARY OF BIDS AND RECOMMENDED ACTIONS:

Item #36 was awarded to Michael Lloyd Hauling on 12/3/15, in the amount of $35,800.00 which included $800.00 cost of asbestos survey as required by bid specifications. The performed asbestos survey requires a wet demolition be performed prior to demolition.

Recommend approval to rescind the award from Michael Lloyd Hauling for Item #36 (PO# 604871 reduced from $35,800.00 to $800.00 to pay for the asbestos survey) and re-award the wet demolition to the new lowest responsive, responsible bidder P & G Land Clearing, in the amount of $38,975.00 (less survey) and $3,000.00 for the wet demolition. Revised total award amount for Item #36 not-to-exceed $41,975.00.

This award to be funded by account: ERCD1N1FR-03410 to be executed by Purchase Order/Change Order.

Attachments: Recommendation Memo, Asbestos Report, Previous Award

BUYER: Marilyn Laidler
MARILYN LAIDLER

RESPECTFULLY SUBMITTED: Greg Pease
GREGORY PEASE, CHIEF
PROCUREMENT DIVISION

CONCURRENCE BY: **Bryan Mosier, Chief, Municipal Code Compliance Division**

(ALL AWARD ACTIONS SUBJECT TO LAWFULLY APPROPRIATED FUNDS)
ACTION OF GGAC COMMITTEE ON RECOMMENDATIONS ABOVE

MEMBERS APPROVING _____ MEMBERS DISAPPROVING _____ DATE: _____

_____ _____ OTHER: _____

_____ _____

_____ _____

ACTION OF AWARDING AUTHORITY DATE: _____

APPROVED _____ DISAPPROVED _____

OTHER _____

SIGNATURE OF AUTHENTICATION _____

FORM GB-108, Revised 12/2007

NEIGHBORHOODS DEPARTMENT

MUNICIPAL CODE COMPLIANCE DIVISION

Jacksonville
Where Florida Begins.

February 1, 2017

M E M O R A N D U M

TO: Gregory Pease, Division Chief
Procurement Division

FROM: Bryan Mosier, Division Chief
Municipal Code Compliance Division

RE: Change Order Request for Item #36 on Formal Demolition Bid #CF- 0336-16

The asbestos survey of 2081 Walnut St revealed the asbestos content of the floor tile, sheet flooring and roof mastic which requires wet demolition.

I recommend approval to rescind the award from Michael Lloyd Hauling (PO# 604871 reduced from $35,800.00 to $800.00 to pay for the asbestos survey) and re-award the wet demolition to the new lowest, responsible, responsive bidder P&G Land Clearing in the amount of $41,975.00.

Contractor	Item Number	Amount
P&G Land Clearing, Inc.	36	$41,975.00

Funding Source: ERCD1N1FR / 03410.

BM/mc

ENVIRONEERING INC.
109 AZALEA POINT DRIVE SOUTH • PONTE VEDRA BEACH • FLORIDA • 32082

April 26, 2016

Mr. Michael Lloyd
Michael Llyod Hauling, Inc.
1601 Rudd Road
Jacksonville, Florida 32220

Reference: One (1) Two Story Structure – Asbestos Demolition Survey – Commercial Bldg.
2081 Walnut Street
Jacksonville, Florida

Dear Mr. Llyod:

Pursuant to your request an Asbestos Demolition Survey has been performed at the above location for the purpose of identifying asbestos that needs to be removed prior to the planned demolition of the structure. The purpose of the investigation was to visually identify homogenous materials that need to have bulk samples obtained for analysis to determine the presence of Asbestos Containing Building Materials with in the structure. The scope of this survey was limited to the referenced single structure in Jacksonville, Florida. The building was inspected for demolition. The facility has a single two story structure for demolition, which is constructed with concrete, drywall, wood, roof mastic, vinyl floor tile, sheet flooring, single ply roof system, built-up roof system, metal roof system, ceiling tile, pipe wrap, steel and aluminum. There were forty (40) suspected materials that were sampled for Polarized Light Microscopy (PLM) analysis. Based on the visual inspection, it was evident that regulated Asbestos Material was found to be present at the facility. The scope of work for this survey included sampling and analysis of suspect homogenous building materials. The asbestos demolition inspection process was initiated on April 21, 2016. Materials must contain greater than 1% asbestos to be regulated. The following recommendations are provided for the material that was found to contain Asbestos Fibers within the referenced structure.

RECOMMENDATIONS

Recommended response actions have been selected for all Asbestos Containing Materials identified by this survey within the facility. Recommendations for response actions, where arrived at, are stated as follows:

FRIABLE ASBESTOS CONTAINING MATERIALS

Friable Asbestos Material means any material containing more than one (1%) percent asbestos, that when dry can be crumbled, pulverized or reduced to powder by hand pressure.

(904) 665-0100 (904) 612-1456 • MOBILE (904) 665-0101 • FAX

Friable Asbestos Material was found in the following area:

None.

The above material is considered friable and must be removed by a Certified Florida Asbestos Abatement Contractor prior to any disturbance caused by renovation or demolition of the referenced structure.

CATEGORY I, NON-FRIABLE ASBESTOS MATERIAL

HM-6 9"X9" Vinyl Floor Tile (VFT) Brown w/ Black Mastic (Center Building 1st & 2nd Floor) [1.5% Chrysotile Asbestos Tile, 1.5% Chrysotile Asbestos Mastic, Composite = 1.5% Chrysotile Asbestos]

HM-7 Sheet Flooring - Beige 1st Layer, Sheet Flooring brown Pebble 2nd Layer over 9"X9" (VFT) Brown /Black/Green w/ Black Mastic [20% Chrysotile Asbestos]

CATEGORY II, NON-FRIABLE ASBESTOS MATERIAL

None.

NONREGULATED BY NESHAP; REGULATED BY OSHA

HM-13 Roof Mastic - Wall - Black [<1% Chrysotile Asbestos]

The preceding materials are considered a Category I or II Non-Friable Material and therefore, under normal circumstances, the Category I material does not need not be removed prior to demolition, because generally these materials do not release significant amounts of Asbestos Fibers, even when damaged.

Category I material must be kept wet to prevent the release of fibers during demolition. The Category I asbestos waste must be placed in a permitted asbestos landfill in accordance with FDEP regulations. Friable asbestos and Category II material must be removed prior to demolition or renovation of the structure.

Yet, in the event removal is deemed necessary as a part of renovation all Asbestos Containing Material should be removed by a Florida Licensed Asbestos Contractor.

The building materials identified in this asbestos renovation survey were in good condition to significantly damaged at the time of the inspection. The material condition can change over time and will degrade with exposure to water, air movement, physical damage, weather and chemical exposure.

The structure has an address of, 2081 Walnut Street, Jacksonville, Florida. The facility was at one time a commercial building. The facility has one structure for demolition.

When implementing the response actions, parties responsible for final selection should remember that actions shall be sufficient to protect HUMAN HEALTH AND THE ENVIRONMENT, but may also be the least burdensome method. Nothing in these recommendations should be construed as PROHIBITING or discouraging removal.

All parties shall comply with all applicable laws, ordinances, rules and regulations of Federal, State and Local Governments and Agencies relating to or affecting the proposed work in whole or in part when implementing any response action associated with the facility.

The following samples are recommended to be further analyzed by the point count method using a positive stop approach.

None.

This asbestos survey shall not be used as a design or specification for the removal of asbestos within the referenced structure.

RECOMMENDATIONS FOR ASBESTOS ABATEMENT: (2081 Walnut Street, Jacksonville, Florida)

The HM-6, HM-7 and HM-13 asbestos materials should be wet demolished or should be removed by an asbestos abatement contractor keeping in mind that the most economical method or least burdensome method can be used.

It has been a pleasure working with you and I look forward to working with you once again in the future. I can be reached at (904) 665-0100 or mobile (904) 612-1456 if you should have any questions.

Respectfully submitted,

Timothy W. Rudolph, P.E., L.A.C.
Licensed Asbestos Consultant AX 0000058
Asbestos Business License ZA0000243
< MICHAEL LLOYD HAULING-ASBESTOS- SURVEY-JON-5572.doc>

4/26/2016

1004469

ROUTINE **CHAIN OF CUSTODY FORM** **JON 5572**

ENVIRONEERING, INC., 109 Azalea Point Drive South, Ponte Vedra Beach, Florida 32082

To Laboratory: Dove Environmental Laboratory
8910 Miramar Parkway, Suite 200
Miramar, FL 33025

ROUTINE TAT

Customer Information
Company Name: ENVIRONEERING, INC
Address: 109 Azalea Point Drive South
City, State, Zip: Ponte Vedra Beach, FL 32082
Contact: Mr. Tim Rudolph

Date: 4/21/2016
Phone: (904) 665-0100
Fax: (904) 665-0101
Project: Michael Lloyd Hauling, Inc.
2081 Walnut Street
Jacksonville, FL
<COC-DOVE-5571-1.XLS>

Sample #	Sample Type	Sample Location	COLOR/AREA	F/NF
1-1,2,&3	BULK	Drywall System - White	White/Ceilings	F/NF
2-1,2,&3	BULK	Plaster System Two Coats White/Gray over Drywall Board	White/Ceilings/Walls	F/NF
3-1,2,&3	BULK	Wall Board - Gray (South Building)	Gray/Walls	NF
4-1,2,&3	BULK	Partition Wall Insualtion - White Mineral Glass/Wool with Cloth Covering	White/Walls	F
5-1,2,&3	BULK	4'X2' Ceiling Tile - Worm with Pin Hole Pattern - White (Office Center Building)	White/Ceiling	F
6-1,2,&3	BULK	9"X9" Vinyl Floor Tile (VFT) Brown w/ Black Matic (Center Building 1st & 2nd Floor)	Brown/Floor	NF
7-1,2,&3	BULK	Sheet Flooring - Beige 1st Layer, Sheet Flooring brown Pebble 2nd Layer over 9"X9" (VFT) Brown /Black/Green w/ Black Matic	Beige/Floor	NF
8-1,2,&3	BULK	Pipe Wrap - Black (South Building)	Black/Pipes	NF
9-1,2,&3	BULK	Built Up Roof System - Black (South Building)	Black/Roof	NF
10-1,2,&3	BULK	Roof Flashing - Black (South Building)	Black/Roof	NF

ASBESTOS - PLM * USE POSITIVE STOP METHOD *

CHAIN OF CUSTODY CHECK # 2643

Date/Time	Released by:
4/22/16 - 10:00:00	TIM RUDOLPH

ENCLOSURE (1)
ENVIRONEERING, Inc. Ltr Dtd 4/26/16

c:\program files\Microsoft office\office\winword

D604464

ROUTINE **CHAIN OF CUSTODY FORM** **JON 5572**

ENVIRONEERING, INC., 109 Azalea Point Drive South, Ponte Vedra Beach, Florida 32082

To Laboratory: Dove Environmental Laboratory
8910 Miramar Parkway, Suite 200
Miramar, FL 33025

ROUTINE TAT

Customer Information
Company Name: ENVIRONEERING, INC.
Address: 109 Azalea Point Drive South
City, State, Zip: Ponte Vedra Beach, FL 32082
Contact: Mr. Tim Rudolph

Date: 4/21/2016
Phone: (904) 665-0100
Fax: (904) 665-0101
Project: Michael Lloyd Hauling, Inc.
2081 Walnut Street
Jacksonville, FL
<COC-DOVE-5571-1.XLS>

Sample #	Sample Type	Sample Location	COLOR/AREA	F/NF
11-1,2,&3	BULK	Single Ply Roof System - Mop Down - Black w/ Silver Paint (North Building)	Black/Roof	NF
12-1,2,&3	BULK	Exterior Stucco - Gray (South Building)	Gray/Walls	NF
13-1,2,&3	BULK	Roof Mastic - Wall - Black	Black/Walls	NF
14-1	BULK	Electrical Wiring - Black	Black/Building	NF

ASBESTOS - PLM * USE POSITIVE STOP METHOD *

CHAIN OF CUSTODY CHECK # 2643

Date/Time	Released by:	Date/Time	Released by:
4/22/16 - 10:00:00			
c:\program files\Microsoft office\office\mcs.inf	TIM RUDOLPH		

DOVE ENVIRONMENTAL CORP.
8910 MIRAMAR PARKWAY, SUITE 200 MIRAMAR FL 33025
Tel. (954) 374-9274 Fax: (954) 639-7426

ASBESTOS TEST REPORT

CLIENT : ENVIRONEERING, INC.
ADDRESS: 109 AZALEA POINT DRIVE., SOUTH
PONTE VEDRA BCH FL 32082
PROJECT: JON 5572// MICHAEL LLOYD HAULING, INC..
2081 WALNUT STREET JACKSONVILLE, FL
CONSULT: TIM RUDOLPH

PAGE : 1
DATE : 04/25/16
SAMPLE ID : D604469
NVLAP Lab Code: 102053-0

LAB NO. : 01
FRI/HOM : YES/NO LAYERS: 03
DESCRIPTION : DRYWALL SYSTEM - WHITE
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 20% CELLULOSE
NON FIBERS : 70% MINERALS

SAMPLE NO.: 1-1
DATE OF ANALYSIS: 04/25/16

10% PAINT

LAB NO. : 02
FRI/HOM : YES/NO LAYERS: 03
DESCRIPTION : DRYWALL SYSTEM - WHITE
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 20% CELLULOSE
NON FIBERS : 70% MINERALS

SAMPLE NO.: 1-2
DATE OF ANALYSIS: 04/25/16

10% PAINT

LAB NO. : 03
FRI/HOM : YES/NO LAYERS: 03
DESCRIPTION : DRYWALL SYSTEM - WHITE
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 20% CELLULOSE
NON FIBERS : 70% MINERALS

SAMPLE NO.: 1-3
DATE OF ANALYSIS: 04/25/16

10% PAINT

Dove Environmental Corporation is solely responsible for analysis performed on sample content supplied by client and is NVLAP accredited for Method 40 CFR Pt. 736, App. E to Subpart E EPA/600/R-93/116. Measurement Uncertainty information is available by contacting the Laboratory. Laboratory Reports will be kept for a period of three (3) years electronically. Percentages are visually estimated. Point count performed at clients request only. Results relates only to item analyzed. This report should not be reproduced by client or anyone without written permision from Dove Environmental Corporation. All samples will be stored for a period of 1 month. The use of the term NVLAP does not constitute endorsement by NVLAP or any agency of the United States Government. Floor-Tile is non-homogeneous and results only reflect sample content.

Analyst 1

R. Pepe Ramnath, PhD
LABORATORY MANAGER

DOVE ENVIRONMENTAL CORP.
8910 MIRAMAR PARKWAY, SUITE 200 MIRAMAR FL 33025
Tel. (954) 374-9274 Fax: (954) 639-7426

ASBESTOS TEST REPORT

CLIENT : ENVIRONEERING, INC.
ADDRESS: 109 AZALEA POINT DRIVE.. SOUTH
PONTE VEDRA BCH FL 32082
PROJECT: JON 5572// MICHAEL LLOYD HAULING, INC..
2081 WALNUT STREET JACKSONVILLE, FL
CONSULT: TIM RUDOLPH

PAGE : 2
DATE : 04/25/16
SAMPLE ID : D604469
NVLAP Lab Code: 102053-0

LAB NO. : 04
FRI/HOM : NO/NO LAYERS: 02
SAMPLE NO.: 2-1
DATE OF ANALYSIS: 04/25/16
DESCRIPTION : PLASTER SYSTEM TWO COATS WHITE/GRAY OVER DRYWALL BOARD
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 5% CELLULOSE
NON FIBERS : 55% MINERALS 10% PAINT
30% POLYMERS

LAB NO. : 05
FRI/HOM : NO/NO LAYERS: 02
SAMPLE NO.: 2-2
DATE OF ANALYSIS: 04/25/16
DESCRIPTION : PLASTER SYSTEM TWO COATS WHITE/GRAY OVER DRYWALL BOARD
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 5% CELLULOSE
NON FIBERS : 55% MINERALS 10% PAINT
30% POLYMERS

LAB NO. : 06
FRI/HOM : NO/NO LAYERS: 02
SAMPLE NO.: 2-3
DATE OF ANALYSIS: 04/25/16
DESCRIPTION : PLASTER SYSTEM TWO COATS WHITE/GRAY OVER DRYWALL BOARD
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 5% CELLULOSE
NON FIBERS : 55% MINERALS 10% PAINT
30% POLYMERS

Dove Environmental Corporation is solely responsible for analysis performed on sample content supplied by client and is NVLAP accredited for Method 40 CFR Pt. 736, App. E to Subpart E EPA/600/R-93/116. Measurement Uncertainty information is available by contacting the Laboratory. Laboratory Reports will be kept for a period of three (3) years electronically. Percentages are visually estimated. Point count performed at clients request only. Results relates only to item analyzed. This report should not be reproduced by client or anyone without written permision from Dove Environmental Corporation. All samples will be stored for a period of 1 month. The use of the term NVLAP does not constitute endorsement by NVLAP or any agency of the United States Government. Floor-Tile is non-homogeneous and results only reflect sample content.

Analyst 1

R. Pepe Ramnath, PhD
LABORATORY MANAGER

DOVE ENVIRONMENTAL CORP.
8910 MIRAMAR PARKWAY, SUITE 200 MIRAMAR FL 33025
Tel. (954) 374-9274 Fax: (954) 639-7426

ASBESTOS TEST REPORT

CLIENT : ENVIRONEERING. INC.
ADDRESS: 109 AZALEA POINT DRIVE., SOUTH
PONTE VEDRA BCH FL 32082
PROJECT: JON 5572// MICHAEL LLOYD HAULING, INC..
2081 WALNUT STREET JACKSONVILLE, FL
CONSULT: TIM RUDOLPH

PAGE : 3
DATE : 04/25/16
SAMPLE ID : D604469
NVLAP Lab Code: 102053-0

LAB NO. : 07
FRI/HOM : YES/NO LAYERS: 02
DESCRIPTION : WALL BOARD - GRAY (SOUTH BUILDING)
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 70% CELLULOSE
NON FIBERS : 20% MINERALS

SAMPLE NO.: 3-1
DATE OF ANALYSIS: 04/25/16

10% PAINT

LAB NO. : 08
FRI/HOM : YES/NO LAYERS: 02
DESCRIPTION : WALL BOARD - GRAY (SOUTH BUILDING)
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 70% CELLULOSE
NON FIBERS : 20% MINERALS

SAMPLE NO.: 3-2
DATE OF ANALYSIS: 04/25/16

10% PAINT

LAB NO. : 09
FRI/HOM : YES/NO LAYERS: 02
DESCRIPTION : WALL BOARD - GRAY (SOUTH BUILDING)
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 70% CELLULOSE
NON FIBERS : 20% MINERALS

SAMPLE NO.: 3-3
DATE OF ANALYSIS: 04/25/16

10% PAINT

Dove Environmental Corporation is solely responsible for analysis performed on sample content supplied by client and is NVLAP accredited for Method 40 CFR Pt. 736, App. E to Subpart E EPA/600/R-93/116. Measurement Uncertainty information is available by contacting the Laboratory. Laboratory Reports will be kept for a period of three (3) years electronically. Percentages are visually estimated. Point count performed at clients request only. Results relates only to item analyzed. This report should not be reproduced by client or anyone without written permision from Dove Environmental Corporation. All samples will be stored for a period of 1 month. The use of the term NVLAP does not constitute endorsement by NVLAP or any agency of the United States Government. Floor-Tile is non-homogeneous and results only reflect sample content.

Analyst 1

R. Pepe Ramnath, PhD
LABORATORY MANAGER

DOVE ENVIRONMENTAL CORP.
8910 MIRAMAR PARKWAY, SUITE 200 MIRAMAR FL 33025
Tel. (954) 374-9274 Fax: (954) 639-7426

ASBESTOS TEST REPORT

CLIENT : ENVIRONEERING, INC.
ADDRESS: 109 AZALEA POINT DRIVE., SOUTH
PONTE VEDRA BCH FL 32082
PROJECT: JON 5572// MICHAEL LLOYD HAULING, INC..
2081 WALNUT STREET JACKSONVILLE, FL
CONSULT: TIM RUDOLPH

PAGE : 4
DATE : 04/25/16
SAMPLE ID : D604469
NVLAP Lab Code: 102053-0

LAB NO. : 10
FRI/HOM : YES/YES LAYERS: 01
SAMPLE NO.: 4-1
DATE OF ANALYSIS: 04/25/16
DESCRIPTION : PARTITION WALL INSULATION - WHITE MINERIAL GLASS/WOOL W/CLOTH COVERING
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 80% CELLULOSE 10% SYNTHETIC
NON FIBERS : 10% MINERALS

LAB NO. : 11
FRI/HOM : YES/YES LAYERS: 01
SAMPLE NO.: 4-2
DATE OF ANALYSIS: 04/25/16
DESCRIPTION : PARTITION WALL INSULATION - WHITE MINERIAL GLASS/WOOL W/CLOTH COVERING
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 80% CELLULOSE 10% SYNTHETIC
NON FIBERS : 10% MINERALS

LAB NO. : 12
FRI/HOM : YES/YES LAYERS: 01
SAMPLE NO.: 4-3
DATE OF ANALYSIS: 04/25/16
DESCRIPTION : PARTITION WALL INSULATION - WHITE MINERIAL GLASS/WOOL W/CLOTH COVERING
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 80% CELLULOSE 10% SYNTHETIC
NON FIBERS : 10% MINERALS

Dove Environmental Corporation is solely responsible for analysis performed on sample content supplied by client and is NVLAP accredited for Method 40 CFR Pt. 736, App. E to Subpart E EPA/600/R-93/116. Measurement Uncertainty information is available by contacting the Laboratory. Laboratory Reports will be kept for a period of three (3) years electronically. Percentages are visually estimated. Point count performed at clients request only. Results relates only to item analyzed. This report should not be reproduced by client or anyone without written permision from Dove Environmental Corporation. All samples will be stored for a period of 1 month. The use of the term NVLAP does not constitute endorsement by NVLAP or any agency of the United States Government. Floor-Tile is non-homogeneous and results only reflect sample content.

Analyst 1

R. Pepe Ramnath, PhD
LABORATORY MANAGER

DOVE ENVIRONMENTAL CORP.
8910 MIRAMAR PARKWAY, SUITE 200 MIRAMAR FL 33025
Tel. (954) 374-9274 Fax: (954) 639-7426

ASBESTOS TEST REPORT

CLIENT : ENVIRONEERING, INC.
ADDRESS: 109 AZALEA POINT DRIVE., SOUTH
PONTE VEDRA BCH FL 32082
PROJECT: JON 5572// MICHAEL LLOYD HAULING, INC..
2081 WALNUT STREET JACKSONVILLE, FL
CONSULT: TIM RUDOLPH

PAGE : 5
DATE : 04/25/16
SAMPLE ID : D604469
NVLAP Lab Code: 102053-0

LAB NO. : 13
FRI/HOM : YES/NO LAYERS: 03 SAMPLE NO.: 5-1
DATE OF ANALYSIS: 04/25/16
DESCRIPTION : 4'X2' CEILING TILE - WORM WITH PIN HOLE PATT.
WHITE (OFFICE CENTER BUILDING)
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 40% CELLULOSE 15% FIBER-GLASS
15% MINERAL WOOL
NON FIBERS : 10% MINERALS 10% PAINT
5% PERLITES 5% GLASS-SHOTS

LAB NO. : 14
FRI/HOM : YES/NO LAYERS: 03 SAMPLE NO.: 5-2
DATE OF ANALYSIS: 04/25/16
DESCRIPTION : 4'X2' CEILING TILE - WORM WITH PIN HOLE PATT.
WHITE (OFFICE CENTER BUILDING)
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 40% CELLULOSE 15% FIBER-GLASS
15% MINERAL WOOL
NON FIBERS : 10% MINERALS 10% PAINT
5% PERLITES 5% GLASS-SHOTS

LAB NO. : 15
FRI/HOM : YES/NO LAYERS: 03 SAMPLE NO.: 5-3
DATE OF ANALYSIS: 04/25/16
DESCRIPTION : 4'X2' CEILING TILE - WORM WITH PIN HOLE PATT.
WHITE (OFFICE CENTER BUILDING)
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 40% CELLULOSE 15% FIBER-GLASS
15% MINERAL WOOL
NON FIBERS : 10% MINERALS 10% PAINT
5% PERLITES 5% GLASS-SHOTS

Dove Environmental Corporation is solely responsible for analysis performed on sample content supplied by client and is NVLAP accredited for Method 40 CFR Pt. 736, App. E to Subpart E EPA/600/R-93/116. Measurement Uncertainty information is available by contacting the Laboratory. Laboratory Reports will be kept for a period of three (3) years electronically. Percentages are visually estimated. Point count performed at clients request only. Results relates only to item analyzed. This report should not be reproduced by client or anyone without written permision from Dove Environmental Corporation. All samples will be stored for a period of 1 month. The use of the term NVLAP does not constitute endorsement by NVLAP or any agency of the United States Government. Floor-Tile is non-homogeneous and results only reflect sample content.

Analyst 1

R. Pepe Ramnath, PhD
LABORATORY MANAGER

DOVE ENVIRONMENTAL CORP.
8910 MIRAMAR PARKWAY, SUITE 200 MIRAMAR FL 33025
Tel. (954) 374-9274 Fax: (954) 639-7426

ASBESTOS TEST REPORT

CLIENT : ENVIRONEERING, INC.
ADDRESS: 109 AZALEA POINT DRIVE., SOUTH
PONTE VEDRA BCH FL 32082
PROJECT: JON 5572// MICHAEL LLOYD HAULING, INC..
2081 WALNUT STREET JACKSONVILLE, FL
CONSULT: TIM RUDOLPH

PAGE : 6
DATE : 04/25/16
SAMPLE ID : D604469
NVLAP Lab Code: 102053-0

LAB NO. : 16
FRI/HOM : NO/NO LAYERS: 02
SAMPLE NO.: 6-1
DATE OF ANALYSIS: 04/25/16
DESCRIPTION : 9"X9" VFT BROWN W/BLK MASTIC
TILE=1.5%CHRY, MASTIC=1.5%CHRY, COMP=1.5%CHRY
ASBESTOS TYPE: 1.5 % CHRYSOTILE
OTHER FIBERS : 3.5 % CELLULOSE
NON FIBERS : 55% MINERALS
10% RESINS
30% POLYMERS

LAB NO. : 17
FRI/HOM : NO/NO LAYERS: 02
SAMPLE NO.: 6-2
DATE OF ANALYSIS: 04/25/16
DESCRIPTION : 9"X9" VFT BROWN W/BLK MASTIC
TILE=1.5%CHRY, MASTIC=1.5%CHRY, COMP=1.5%CHRY
ASBESTOS TYPE: 1.5 % CHRYSOTILE
OTHER FIBERS : 3.5 % CELLULOSE
NON FIBERS : 55% MINERALS
10% RESINS
30% POLYMERS

LAB NO. : 18
FRI/HOM : NO/NO LAYERS: 02
SAMPLE NO.: 6-3
DATE OF ANALYSIS: 04/25/16
DESCRIPTION : 9"X9" VFT BROWN W/BLK MASTIC
TILE=1.5%CHRY, MASTIC=1.5%CHRY, COMP=1.5%CHRY
ASBESTOS TYPE: 1.5 % CHRYSOTILE
OTHER FIBERS : 3.5 % CELLULOSE
NON FIBERS : 55% MINERALS
10% RESINS
30% POLYMERS

Dove Environmental Corporation is solely responsible for analysis performed on sample content supplied by client and is NVLAP accredited for Method 40 CFR Pt. 736, App. E to Subpart E EPA/600/R-93/116. Measurement Uncertainty information is available by contacting the Laboratory. Laboratory Reports will be kept for a period of three (3) years electronically. Percentages are visually estimated. Point count performed at clients request only. Results relates only to item analyzed. This report should not be reproduced by client or anyone without written permision from Dove Environmental Corporation. All samples will be stored for a period of 1 month. The use of the term NVLAP does not constitute endorsement by NVLAP or any agency of the United States Government. Floor-Tile is non-homogeneous and results only reflect sample content.

Analyst 1

R. Pepe Ramnath, PhD
LABORATORY MANAGER

DOVE ENVIRONMENTAL CORP.
8910 MIRAMAR PARKWAY, SUITE 200 MIRAMAR FL 33025
Tel. (954) 374-9274 Fax: (954) 639-7426

ASBESTOS TEST REPORT

CLIENT : ENVIRONEERING, INC.
ADDRESS: 109 AZALEA POINT DRIVE., SOUTH
PONTE VEDRA BCH FL 32082
PROJECT: JON 5572// MICHAEL LLOYD HAULING, INC..
2081 WALNUT STREET JACKSONVILLE, FL
CONSULT: TIM RUDOLPH

PAGE : 7
DATE : 04/25/16
SAMPLE ID : D604469
NVLAP Lab Code: 102053-0

LAB NO. : 19
FRI/HOM : NO/NO LAYERS: 04
SAMPLE NO.: 7-1
DATE OF ANALYSIS: 04/25/16
DESCRIPTION : SF-BEIGE 1ST LAYER, SF BROWN PEBBLE 2ND LAYER O/
9"X9" VFT BR/BLK/GR W/BLK/M - FELT LAYER=20% CHRY
ASBESTOS TYPE: 20% CHRYSOTILE
OTHER FIBERS : 10% CELLULOSE
NON FIBERS : 30% MINERALS 30% POLYMERS
10% RESINS

LAB NO. : 20
FRI/HOM : NO/NO LAYERS: 04
SAMPLE NO.: 7-2
DATE OF ANALYSIS: 04/25/16
DESCRIPTION : STOP @ 1ST POSTIVE
ASBESTOS TYPE:
OTHER FIBERS :
NON FIBERS :

LAB NO. : 21
FRI/HOM : NO/NO LAYERS: 04
SAMPLE NO.: 7-3
DATE OF ANALYSIS: 04/25/16
DESCRIPTION : STOP @ 1ST POSTIVE
ASBESTOS TYPE:
OTHER FIBERS :
NON FIBERS :

Dove Environmental Corporation is solely responsible for analysis performed on sample content supplied by client and is NVLAP accredited for Method 40 CFR Pt. 736, App. E to Subpart E EPA/600/R-93/116. Measurement Uncertainty information is available by contacting the Laboratory. Laboratory Reports will be kept for a period of three [3] years electronically. Percentages are visually estimated. Point count performed at clients request only. Results relates only to item analyzed. This report should not be reproduced by client or anyone without written permision from Dove Environmental Corporation. All samples will be stored for a period of 1 month. The use of the term NVLAP does not constitute endorsement by NVLAP or any agency of the United States Government. Floor-Tile is non-homogeneous and results only reflect sample content.

Analyst 1

R. Pope Ramnath, PhD
LABORATORY MANAGER

DOVE ENVIRONMENTAL CORP.
8910 MIRAMAR PARKWAY, SUITE 200 MIRAMAR FL 33025
Tel. (954) 374-9274 Fax: (954) 639-7426

ASBESTOS TEST REPORT

CLIENT : ENVIRONEERING, INC.
ADDRESS: 109 AZALEA POINT DRIVE., SOUTH
PONTE VEDRA BCH FL 32082
PROJECT: JON 5572// MICHAEL LLOYD HAULING, INC..
2081 WALNUT STREET JACKSONVILLE, FL
CONSULT: TIM RUDOLPH

PAGE : 8
DATE : 04/25/16
SAMPLE ID : D604469
NVLAP Lab Code: 102053-0

LAB NO. : 22
FRI/HOM : NO/YES LAYERS: 01
DESCRIPTION : PIPE WRAP - BLACK (SOUTH BUILDING)
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 10% CELLULOSE
NON FIBERS : 20% MINERALS
10% RESINS

SAMPLE NO.: 8-1
DATE OF ANALYSIS: 04/25/16

60% BITUMEN

LAB NO. : 23
FRI/HOM : NO/YES LAYERS: 01
DESCRIPTION : PIPE WRAP - BLACK (SOUTH BUILDING)
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 10% CELLULOSE
NON FIBERS : 20% MINERALS
10% RESINS

SAMPLE NO.: 8-2
DATE OF ANALYSIS: 04/25/16

60% BITUMEN

LAB NO. : 24
FRI/HOM : NO/YES LAYERS: 01
DESCRIPTION : PIPE WRAP - BLACK (SOUTH BUILDING)
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 10% CELLULOSE
NON FIBERS : 20% MINERALS
10% RESINS

SAMPLE NO.: 8-3
DATE OF ANALYSIS: 04/25/16

60% BITUMEN

Dove Environmental Corporation is solely responsible for analysis performed on sample content supplied by client and is NVLAP accredited for Method 40 CFR Pt. 736, App. E to Subpart E EPA/600/R-93/116. Measurement Uncertainty information is available by contacting the Laboratory. Laboratory Reports will be kept for a period of three (3) years electronically. Percentages are visually estimated. Point count performed at clients request only. Results relates only to item analyzed. This report should not be reproduced by client or anyone without written permision from Dove Environmental Corporation. All samples will be stored for a period of 1 month. The use of the term NVLAP does not constitute endorsement by NVLAP or any agency of the United States Government. Floor-Tile is non-homogeneous and results only reflect sample content.

Analyst 1

R. Pepe Ramnath, PhD
LABORATORY MANAGER

DOVE ENVIRONMENTAL CORP.
8910 MIRAMAR PARKWAY, SUITE 200 MIRAMAR FL 33025
Tel. (954) 374-9274 Fax: (954) 639-7426

ASBESTOS TEST REPORT

CLIENT : ENVIRONEERING, INC.
ADDRESS: 109 AZALEA POINT DRIVE., SOUTH
PONTE VEDRA BCH FL 32082
PROJECT: JON 5572// MICHAEL LLOYD HAULING, INC..
2081 WALNUT STREET JACKSONVILLE, FL
CONSULT: TIM RUDOLPH

PAGE : 9
DATE : 04/25/16
SAMPLE ID : D604469
NVLAP Lab Code: 102053-0

LAB NO. : 25
FRI/HOM : NO/YES LAYERS: 01 SAMPLE NO.: 9-1
DESCRIPTION : BUILT UP ROOF SYSTEM - BLACK (SOUTH BUILDING) DATE OF ANALYSIS: 04/25/16
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 10% CELLULOSE
NON FIBERS : 20% MINERALS 70% BITUMEN

LAB NO. : 26
FRI/HOM : NO/YES LAYERS: 01 SAMPLE NO.: 9-2
DESCRIPTION : BUILT UP ROOF SYSTEM - BLACK (SOUTH BUILDING) DATE OF ANALYSIS: 04/25/16
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 10% CELLULOSE
NON FIBERS : 20% MINERALS 70% BITUMEN

LAB NO. : 27
FRI/HOM : NO/YES LAYERS: 01 SAMPLE NO.: 9-3
DESCRIPTION : BUILT UP ROOF SYSTEM - BLACK (SOUTH BUILDING) DATE OF ANALYSIS: 04/25/16
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 10% CELLULOSE
NON FIBERS : 20% MINERALS 70% BITUMEN

Dove Environmental Corporation is solely responsible for analysis performed on sample content supplied by client and is NVLAP accredited for Method 40 CFR Pt. 736, App. E to Subpart E EPA/600/R-93/116. Measurement Uncertainty information is available by contacting the Laboratory. Laboratory Reports will be kept for a period of three (3) years electronically. Percentages are visually estimated. Point count performed at clients request only. Results relates only to item analyzed. This report should not be reproduced by client or anyone without written permision from Dove Environmental Corporation. All samples will be stored for a period of 1 month. The use of the term NVLAP does not constitute endorsement by NVLAP or any agency of the United States Government. Floor-Tile is non-homogeneous and results only reflect sample content.

Analyst 1

R. Pepe Ramnath, PhD
LABORATORY MANAGER

DOVE ENVIRONMENTAL CORP.
8910 MIRAMAR PARKWAY, SUITE 200 MIRAMAR FL 33025
Tel. (954) 374-9274 Fax: (954) 639-7426

ASBESTOS TEST REPORT

CLIENT : ENVIRONEERING, INC.
ADDRESS: 109 AZALEA POINT DRIVE., SOUTH
PONTE VEDRA BCH FL 32082
PROJECT: JON 5572// MICHAEL LLOYD HAULING, INC..
2081 WALNUT STREET JACKSONVILLE, FL
CONSULT: TIM RUDOLPH

PAGE : 10
DATE : 04/25/16
SAMPLE ID : D604469
NVLAP Lab Code: 102053-0

LAB NO. : 28
FRI/HOM : NO/YES LAYERS: 01 SAMPLE NO.: 10-1
DESCRIPTION : ROOF FLASHING - BLACK (SOUTH BUILDING) DATE OF ANALYSIS: 04/25/16
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 10% CELLULOSE
NON FIBERS : 20% MINERALS 70% BITUMEN

LAB NO. : 29
FRI/HOM : NO/YES LAYERS: 01 SAMPLE NO.: 10-2
DESCRIPTION : ROOF FLASHING - BLACK (SOUTH BUILDING) DATE OF ANALYSIS: 04/25/16
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 10% CELLULOSE
NON FIBERS : 20% MINERALS 70% BITUMEN

LAB NO. : 30
FRI/HOM : NO/YES LAYERS: 01 SAMPLE NO.: 10-3
DESCRIPTION : ROOF FLASHING - BLACK (SOUTH BUILDING) DATE OF ANALYSIS: 04/25/16
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 10% CELLULOSE
NON FIBERS : 20% MINERALS 70% BITUMEN

Dove Environmental Corporation is solely responsible for analysis performed on sample content supplied by client and is NVLAP accredited for Method 40 CFR Pt. 736, App. E to Subpart E EPA/600/R-93/116. Measurement Uncertainty information is available by contacting the Laboratory. Laboratory Reports will be kept for a period of three (3) years electronically. Percentages are visually estimated. Point count performed at clients request only. Results relates only to item analyzed. This report should not be reproduced by client or anyone without written permision from Dove Environmental Corporation. All samples will be stored for a period of 1 month. The use of the term NVLAP does not constitute endorsement by NVLAP or any agency of the United States Government. Floor-Tile is non-homogeneous and results only reflect sample content.

Analyst 1

R. Pepe Ramnath, PhD
LABORATORY MANAGER

DOVE ENVIRONMENTAL CORP.
8910 MIRAMAR PARKWAY, SUITE 200 MIRAMAR FL 33025
Tel. (954) 374-9274 Fax: (954) 639-7426

ASBESTOS TEST REPORT

CLIENT : ENVIRONEERING. INC.
ADDRESS: 109 AZALEA POINT DRIVE.. SOUTH
PONTE VEDRA BCH FL 32082
PROJECT: JON 5572// MICHAEL LLOYD HAULING, INC..
2081 WALNUT STREET JACKSONVILLE, FL
CONSULT: TIM RUDOLPH

PAGE : 11
DATE : 04/25/16
SAMPLE ID : D604469
NVLAP Lab Code: 102053-0

LAB NO. : 31
FRI/HOM : NO/NO LAYERS: 02
SAMPLE NO.: 11-1
DATE OF ANALYSIS: 04/25/16
DESCRIPTION : SINGLE PLY SYSTEM -MOP DOWN -BLACK W/SILVER PAINT (NORTH BUILDING)
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 10% CELLULOSE
NON FIBERS : 20% MINERALS
50% BITUMEN
10% FIBER-GLASS
10% PAINT

LAB NO. : 32
FRI/HOM : NO/NO LAYERS: 02
SAMPLE NO.: 11-2
DATE OF ANALYSIS: 04/25/16
DESCRIPTION : SINGLE PLY SYSTEM -MOP DOWN -BLACK W/SILVER PAINT (NORTH BUILDING)
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 10% CELLULOSE
NON FIBERS : 20% MINERALS
50% BITUMEN
10% FIBER-GLASS
10% PAINT

LAB NO. : 33
FRI/HOM : NO/NO LAYERS: 02
SAMPLE NO.: 11-3
DATE OF ANALYSIS: 04/25/16
DESCRIPTION : SINGLE PLY SYSTEM -MOP DOWN -BLACK W/SILVER PAINT (NORTH BUILDING)
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 10% CELLULOSE
NON FIBERS : 20% MINERALS
50% BITUMEN
10% FIBER-GLASS
10% PAINT

Dove Environmental Corporation is solely responsible for analysis performed on sample content supplied by client and is NVLAP accredited for Method 40 CFR Pt. 736, App. E to Subpart E EPA/600/R-93/116. Measurement Uncertainty information is available by contacting the Laboratory. Laboratory Reports will be kept for a period of three (3) years electronically. Percentages are visually estimated. Point count performed at clients request only. Results relates only to item analyzed. This report should not be reproduced by client or anyone without written permision from Dove Environmental Corporation. All samples will be stored for a period of 1 month. The use of the term NVLAP does not constitute endorsement by NVLAP or any agency of the United States Government. Floor-Tile is non-homogeneous and results only reflect sample content.

Analyst 1

R. Pepe Ramnath, PhD
LABORATORY MANAGER

DOVE ENVIRONMENTAL CORP.
8910 MIRAMAR PARKWAY, SUITE 200 MIRAMAR FL 33025
Tel. (954) 374-9274 Fax: (954) 639-7426

ASBESTOS TEST REPORT

CLIENT : ENVIRONEERING, INC.
ADDRESS: 109 AZALEA POINT DRIVE., SOUTH
PONTE VEDRA BCH FL 32082
PROJECT: JON 5572// MICHAEL LLOYD HAULING, INC..
2081 WALNUT STREET JACKSONVILLE, FL
CONSULT: TIM RUDOLPH

PAGE : 12
DATE : 04/25/16
SAMPLE ID : D604469
NVLAP Lab Code: 102053-0

LAB NO. : 34
FRI/HOM : NO/YES LAYERS: 01
SAMPLE NO.: 12-1
DATE OF ANALYSIS: 04/25/16
DESCRIPTION : EXTERIOR STUCCO - GRAY (SOUTH BUILDING)
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 5% CELLULOSE
NON FIBERS : 55% MINERALS
30% POLYMERS
10% PAINT

LAB NO. : 35
FRI/HOM : NO/YES LAYERS: 01
SAMPLE NO.: 12-2
DATE OF ANALYSIS: 04/25/16
DESCRIPTION : EXTERIOR STUCCO - GRAY (SOUTH BUILDING)
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 5% CELLULOSE
NON FIBERS : 55% MINERALS
30% POLYMERS
10% PAINT

LAB NO. : 36
FRI/HOM : NO/YES LAYERS: 01
SAMPLE NO.: 12-3
DATE OF ANALYSIS: 04/25/16
DESCRIPTION : EXTERIOR STUCCO - GRAY (SOUTH BUILDING)
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 5% CELLULOSE
NON FIBERS : 55% MINERALS
30% POLYMERS
10% PAINT

Dove Environmental Corporation is solely responsible for analysis performed on sample content supplied by client and is NVLAP accredited for Method 40 CFR Pt. 736, App. E to Subpart E EPA/600/R-93/116. Measurement Uncertainty information is available by contacting the Laboratory. Laboratory Reports will be kept for a period of three (3) years electronically. Percentages are visually estimated. Point count performed at clients request only. Results relates only to item analyzed. This report should not be reproduced by client or anyone without written permision from Dove Environmental Corporation. All samples will be stored for a period of 1 month. The use of the term NVLAP does not constitute endorsement by NVLAP or any agency of the United States Government. Floor-Tile is non-homogeneous and results only reflect sample content.

Analyst 1

R. Pepe Ramnath, PhD
LABORATORY MANAGER

DOVE ENVIRONMENTAL CORP.
8910 MIRAMAR PARKWAY, SUITE 200 MIRAMAR FL 33025
Tel. (954) 374-9274 Fax: (954) 639-7426

ASBESTOS TEST REPORT

CLIENT : ENVIRONEERING, INC.
ADDRESS: 109 AZALEA POINT DRIVE., SOUTH
PONTE VEDRA BCH FL 32082
PROJECT: JON 5572// MICHAEL LLOYD HAULING, INC..
2081 WALNUT STREET JACKSONVILLE, FL
CONSULT: TIM RUDOLPH

PAGE : 13
DATE : 04/25/16
SAMPLE ID : D604469
NVLAP Lab Code: 102053-0

LAB NO. : 37
FRI/HOM : NO/NO LAYERS: 02
DESCRIPTION : ROOF MASTIC -WALL - BLACK
<1% CHRY THROUGHOUT BLK MASTIC
ASBESTOS TYPE: <1% CHRYSOTILE
OTHER FIBERS : 9.5 % CELLULOSE
NON FIBERS : 20% MINERALS
60% RESINS

SAMPLE NO.: 13-1
DATE OF ANALYSIS: 04/25/16

10% PAINT

LAB NO. : 38
FRI/HOM : NO/NO LAYERS: 02
DESCRIPTION : ROOF MASTIC -WALL - BLACK
<1% CHRY THROUGHOUT BLK MASTIC
ASBESTOS TYPE: <1% CHRYSOTILE
OTHER FIBERS : 9.5 % CELLULOSE
NON FIBERS : 20% MINERALS
60% RESINS

SAMPLE NO.: 13-2
DATE OF ANALYSIS: 04/25/16

10% PAINT

LAB NO. : 39
FRI/HOM : NO/NO LAYERS: 02
DESCRIPTION : ROOF MASTIC -WALL - BLACK
<1% CHRY THROUGHOUT BLK MASTIC
ASBESTOS TYPE: <1% CHRYSOTILE
OTHER FIBERS : 9.5 % CELLULOSE
NON FIBERS : 20% MINERALS
60% RESINS

SAMPLE NO.: 13-3
DATE OF ANALYSIS: 04/25/16

10% PAINT

Dove Environmental Corporation is solely responsible for analysis performed on sample content supplied by client and is NVLAP accredited for Method 40 CFR Pt. 736, App. E to Subpart E EPA/600/R-93/116. Measurement Uncertainty information is available by contacting the Laboratory. Laboratory Reports will be kept for a period of three [3] years electronically. Percentages are visually estimated. Point count performed at clients request only. Results relates only to item analyzed. This report should not be reproduced by client or anyone without written permision from Dove Environmental Corporation. All samples will be stored for a period of 1 month. The use of the term NVLAP does not constitute endorsement by NVLAP or any agency of the United States Government. Floor-Tile is non-homogeneous and results only reflect sample content.

Analyst 1

R. Pepe Ramnath, PhD
LABORATORY MANAGER

DOVE ENVIRONMENTAL CORP.
8910 MIRAMAR PARKWAY, SUITE 200 MIRAMAR FL 33025
Tel. (954) 374-9274 Fax: (954) 639-7426

ASBESTOS TEST REPORT

CLIENT : ENVIRONEERING, INC.
ADDRESS: 109 AZALEA POINT DRIVE., SOUTH
PONTE VEDRA BCH FL 32082
PROJECT: JON 5572// MICHAEL LLOYD HAULING, INC..
2081 WALNUT STREET JACKSONVILLE, FL
CONSULT: TIM RUDOLPH

PAGE : 14
DATE : 04/25/16
SAMPLE ID : D604469
NVLAP Lab Code: 102053-0

LAB NO. : 40
FRI/HOM : NO/YES LAYERS: 01
DESCRIPTION : ELECTRICAL WIRING - BLACK
ASBESTOS TYPE: NONE-DETECTED
OTHER FIBERS : 20% CELLULOSE
NON FIBERS : 20% MINERALS 60% POLYMERS

SAMPLE NO.: 14-1
DATE OF ANALYSIS: 04/25/16

Dove Environmental Corporation is solely responsible for analysis performed on sample content supplied by client and is NVLAP accredited for Method 40 CFR Pt. 736, App. E to Subpart E EPA/600/R-93/116. Measurement Uncertainty information is available by contacting the Laboratory. Laboratory Reports will be kept for a period of three (3) years electronically. Percentages are visually estimated. Point count performed at clients request only. Results relates only to item analyzed. This report should not be reproduced by client or anyone without written permision from Dove Environmental Corporation. All samples will be stored for a period of 1 month. The use of the term NVLAP does not constitute endorsement by NVLAP or any agency of the United States Government. Floor-Tile is non-homogeneous and results only reflect sample content.

Analyst 1

R. Pepe Ramnath, PhD
LABORATORY MANAGER

TITLE:	DEMO & SITE CLEARANCE OF 50 PROPERTIES	P & G LAND CLEARING, INC.				ONAS CORPORATION			
BID NO.	CF-0336-16 (MUNICIPAL CODE)								
36	2081 Walnut Street , (retail store) described as; 5-25 12-2S-26E .57 HALSEMA INV CO R/P LOTS 4,5,6,7,8 & CLOSED ALLEY LYING WEST OF LOT 4 ORD FF-463, PT CL ST (Demolition and Site Clearance) R.E. #055259-0000 (CONTRACTOR MUST SUBMIT A BID FOR THE COST OF AN ASBESTOS SURVEY AND A WET DEMOLITION) (URBAN CORE)	$ 1,000.00	$ 38,975.00	$ 39,975.00	$ 3,000.00	$ 5,000.00	$ 33,000.00	$ 38,000.00	$ 49,000.00
37	1602 Wambolt Street , (accessory only) described as; 12-79 18-2S-27E FAIRLAWN LOT 30 (Demolition and Site Clearance) R.E. #122034-0000 (CONTRACTOR MUST SUBMIT A BID FOR THE COST OF AN ASBESTOS SURVEY AND A WET DEMOLITION) (URBAN CORE)	$ 275.00	$ 1,750.00	$ 2,025.00	$ 1,000.00	$ 3,000.00	$ 30,000.00	$ 33,000.00	$ 42,000.00
38	1405 Windle Street, (rear fire damage structure only) described as; 5-37 40-2S-26E .137 NOONEYS S/D LOT 7, PT LOT 6 RECD O/R 15988-1569 BLK 5 (Demolition and Site Clearance) R.E. #076655-0000 (CONTRACTOR MUST SUBMIT A BID FOR THE COST OF AN ASBESTOS SURVEY AND A WET DEMOLITION) (NORTHWEST)	$ 275.00	$ 4,400.00	$ 4,675.00	$ 1,000.00	$ 3,000.00	$ 35,000.00	$ 38,000.00	$ 43,000.00
39	2162 Yulee Street, (single family structure) described as; 9-29 16-2S-26E GRANT ADDN TO JAX LOT 3 BLK 3 (Demolition and Site Clearance) R.E. #076820-0000 (CONTRACTOR MUST SUBMIT A BID FOR THE COST OF AN ASBESTOS SURVEY AND A WET DEMOLITION) (NORTHWEST)	NO BID	NO BID	NO BID	NO BID	$ 3,000.00	$ 15,000.00	$ 18,000.00	$ 28,000.00
40	3123 North 3rd Street Circle, (accessory structure only) described as; 22-7 08-2S-26E WESTWOOD PARK LOT 10 BLK 2 (Demolition and Site Clearance) R.E. #050160-0000 (CONTRACTOR MUST SUBMIT A BID FOR THE COST OF AN ASBESTOS SURVEY AND A WET DEMOLITION) (NORTHWEST)	$ 275.00	$ 5,275.00	$ 5,550.00	$ 1,000.00	$ 3,000.00	$ 25,000.00	$ 28,000.00	$ 38,000.00
41	34 West 17th Street, (single family structure) described as; 5-23 01-2S-26E YOUNGS R/P LOT 20(Demolition and Site Clearance) R.E. #044487-0000 (CONTRACTOR MUST SUBMIT A BID FOR THE COST OF AN ASBESTOS SURVEY AND A WET DEMOLITION) (URBAN CORE)	$ 275.00	$ 4,350.00	$ 4,625.00	$ 1,000.00	$ 3,000.00	$ 15,000.00	$ 18,000.00	$ 28,000.00

TITLE:	DEMO & SITE CLEARANCE OF 50 PROPERTIES	MICHAEL LLOYD HAULING				WATSON DEMO, INC.			
BID NO.	CF-0336-16 (MUNICIPAL CODE)								
36	2081 Walnut Street , (retail store) described as; 5-25 12-2S-26E .57 HALSEMA INV CO R/P LOTS 4,5,6,7,8 & CLOSED ALLEY LYING WEST OF LOT 4 ORD FF-463, PT CL ST (Demolition and Site Clearance) R.E. #055259-0000 (CONTRACTOR MUST SUBMIT A BID FOR THE COST OF AN ASBESTOS SURVEY AND A WET DEMOLITION) (URBAN CORE)	$ 800.00	$ 35,000.00	$ 35,800.00	$ 45,800.00			$ -	
37	1602 Wambolt Street , (accessory only) described as; 12-79 18-2S-27E FAIRLAWN LOT 30 (Demolition and Site Clearance) R.E. #122034-0000 (CONTRACTOR MUST SUBMIT A BID FOR THE COST OF AN ASBESTOS SURVEY AND A WET DEMOLITION) (URBAN CORE)	$ 175.00	$ 1,200.00	$ 1,375.00	$ 1,875.00	$ 200.00	$ 1,470.00	$ 1,670.00	$ 500.00
38	1405 Windle Street, (rear fire damage structure only) described as; 5-37 40-2S-26E .137 NOONEYS S/D LOT 7, PT LOT 6 RECD O/R 15988-1569 BLK 5 (Demolition and Site Clearance) R.E. #076655-0000 (CONTRACTOR MUST SUBMIT A BID FOR THE COST OF AN ASBESTOS SURVEY AND A WET DEMOLITION) (NORTHWEST)	$ 275.00	$ 3,800.00	$ 4,075.00	$ 5,275.00			$ -	
39	2162 Yulee Street, (single family structure) described as; 9-29 16-2S-26E GRANT ADDN TO JAX LOT 3 BLK 3 (Demolition and Site Clearance) R.E. #076820-0000 (CONTRACTOR MUST SUBMIT A BID FOR THE COST OF AN ASBESTOS SURVEY AND A WET DEMOLITION) (NORTHWEST)	$ 275.00	$ 3,850.00	$ 4,125.00	$ 5,325.00			$ -	
40	3123 North 3rd Street Circle, (accessory structure only) described as; 22-7 08-2S-26E WESTWOOD PARK LOT 10 BLK 2 (Demolition and Site Clearance) R.E. #050160-0000 (CONTRACTOR MUST SUBMIT A BID FOR THE COST OF AN ASBESTOS SURVEY AND A WET DEMOLITION) (NORTHWEST)	$ 175.00	$ 1,850.00	$ 2,025.00	$ 2,525.00			$ -	
41	34 West 17th Street, (single family structure) described as; 5-23 01-2S-26E YOUNGS R/P LOT 20(Demolition and Site Clearance) R.E. #044487-0000 (CONTRACTOR MUST SUBMIT A BID FOR THE COST OF AN ASBESTOS SURVEY AND A WET DEMOLITION) (URBAN CORE)	$ 275.00	$ 4,800.00	$ 5,075.00	$ 6,575.00			$ -	

SUBJECT: **DEMO & SITE CLEARANCE OF (50) PROPERTIES**

BID# CF-0336-16 OPEN DATE: **2015-11-18**

GENERAL GOVERNMENT AWARDS COMMITTEE

KIND AND BASIS OF CONTRACT:
CONSTRUCTION FIXED

AGENCY: **MUNICIPAL CODE**

BASIS OF AWARD: **BY ITEM TO THE LOWEST RESPONSIVE, RESPONSIBLE BIDDER**

NUMBER OF BIDS INVITED 7 NUMBER RECEIVED 4 OTHER 0

SUMMARY OF BIDS AND RECOMMENDED ACTIONS:

Recommend approval of award by item to the lowest responsive, responsible bidder(s) as follows: Michael Lloyd Hauling, bid items # 2, 3, 4, 6, 8, 9, 11, 12, 14, 21, 22, 24, 25, 26, 27, 28, 29, 32, 33, 36, 37, 38, 39, 40, 43, 44, 48 and 50 in the amount of $154,450.00; P & G Land Clearing, Inc., bid items # 7, 15, 16, 17, 19, 20, 23, 30, 31, 34, 35, 41, 42, 45, 47 and 49 in the amount of $75,260.00. Total award not-to-exceed $229,710.00.
Items 1, 5, 10, 13, 18 and 46 will not be awarded at this time.

This award to funded by account: ERCC011VPR-03410 to be executed by Purchase Order(s).

Attachments: Recommendation Memo, Bid Tabulation Sheet, Terms & Conditions

BUYER: Marilyn Laidler RESPECTFULLY SUBMITTED:
MARILYN LAIDLER
GREGORY PEASE, CHIEF
PROCUREMENT DIVISION

CONCURRENCE BY: **Bryan Mosier, Interim Chief, Municipal Code Compliance Division**

(ALL AWARD ACTIONS SUBJECT TO LAWFULLY APPROPRIATED FUNDS)
ACTION OF GGAC COMMITTEE ON RECOMMENDATIONS ABOVE
MEMBERS APPROVING 3 MEMBERS DISAPPROVING _____ DATE: 12-3-15

OTHER: _____

ACTION OF AWARDING AUTHORITY DATE: 12/03/15

APPROVED _____ DISAPPROVED _____

OTHER _____

SIGNATURE OF AUTHENTICATION _____

Sam E. Mousa
Chief Administrative Officer
For: Mayor Lenny Curry
Under Authority of:
Executive Order No. 2015-05

FORM GB-108, Revised 12/2007

TERMS AND CONDITIONS
BID# CF-0336-16

SCOPE OF WORK
The **MUNICIPAL CODE** division of the City of Jacksonville, Florida is currently accepting bids to obtain source(s) of supply for the services as outlined in the bid documents provided. The purpose of this bid invitation is to obtain information about your firm and its ability to provide these services and to obtain pricing commitments for **DEMO & SITE CLEARANCE OF 50 PROPERTIES** as listed in the bid documents All bidders of this project shall be on the approved pre-qualified bidders list with the City of Jacksonville's Procurement Division (info at www.coj.net) under **DEMOLITION LESS THAN 3 STORIES** category at the time of bid opening..

AWARD
Award will be BY ITEM to the lowest, responsive, responsible bidder based on the sum of an asbestos survey and an asbestos free demolition. Bidders must list a price for both the asbestos survey, and the total cost to perform a wet demolition, in order to be considered responsive. Any awarded item that requires a "wet demolition" per the asbestos survey is subject to being rescinded and re-awarded to the lowest responsive, responsible bidder for a "wet demolition". The City shall reserve the right to not award any "wet demolitions" and rebid at a later date if determined to be in the best interest of the City. All awards are subject to the availability of funds.

TERM OF AGREEMENT
Submitted bid pricing shall remain firm for one hundred twenty (120) days from the bid open date. In the event a Notice to Proceed is not issued prior to this, the successful bidder shall be required to confirm in writing, if the submitted pricing will be honored; The bid item may be subject to be awarded to the next lowest responsive, responsible bidder if determined to be in the best interest of the City.

Contractor shall complete all work for each project within **thirty (30)** days from the date of receipt of the "Notice to Proceed".

PRE-BID CONFERENCE
N/A

COMPLIANCE WITH SPECIFICATIONS
The bidder, by affixing their signature to the bid form submitted, agrees to provide item(s)/service(s) in accordance with the bid documents provided. Bid only a single offering for each bid item. Multiple offerings, alternates (unless stated) and or stipulations may be cause for bid rejection. Bid only on forms provided herein unless otherwise stated. Bid submissions shall be in ink or typewritten. All corrections must be initialed.

STATE CONTRACTS
The City reserves the right to utilize contracts established by the State of Florida and/or other governmental agencies for item(s)/service(s) covered under this bid. The City reserves the right to cancel this contract in whole or in part for such item(s)/service(s).

QUANTITIES

QWS3270X 2/3/2017 8:22 AM
FAML6350 V5.1 ** NW COJ FAMIS PRODUCTION ** 02/03/2017
LINK TO: ACCOUNT SUMMARY INQUIRY 8:21 AM

FISCAL MO/YEAR : 05 2017 CURRENCY CODE :
INDEX CODE : ERCD1N1FR FORECLOSED PROPERTY REGISTRY-HOUSING SER
SUBOBJECT : 03410 CONTRACTUAL SERVICES
PROJECT :
PROJECT DETAIL :
GRANT :
GRANT DETAIL :
USER CODE :

S	FEB 2017	ANNUAL BALANCE	ALL YEARS BALANCE
ESTIMATED REVENUES	.00	.00	.00
REVENUES	.00	.00	.00
UNREALIZED REVENUES	.00	.00	.00
BUDGET	.00	1,115,930.00	1,115,930.00
EXPENDITURES	.00	5,450.00	5,450.00
ENCUMBRANCES	.00	261,907.00	261,907.00
PRE-ENCUMBRANCES	.00	.00	.00
REMAINING BALANCE	.00	848,573.00	848,573.00

F1-HELP F2-SELECT F4-PRIOR F5-NEXT
F9-LINK F10-PRIOR-MO F11-NEXT-MO
G005 - PRIOR RECORD DISPLAYED