SUBJECT: DEMO & SITE CLEARANCE OF 40 PROPERTIES

BID #: CF-0088-17 **OPEN DATE:** 2017-03-01

GENERAL GOVERNMENT AWARDS COMMITTEE

KIND AND BASIS OF CONTRACT: CONSTRUCTION FIXED

AGENCY: MUNICIPAL CODE

BASIS OF AWARD: BY ITEM TO THE LOWEST RESPONSIVE, RESPONSIBLE BIDDER

NUMBER OF BIDS INVITED: (7) **NUMBER RECEIVED:** (3) **OTHER** (0)

SUMMARY OF BIDS AND RECOMMENDED ACTIONS:

Item #11 was awarded to ERS, Corp on 03/16/17 in the amount of $5,133.00 which included $275.00 cost of asbestos survey as required by bid specifications. The performed asbestos survey requires a wet demolition be performed prior to demolition

Recommend approval to increase award for Item #11 to ERS, Corp, as the lowest responsive, responsible bidder in the amount of $1,000.00 for the wet demolition. Total revised award amount for Item #11 not-to-exceed $6,133.00.

The award to be funded by account: ERCC1L2CP-03410 to be executed by Purchase Order/Change Order.

Attachments: Recommendation Memo, Change Order, Asbestos Report, Previous Award

ANALYST: Marilyn Laidler
MARILYN LAIDLER

RESPECTFULLY SUBMITTED Gregory Pease
GREGORY PEASE, CHIEF
PROCUREMENT DIVISION

CONCURRENCE BY: Bryan Mosier, Chief, Municipal Code Compliance

---

(ALL AWARD ACTIONS SUBJECT TO LAWFULLY APPROPRIATED FUNDS)
ACTION OF GGAC COMMITTEE ON RECOMMENDATIONS ABOVE

MEMBERS APPROVING _____ MEMBERS DISAPPROVING _____ DATE: _____

_____ _____ OTHER: _____

_____ _____

_____ _____

ACTION OF AWARDING AUTHORITY DATE _____

APPROVED _____ DISAPPROVED _____

OTHER _____

SIGNATURE OF AUTHENTICATION _____

City of Jacksonville, Florida

Lenny Curry, Mayor

Municipal Code Compliance Division
Ed Ball Building
214 N. Hogan Street, 7th Floor
Jacksonville, Florida 32202

ONE CITY. ONE JACKSONVILLE.

October 23, 2017

M E M O R A N D U M

TO: Gregory Pease, Division Chief
Procurement Division

FROM: Bryan Mosier, Division Chief, for
Municipal Code Compliance Division

RE: **Change order request for item #11 on CF-0088-17**

The survey of the condemned structure at 646 Escambia St. revealed asbestos in the 12" x 12" gray floor tile with black mastic and 12" x 12" tan and black floor tile with black mastic, which will have to be removed using the wet demo method.

I recommend approval of the change order from ERS in the amount of $1,000.00 (reference purchase order # 7A09239)

Contractor	Item Number	Amount
ERS Corp.	11	$1,000.00

Funding Source: ERCC1L2CP /03410

BM/ds

ERS Corp.

PROPOSAL

Prepared for:
COJ- Municipal Code Compliance Division
Neighborhoods Department
214 N Hogan St., 7th Floor
Jacksonville, FL 32202

Proposal No: 17545_CO1
Date 8/17/2017
Phone: 904-255-7015
Fax: 904-255-8920
E-Mail: dsteele@coj.net

Attention: Mr. Steele

RE: 646 Escambia St., RE: 031928-0010 (Case No. 2016-82962)
Current Purchase Order No. PO7A09239

Request for Change Order #1:

Original Contract Amount.....$5,133.00

Add Wet Demo activities because of Asbestos Contained Materials..... $1,000.00

We appreciate the opportunity to submit this proposal. If you have any questions or require additional information, please contact John Anderson.

Submitted by:
John Anderson
President – ERS Corp.

PRE-DEMOLITION ASBESTOS SURVEY REPORT

646 Escambia Street
Jacksonville, Florida

GLE Project No.: 17000-18020

Prepared for:

ERS Corp
760 Talleyrand Avenue
Jacksonville, Florida 32202

August 2017

Prepared by:

8659 Baypine Road, Suite 306
Jacksonville, Florida 32256
904-296-1880 • Fax 904-296-1860

GLE

ARCHITECTS | ENGINEERS | ENVIRONMENTAL CONSULTANTS

August 15, 2017

Mr. John Anderson
President
ERS Corp
760 Talleyrand Avenue
Jacksonville, Florida 32202

RE: Pre-Demolition Asbestos Survey Report
646 Escambia Street
Jacksonville, Florida

GLE Project No.: 17000-18020

Dear Mr. Anderson:

GLE Associates, Inc. (GLE) performed a demolition survey for asbestos-containing materials (ACM) on August 2, 2017 at 646 Escambia Street, located in Jacksonville, Florida. The survey was performed by Mr. Ryan Hendry and Ms. Stephanie Whitney with GLE. This report outlines the sampling and testing procedures, and presents the results along with our conclusions and recommendations.

GLE appreciates the opportunity to serve as your consultant on this project. If you should have any questions, or if we can be of further service, please do not hesitate to call.

Sincerely,
GLE Associates, Inc.

Ryan Hendry
Project Manager

Robert B. Greene, PE, PG, CIH, LEED AP
President
Florida LAC# EA 0000009

RH/RBG/lr

M:\Work\Asb\17000\18020-646 Escambia Street\Report\SurveyReport-646 Escambia St.doc

TABLE OF CONTENTS

1.0 INTRODUCTION **1**

1.1 Introduction 1
1.2 Facility Description 1

2.0 RESULTS **1**

2.1 Asbestos Survey Procedures 1
2.2 Identified Suspect Asbestos-Containing Materials 2
Table 2.2-1 — Summary of Homogeneous Sampling Areas

3.0 CONCLUSIONS AND RECOMMENDATIONS **4**

3.1 General 4
3.2 Specific 5

4.0 LIMITATIONS AND CONDITIONS **5**

APPENDICES

Appendix A – Analytical Results and Chain of Custody
Appendix B – Personnel and Laboratory Certifications

1.0 INTRODUCTION

1.1 INTRODUCTION

The purpose of this demolition survey was to identify accessible asbestos-containing materials (ACMs) and their general locations within a residential site, located at 646 Escambia Street in Jacksonville, Florida. The survey was conducted pursuant to National Emission Standards for Hazardous Air Pollutants (NESHAP, 40 CFR 61) requirements, associated with the scheduled demolition plans. The survey was performed on August 2, 2017, by Mr. Ryan Hendry and Ms. Stephanie Whitney, Environmental Protection Agency/Asbestos Hazard Emergency Response Act (EPA/AHERA) accredited inspectors. The scope of this survey did not include demolition of any building components, evaluation of architectural plans, or the quantification of materials for abatement purposes, or removal cost estimating.

1.2 FACILITY DESCRIPTION

A summary of the facility investigated is outlined in the table below.

Facility Type:	Residential
Construction Date:	Unknown
Number of Floors:	One
Exterior	
Floor Support:	Raised Wood Floor
Wall Support:	Wood Frame
Exterior Finish:	Paint
Roof System Type:	Asphalt Shingle (3-Tab)
Interior	
Wall Substrate:	Plaster
Wall Finishes:	Paint, Wallpaper
Floor Finishes:	Vinyl Floor Tile, Sheet Vinyl Flooring
Ceiling System:	Plaster
Ceiling Finishes:	Paint

2.0 RESULTS

2.1 ASBESTOS SURVEY PROCEDURES

The survey was performed by visually observing accessible areas of the building. EPA/AHERA accredited inspectors performed the visual observations (refer to Appendix B for personnel qualifications).

After the overall visual survey was completed, representative sampling areas were determined. The surveyors delineated homogeneous areas of suspect materials and samples of each material were obtained, in general accordance with regulations as established by the Occupational Safety

and Health Administration (OSHA) and NESHAP. The field surveyors determined sample locations based on previous experience. Both friable and non-friable materials were sampled. A friable material is one that can be crushed when dry by normal hand pressure. At the request of the Client, GLE collected three representative samples of friable materials and two representative samples of non-friable materials. This survey did not include the demolition of building components to access suspect material.

After completion of the fieldwork, the samples were delivered to GLE's National Voluntary Laboratory Accreditation Program (NVLAP) accredited laboratory for analysis. The samples were analyzed by Polarized Light Microscopy (PLM) coupled with dispersion staining, in general accordance with EPA-600/R-93/116. Utilizing this procedure, the various asbestos minerals (chrysotile, amosite, crocidolite, actinolite, tremolite, and anthophyllite) can be determined. The percentages of asbestos minerals in the samples were visually determined by the microscopist. Please note that the EPA designates all materials containing greater than 1% asbestos as an "asbestos-containing material" (ACM).

Regulated Asbestos-Containing Material (RACM) is defined as (a) Friable asbestos materials, (b) Category I non-friable ACM that has become friable, (c) Category I non-friable ACM that will be or has been subjected to sanding, grinding, cutting, or abrading, or (d) Category II non-friable ACM that has a high probability of becoming or has become crumbled, pulverized, or reduced to powder by the forces expected to act on the material in the course of demolition or renovation operations regulated by this subpart.

Category I and Category II non-friable ACM, as defined by the EPA:

- Category I non-friable ACM means asbestos containing packings, gaskets, resilient floor covering, asphalt roofing products, and pliable sealants and mastics that are in good condition and not friable, containing more than 1 percent asbestos, as determined using the method specified in Appendix E, Subpart E, 40 CFR Part 763, Section 1, PLM.

- Category II non-friable ACM means any material, excluding Category I non-friable ACM, containing more than 1 percent asbestos as determined using the methods specified in Appendix E, Subpart E, 40 CFR Part 763 Section 1, PLM that, when dry, cannot be crumbled, pulverized, or reduced to powder by hand pressure.

2.2 IDENTIFIED SUSPECT ASBESTOS-CONTAINING MATERIALS

A total of 17 samples of suspect building materials were collected from the facility during the survey, representing eight different identified homogeneous areas. The results of the laboratory analyses are included in Appendix A.

A summary of the homogenous sampling areas of suspect ACM determined to be present is outlined in the following table.

TABLE 2.2-1: SUMMARY OF HOMOGENEOUS SAMPLING AREAS 646 ESCAMBIA STREET – JACKSONVILLE, FLORIDA							
HA #	HOMOGENEOUS MATERIAL DESCRIPTION	HOMOGENEOUS MATERIAL LOCATION	FRIABILITY (F /NF)	% ASBESTOS*	# OF SAMPLES COLLECTED	APPROXIMATE QUANTITY	ACM CATEGORY
FT-01	**12" x 12" Gray Floor Tile with Black Mastic and Leveling Compound**	**Front Room, Porch**	**NF**	**Gray Floor Tile – 7% C Black Mastic 5% C Leveling Compound - ND**	**2**	**200 SF**	**CAT I**
FT-02	**12" x 12" Tan Floor Tile, Black Floor Tile with Black Mastic and Leveling Compound**	**Under MSV-01, Kitchen/Entry**	**NF**	**Tan Floor Tile – 7% C Black Floor Tile – 7%C Black Mastic – 5% C Leveling Compound - ND**	**2**	**150 SF**	**CAT I**
MSV-01	Square Sheet Vinyl Flooring With Tan Mastic	Kitchen/Entry	NF	ND	2	NIS	NA
MSV-02	Floral Sheet Vinyl Flooring with Tan Mastic	Bathroom	NF	ND	2	NIS	NA
PL-01	Plaster	Throughout	NF	ND	3	NIS	NA
RS-01	Asphalt Roof Shingles	Roof	NF	ND	2	NIS	NA
M-01	Grout	Bathroom	NF	ND	2	NIS	NA
M-02	Vapor Barrier	Garage	NF	ND	2	NIS	NA

ASBESTOS CONTENT Expressed as percent	* = The facility owner has the option of point-counting by polarized light microscopy (PLM) those RACM whose asbestos content is less than 10% in order to more accurately determine the asbestos content therein.				
	PC = Results based on Point-Count analysis				
FRIABILITY	F = Friable Material	NF = Non-Friable Material			
ACM CATEGORY	RACM = Regulated ACM	CAT I = Category I non-friable ACM	CAT II = Category II non-friable ACM		
ABBREVIATIONS:	NA = Not Applicable	ND = None Detected	NIS = Not in Scope	C = Chrysotile	A = Amosite
	HA = Homogeneous Area	SF = Square Feet	LF = Linear Feet	CF = Cubic Feet	

3.0 CONCLUSIONS AND RECOMMENDATIONS

3.1 GENERAL

Asbestos-containing materials (ACMs) were identified in the scope of this survey. General and specific conclusions and recommendations are provided below.

The EPA, OSHA and the State of Florida have promulgated regulations dealing with asbestos. For commercial building owners, the EPA NESHAP (40 CFR 61) regulations require removal of RACM, prior to conducting activities which might disturb the material. They also deal with notification, handling and disposal of asbestos.

No homogenous area of suspect RACM was determined to contain less than 10% asbestos by PLM analysis. According to the NESHAP, when the asbestos content of a bulk sample of suspect RACM is determined to be less than 10% by PLM visual estimation, you may:

1. Assume the amount to be greater than 1% and treat the material as asbestos-containing; or
2. Conduct confirmatory verification by point-counting. Note, the results obtained by point-counting are considered the definitive analytical result.

The EPA recommends that an Operations and Maintenance (O&M) Program be developed for any facilities with ACM, and this Program should address all ACM (known and/or assumed) present. The O&M Program establishes notification and training requirements along with special procedures for working around the ACM. The O&M Program would remain in effect until all asbestos is removed.

Category I and Category II non-friable materials, as defined by the EPA, may remain within a facility during demolition with no potential cessation of work, provided they remain non-friable and the appropriate engineering controls (i.e., wet methods) are utilized, with the resulting waste disposed of as asbestos-containing waste. However, there is no guarantee that these materials will remain non-friable. If the materials become friable, then they are classified as RACM.

RACM, as defined by the EPA, must be removed prior to renovation or demolition activities that may disturb the materials.

The OSHA regulations deal with employee exposure to airborne asbestos fibers. The regulations restrict employee exposure, and require special monitoring, training and handling procedures when dealing with asbestos. Additionally, OSHA has regulations that may supersede the EPA regulations. In order to protect the worker, OSHA has established a permissible exposure limit (PEL), which limits employee exposure to airborne fiber concentrations. OSHA requires objective evidence that the PEL will not be exceeded, as justification that personal air monitoring and engineering controls will not be required. OSHA has also established rules requiring the containerization and labeling of asbestos waste.

The State regulations require that anyone involved in asbestos consulting activities be a licensed asbestos consultant and that anyone involved in asbestos abatement, with the exception of roofing materials, be a licensed asbestos abatement contractor.

3.2 SPECIFIC

12" x 12" Gray Floor Tile with Black Mastic
12" x 12" Tan Floor Tile, Black Floor Tile with Black Mastic

These materials are defined by the EPA as Category I non-friable materials. These materials may remain within a facility during demolition with no potential stoppage of work provided they remain non-friable. However, there is no guarantee that it will remain non-friable. If a material becomes friable, then it is classified as RACM. RACM, as defined by the EPA, must be removed prior to renovation or demolition activities that may disturb the materials. Also, OSHA has additional requirements that may supersede the EPA rules. These materials do not appear to present a significant issue, as observed, at the time of the survey. We recommend that the identified Category I material be maintained as part of an O&M Program and periodically monitored for any changes in condition prior to demolition. As discussed above, in order to protect the worker, OSHA has established a PEL which limits airborne fiber concentrations. Objective evidence that the PEL will not be exceeded is required by OSHA as justification that personal air monitoring and engineering controls will not be required. OSHA has also established rules requiring the containerization and labeling of asbestos waste.

Should prior abatement be desired, the work must be performed in accordance with Federal, State, and local regulations. In lieu of abatement, demolition utilizing the wet method is acceptable by a demolition contractor properly trained and certified to conduct Class II asbestos work, along with proper disposal and transport of the demolished materials to an approved landfill as asbestos-containing waste.

4.0 LIMITATIONS AND CONDITIONS

As a result of previous renovations, there may be hidden materials, such as floor tile, sheet vinyl flooring, insulation, etc. These materials may be found in various areas hidden under existing flooring materials or in wall cavities. Any materials found during construction activities, either not addressed in this survey report, or similar to the ACM identified in this survey report should be assumed to be ACM until sampling and analysis documents otherwise.

Because of the hidden nature of many building components (i.e. within mechanical chases), it may be impossible to determine if all of the suspect building materials have been located and subsequently tested. Destructive testing in some instances is not a viable option. We cannot, therefore, guarantee that all potential ACM has been located. For the same reasons, estimates of quantities and/or conditions are subject to readily apparent situations, and our findings reflect this condition. We do warrant, however, that the investigations and methodology reflect our best efforts based upon the prevailing standard of care in the environmental industry.

The information contained in this report was prepared based upon specific parameters and regulations in force at the time of this report. The information herein is only for the specific use of the client and GLE. GLE accepts no responsibility for the use, interpretation, or reliance by other parties on the information contained herein, unless prior written authorization has been obtained from GLE.

APPENDIX A
Analytical Results and Chain of Custody

SUMMARY OF BULK SAMPLE ANALYSIS

ERS; 646 Escambia Drive

17000-18020

Sample	Sample Type		Fiber Type
FT-01A	12x12 Gray Floor Tile	7%	**Chrysotile Asbestos**
		93%	Polymer, Quartz, Calcite, Clay, Mica
	Black Mastic	5%	**Chrysotile Asbestos**
		95%	Bitumen
	Leveling Compound	100%	Quartz, Calcite, Clay, Mica
FT-01B	12x12 Gray Floor Tile & Black Mastic		Positive Stop/Sample not analyzed
	Leveling Compound	100%	Quartz, Calcite, Clay, Mica
FT-02A-QC	12x12 Tan Floor Tile	100%	Polymer, Quartz, Calcite, Clay, Mica
	Black Floor Tile	7%	**Chrysotile Asbestos**
		93%	Polymer, Quartz, Calcite, Clay, Mica
	Black Mastic	5%	**Chrysotile Asbestos**
		95%	Bitumen
	Leveling Compound	100%	Quartz, Calcite, Clay, Mica
FT-02B	12x12 Tan Floor Tile	7%	**Chrysotile Asbestos**
		93%	Polymer, Quartz, Calcite, Clay, Mica
	Black Mastic	100%	Positive Stop/Sample not analyzed
MSV-01A	Square Vinyl Sheet Flooring & Tan Mastic	20%	Cellulose/paper
		80%	Polymer, Quartz, Calcite, Clay, Mica
MSV-01B	Square Vinyl Sheet Flooring & Tan Mastic	20%	Cellulose/paper
		80%	Polymer
MSV-02A	Vinyl Sheet Flooring & Tan Mastic	20%	Cellulose/paper
		80%	Polymer

Analyst / Approved Signatory:

Darryl Neldner

* Polarized Light Microscopy coupled with dispersion is the technique used for identification in accordance with EPA 600/M4-82-020, EPA 600/R-93/116, and NIOSH Method 9002.

** The percentage of each component is visually estimated. The result of this analysis relate only to the material tested. The report shall not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. (>1% greater than one percent, <1% less than one percent) QC - Sample reanalyzed for QA/QC.

*** This report shall not be reproduced except in full, without the written approval of the laboratory. GLE Report # 21487

Analysis performed by GLE Associates, Inc. NVLAP Code 102003-0, CO AL-17485, TX 30-0337

Feedback regarding laboratory performance should be addressed to lab@gleassociates.com.

Report Date: 8/3/2017

SUMMARY OF BULK SAMPLE ANALYSIS

ERS; 646 Escambia Drive

17000-18020

Sample	Sample Type	Fiber Type	
MSV-02B	Vinyl Sheet Flooring & Tan Mastic	20% 80%	Cellulose/paper Polymer
PL-01A	Plaster	100%	Quartz, Calcite, Clay, Mica
PL-01B	Plaster	100%	Quartz, Calcite, Clay, Mica
PL-01C	Plaster	100%	Quartz, Calcite, Clay, Mica
RS-01A	Asphalt Roof Shingles	20% 80%	Glass Fibers Bitumen, Quartz, Calcite, Mica
RS-01B-QC	Asphalt Roof Shingles	20% 80%	Glass Fibers Bitumen, Quartz, Calcite, Mica
M-01A	Grout	100%	Quartz, Calcite, Clay, Mica
M-01B	Grout	100%	Quartz, Calcite, Clay, Mica
M-02A	Vapor Barrier	100%	Cellulose/paper
M-02B	Vapor Barrier	100%	Cellulose/paper

Analyst / Approved Signatory:

Darryl Neldner

* Polarized Light Microscopy coupled with dispersion is the technique used for identification in accordance with EPA 600/M4-82-020, EPA 600/R-93/116, and NIOSH Method 9002.

** The percentage of each component is visually estimated. The result of this analysis relate only to the material tested. The report shall not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. (>1% greater than one percent, <1% less than one percent) QC - Sample reanalyzed for QA/QC.

*** This report shall not be reproduced except in full, without the written approval of the laboratory. GLE Report # 21487

Analysis performed by GLE Associates, Inc. NVLAP Code 102003-0, CO AL-17485, TX 30-0337

Feedback regarding laboratory performance should be addressed to lab@gleassociates.com.

Report Date: 8/3/2017

CHAIN OF CUSTODY/SAMPLE TRANSMITTAL FORM

GLE Associates, Inc.
8659 Baypine Road, Suite 306
Jacksonville, FL 32256
PHONE: (904) 296-1880 FAX: (904) 296-1860

CLIENT:	ERS
PROJECT #:	17000-R020
PROJECT:	416 Escambia dr.
LABORATORY SENT TO:	TAMPA
DATE:	8/2/2017

21487

SAMPLE INFORMATION

SAMPLE #	DESCRIPTION	SAMPLE #	DESCRIPTION
FT-01AB	12x12 Gray floor tile w/black mastic		
FT-02AB	12x12 tan floor tile w/black mastic + backing		
MSV-01AB	Square vinyl sheet flooring w/tan mastic		
MSV-02AB	Floral vinyl sheet flooring w/ tan mastic		
PL-01ABC	Plaster		
RS-01AB	Asphalt roof shingles		
M-01AB	Grout		
M-02AB	Vapor barrier		

IMPORTANT: TOTAL NUMBER OF SAMPLES SUBMITTED	17
IMPORTANT: POSITIVE STOP ANALYSIS	Yes
IMPORTANT: E-MAIL RESULTS TO	Jelliott@gleassociates.com Acanfado @gleassociates.com

NOTE:
Turnaround time starts at receipt by lab and does not include weekend or holidays.

Select Turnaround Time

☐ 3 hour ☐ 6 Hour ☐ 24 Hour ☐ 48 Hour ☐ 3 Day ☑ 4 Day

REPORT RESULTS TO THE ADDRESS ABOVE

CHAIN OF CUSTODY: GLE ASSOCIATES, INC.	CHAIN OF CUSTODY: LABORATORY
PACKAGED BY: Stephanie Whitney	SAMPLES RECEIVED BY:
DATE PACKAGED: 8/2/2017	DATE:
METHOD OF TRANSMITTAL: Fed Ex	TIME:
TRANSMITTED BY:	CONDITION OF PACKAGED SAMPLES:

8-3-17

CHAIN OF CUSTODY: RETURNED TO GLE ASSOCIATES, INC.	
RECEIVED BY:	DATE:
INVENTORIED BY:	DATE:
REPACKAGED AND SEALED BY:	DATE:

PAGE: 1 OF 1

APPENDIX B
Personnel and Laboratory Certifications

STATE OF FLORIDA
DEPARTMENT OF BUSINESS AND PROFESSIONAL REGULATION

ASBESTOS LICENSING UNIT
1940 NORTH MONROE STREET
TALLAHASSEE FL 32399-0783

(850) 487-1395

GLE ASSOCIATES INC
5405 CYPRESS CENTER DRIVE
SUITE 110
TAMPA FL 33609

Congratulations! With this license you become one of the nearly one million Floridians licensed by the Department of Business and Professional Regulation. Our professionals and businesses range from architects to yacht brokers, from boxers to barbeque restaurants, and they keep Florida's economy strong.

Every day we work to improve the way we do business in order to serve you better. For information about our services, please log onto **www.myfloridalicense.com**. There you can find more information about our divisions and the regulations that impact you, subscribe to department newsletters and learn more about the Department's initiatives.

Our mission at the Department is: License Efficiently, Regulate Fairly. We constantly strive to serve you better so that you can serve your customers. Thank you for doing business in Florida, and congratulations on your new license!

STATE OF FLORIDA
DEPARTMENT OF BUSINESS AND
PROFESSIONAL REGULATION

ZA0000034 ISSUED: 12/01/2015

ASBESTOS BUSINESS ORGANIZATION
GLE ASSOCIATES INC

IS LICENSED under the provisions of Ch.469 FS.
Expiration date : NOV 30, 2017 L1512010002475

DETACH HERE

RICK SCOTT, GOVERNOR

KEN LAWSON, SECRETARY

STATE OF FLORIDA
DEPARTMENT OF BUSINESS AND PROFESSIONAL REGULATION
ASBESTOS LICENSING UNIT

LICENSE NUMBER	
ZA0000034	

The ASBESTOS BUSINESS ORGANIZATION
Named below IS LICENSED
Under the provisions of Chapter 469 FS.
Expiration date: NOV 30, 2017

GLE ASSOCIATES INC
5405 CYPRESS CENTER DRIVE
SUITE 110
TAMPA FL 33609

ISSUED: 12/01/2015 DISPLAY AS REQUIRED BY LAW SEQ # L1512010002475

STATE OF FLORIDA
DEPARTMENT OF BUSINESS AND PROFESSIONAL REGULATION

ASBESTOS LICENSING UNIT
2601 BLAIR STONE ROAD
TALLAHASSEE FL 32399-0783

(850) 487-1395

GREENE, ROBERT BLAIR
GLE ASSOCIATES INC
5405 CYPRESS CENTER DR
SUITE 110
TAMPA FL 33609

Congratulations! With this license you become one of the nearly one million Floridians licensed by the Department of Business and Professional Regulation. Our professionals and businesses range from architects to yacht brokers, from boxers to barbeque restaurants, and they keep Florida's economy strong.

Every day we work to improve the way we do business in order to serve you better. For information about our services, please log onto **www.myfloridalicense.com**. There you can find more information about our divisions and the regulations that impact you, subscribe to department newsletters and learn more about the Department's initiatives.

Our mission at the Department is: License Efficiently, Regulate Fairly. We constantly strive to serve you better so that you can serve your customers. Thank you for doing business in Florida, and congratulations on your new license!

STATE OF FLORIDA
DEPARTMENT OF BUSINESS AND
PROFESSIONAL REGULATION

EA0000009 ISSUED: 11/15/2016

ASBESTOS CONSULTANT - ENGINEER
GREENE, ROBERT BLAIR
GLE ASSOCIATES INC

IS LICENSED under the provisions of Ch.469 FS.
Expiration date : NOV 30, 2018 L1611150002176

DETACH HERE

RICK SCOTT, GOVERNOR

KEN LAWSON, SECRETARY

STATE OF FLORIDA
DEPARTMENT OF BUSINESS AND PROFESSIONAL REGULATION
ASBESTOS LICENSING UNIT

LICENSE NUMBER	
EA0000009	

The ASBESTOS CONSULTANT - ENGINEER
Named below IS LICENSED
Under the provisions of Chapter 469 FS.
Expiration date: NOV 30, 2018

GREENE, ROBERT BLAIR
GLE ASSOCIATES INC
5405 CYPRESS CENTER DR
SUITE 110
TAMPA FL 33609

ISSUED: 11/15/2016 DISPLAY AS REQUIRED BY LAW SEQ # L1611150002176

The Environmental Institute

Ryan Hendry

Social Security Number - XXX-XX-9463

GLE Associates, Inc. - 5405 Cypress Center Drive, Suite 110 - Tampa, Florida 33609

Has completed coursework and satisfactorily passed

an examination that meets all criteria required for

EPA/AHERA/ASHARA (TSCA Title II) Approved Accreditation

Asbestos in Buildings: Inspection and Assessment

August 15-17, 2016
Course Date

4862
Certificate Number

August 17, 2016
Examination Date

August 16, 2017
Expiration Date

David W. Hogue - Principal Instructor / Training Manager

Rachel G. McCain - Exam Administrator

(Approved by the ABIH Certification Maintenance Committee for 3 CM points - Approval #11-529)
(Florida Provider Registration Number FL49-0001342 - Course #FL49-0004700)

TEI - 1841 West Oak Parkway, Suite F - Marietta, Georgia 30062 - (770) 427-3600 - www.tei-atl.com

Asbestos Online Training, LLC

13987 94th Avenue N Seminole, FL 33776

727-593-3067

Asbestos Survey & Mechanical (AHERA Building Inspector) Refresher Training

This is to certify that

Stephanie Whitney

Training was in accordance with Title II of TSCA, 40 CFR Part 763. Appendix C to Subpart E as revised

Date of Course Examination 2/17/17

Date of Course Completion 2/17/17

Expiration Date 2/17/18

Certificate # 21717526

Course # FL-490006359 Provider # FL-490005406

INSTRUCTOR

United States Department of Commerce
National Institute of Standards and Technology

Certificate of Accreditation to ISO/IEC 17025:2005

NVLAP LAB CODE: 102003-0

GLE Associates, Inc.

Tampa, FL

is accredited by the National Voluntary Laboratory Accreditation Program for specific services, listed on the Scope of Accreditation, for:

Asbestos Fiber Analysis

This laboratory is accredited in accordance with the recognized International Standard ISO/IEC 17025:2005. This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory quality management system (refer to joint ISO-ILAC-IAF Communique dated January 2009).

2017-04-01 through 2018-03-31

Effective Dates

For the National Voluntary Laboratory Accreditation Program

TITLE: DEMO & SITE CLEARANCE OF 40 PROPERTIES

BID NO.: CF-0088-17 (MUNICIPAL CODE)

OPEN DATE: MARCH 1, 2017 @ 2PM

BUYER: MARILYN LAIDLER, PURCHASING ANALYST

NO. INVITED (7) NO RECVD (3) NO BID(0)

ITEM	DESCRIPTION	P & G LAND CLEARING, INC				MICHAEL LLOYD HAULING, INC				ERS CORP			
		ASBESTOS SURVEY	ASBESTOS FREE DEMO	EXTENDED TOTAL	WET DEMOLITION	ASBESTOS SURVEY	ASBESTOS FREE DEMO	EXTENDED TOTAL	WET DEMOLITION	ASBESTOS SURVEY	ASBESTOS FREE DEMO	EXTENDED TOTAL	WET DEMOLITION
1	**2055 ALLEY ROAD**, (UNIT 2063, MAIN STRUCTURE AND ACCESSORY BEHIND MAIN STRUCTURE) DESCRIBED AS: 17-41 08-2S-29E 1.08 CLARSONS COLORED S/D PT LOT 13 PT LOTS 10, 11 RECD O/R 12261-2086 (DEMOLITION AND SITE CLEARANCE) R.E. #169482-0000 (CONTRACTOR MUST SUBMIT A BID FOR THE COST OF AN ASBESTOS SURVEY AND WET DEMOLITION) (GREATER ARLINGTON)	NO BID	NO BID	NO BID	NO BID	NO BID	NO BID	NO BID	NO BID	$ 275.00	$ 3,000.00	$ 3,275.00	$ 1,000.00
2	**1588 ANDERSON STREET** (SINGLE FAMILY) DESCRIBED AS; 8-44 39-1S-26E .198 PICKETTS S/D SIBBALD GRANT PT LOT 2 RECD O/R 8416-2113 (EX R/W) (DEMOLITION AND SITE CLEARANCE) R.E. #022748-0000 (CONTRACTOR MUST SUBMIT A BID FOR THE COST OF AN ASBESTOS SURVEY AND A WET DEMOLITION) (NORTH)	$ 275.00	$ 6,975.00	$ 7,250.00	$ 1,000.00	$ 275.00	$ 4,400.00	$ 4,675.00	$ 5,875.00	$ 275.00	$ 4,257.00	$ 4,532.00	$ 1,000.00
3	**824 BAKER AVENUE**, (SINGLE FAMILY) DESCRIBED AS: 8-23 41-2S-26E EASTBROOK ANNEX LOT 5 BLK B (DEMOLITION AND SITE CLEARANCE) R.E. #077513-0000 (CONTRACTOR MUST SUBMIT A BID FOR COST OF AN ASBESTOS SURVEY AND WET DEMOLITION) (NORTHWEST)	NO BID	NO BID	NO BID	NO BID	NO BID	NO BID	NO BID	NO BID	$ 275.00	$ 4,000.00	$ 4,275.00	$ 1,000.00
4	**1817 BENNETT STREET** (MAIN AND ACCESSORY) DESCRIBED AS; 08-2S-27E R/P OF GLEN MYRA LOT P BLK 8 (DEMOLITION AND SITE CLEARANCE) R.E. #115720-0000 (CONTRACTOR MUST SUBMIT A BID FOR COST OF AN ASBESTOS SURVEY AND WET DEMOLITON) (URBAN CORE)	$ 475.00	$ 5,250.00	$ 5,725.00	$ 1,200.00	$ 275.00	$ 4,800.00	$ 5,075.00	$ 6,275.00	$ 275.00	$ 4,875.00	$ 5,150.00	$ 1,000.00
5	**1826 BRACKLAND STREET**, (SINGLE FAMILY) DESCRIBED AS; 6-95 08-2S-27E R/P OF GLEN MYRA LOT 3 BLK 5 (DEMOLITION AND SITE CLEARANCE) R.E. #115686-0000 (CONTRACTOR MUST SUBMIT A BID FOR THE COST OF AN ASBESTOS SURVEY AND WET DEMOLITION) (URBAN CORE)	$ 375.00	$ 4,525.00	$ 4,900.00	$ 1,000.00	$ 275.00	$ 3,600.00	$ 3,875.00	$ 4,075.00	$ 275.00	$ 3,565.00	$ 3,840.00	$ 2,500.00
6	**1328 CARVILL AVENUE**, (SINGLE FAMILY) DESCRIBED AS:18-66 39-1S-26E CARVILL PARK S/D PT LOT 2 PICKETTS S/D LOT 52 (DEMOLITION AND SITE CLEARANCE) R.E. #022731-0000 (CONTRACTOR MUST SUBMIT A BID FOR THE COST OF AN ASBESTOS SURVEY AND WET DEMOLITION) (NORTH)	$ 275.00	$ 4,175.00	$ 4,450.00	$ 1,000.00	$ 275.00	$ 5,000.00	$ 5,275.00	$ 6,475.00	$ 275.00	$ 3,237.00	$ 3,512.00	$ 2,300.00
7	**918 DEERWOOD CIRCLE SOUTH**, (SINGLE FAMILY) DESCRIBED AS: 21-46 39-1S-26E HOLMESDALE UNIT 2 S/D PT LOTS 57,58 RECD O/R 7743-684 BLK 2 (DEMOLITION AND SITE CLEARANCE) R.E. #022953-0000(CONTRACTOR MUST SUBMIT A BID FOR THE COST OF ASBESTOS SURVEY AND A WET DEMOLITION) (NORTH)	$ 1,000.00	$ 7,975.00	$ 8,975.00	$ 1,000.00	$ 275.00	$ 9,800.00	$ 10,075.00	$ 12,575.00	$ 275.00	$ 6,100.00	$ 6,375.00	$ 3,400.00
8	**5803 DOEBOY STREET**, (SINGLE FAMILY) DESCRIBED AS: 18-64 39-1S-26E OAK HEIGHTS ADDN S/D PT LOT 2 PICKETTS S/D W 1/2 LOT 20 (DEMOLITION AND SITE CLEARANCE) R.E. #023006-0000 (CONTRACTOR MUST SUBMIT A BID FOR THE COST OF AN ASBESTOS SURVEY AND WET DEMOLITION) (NORTH)	$ 275.00	$ 5,225.00	$ 5,500.00	$ 1,000.00	$ 275.00	$ 4,200.00	$ 4,475.00	$ 5,675.00	$ 275.00	$ 4,117.00	$ 4,392.00	$ 1,000.00
9	**5921 DROAD STREET**, (SINGLE FAMILY) DESCRIBED AS; 39-1S-26E RUTLEDGES S/D LOT 20 PICKETTS S/D PT LOT 41 RECD O/R BK 1374-421 (DEMOLITION AND SITE CLEARANCE) R.E. #026328-0000 (CONTRACTOR MUST SUBMIT A BID FOR THE COST OF AN ASBESTOS SURVEY AND WET DEMOLITON) (NORTH)	$ 275.00	$ 4,975.00	$ 5,250.00	$ 1,000.00	$ 275.00	$ 6,800.00	$ 7,075.00	$ 8,575.00	$ 275.00	$ 3,685.00	$ 3,960.00	$ 1,000.00
10	**824 EAVERSON STREET** (SINGLE FAMILY) DESCRIBED AS; 2-27 40-2S-26E AUBERTS S/D JAX S 26.5FT LOT 2, N 7FT LOT 3 BLK 17 (DEMOLITION AND SITE CLEARANCE) R.E. #075746-0000 (CONTRACTOR MUST SUBMIT A BID FOR THE COST OF AN ASBESTOS SURVEY AND WET DEMOLITION) (NORTHWEST)	$ 275.00	$ 4,525.00	$ 4,800.00	$ 1,000.00	NO BID	NO BID	NO BID	NO BID	$ 275.00	$ 3,000.00	$ 3,275.00	$ 1,000.00
11	**646 ESCAMBIA STREET**, (MAIN AND ACCESSORY STRUCTURE) DESCRIBED AS; 5-19 35-1S-26E NORWOOD LOT 8, E 3FT LOT 9 BLK 20 (DEMOLITION AND SITE CLEARANCE) R.E. #031928-0000 (CONTRACTOR MUST SUBMIT A BID FOR THE COST OF AN ASBESTOS SURVEY AND WET DEMOLITION) (NORTH)	$ 475.00	$ 6,325.00	$ 6,800.00	$ 1,200.00	$ 275.00	$ 4,900.00	$ 5,175.00	$ 6,375.00	$ 275.00	$ 4,858.00	$ 5,133.00	$ 1,000.00

SUBJECT: **DEMO & SITE CLEARANCE OF 40 PROPERTIES**

BID# CF-0088-17 OPEN DATE: **2017-03-01**

GENERAL GOVERNMENT AWARDS COMMITTEE

KIND AND BASIS OF CONTRACT:
CONSTRUCTION FIXED

AGENCY: **MUNICIPAL CODE**

BASIS OF AWARD: **BY ITEM TO THE LOWEST RESPONSIVE, RESPONSIBLE BIDDER**

NUMBER OF BIDS INVITED 7 NUMBER RECEIVED 3 OTHER 0

SUMMARY OF BIDS AND RECOMMENDED ACTIONS:

Recommend approval of award to the lowest responsive, responsible bidder(s) as follows: ERS, Corp., bid item(s): 2, 5, 6, 7, 8, 9, 10, 11, 12, 14, 15, 16, 17, 18, 19, 20, 21, 23, 25, 26, 27, 28, 31, 33, 35, 36 and 39 in the amount of $115,150.25; Michael Lloyd Hauling bid item(s): 4, 13, 32 and 34 in the amount of $18,700.00; and P & G Land Clearing, Inc., bid item(s); 22, 24, 29, 30, 37, and 40 in the amount of $38,600.00. Total award amount not-to-exceed $172,450.25.

Items 1 and 38 will not be awarded. Item 3 has been demolished.

This award to be funded by account: ERCD1N1FR-03410 to be executed by Purchase Order(s).

Attachments: Recommendation Memo, Bid Tabulation Sheet, Terms & Conditions

BUYER: Marilyn Laidler
MARILYN LAIDLER

RESPECTFULLY SUBMITTED: _____
GREGORY PEASE, CHIEF
PROCUREMENT DIVISION

CONCURRENCE BY: **Bryan Mosier, Chief, Municipal Code Compliance Division**

(ALL AWARD ACTIONS SUBJECT TO LAWFULLY APPROPRIATED FUNDS)

ACTION OF GGAC COMMITTEE ON RECOMMENDATIONS ABOVE

MEMBERS APPROVING 3 MEMBERS DISAPPROVING Ø DATE: 3/16/17

Teresa R. Eichner _____ OTHER: _____

_____ _____

_____ _____

ACTION OF AWARDING AUTHORITY DATE: 3/16/17

APPROVED _____ DISAPPROVED _____

OTHER _____

SIGNATURE OF AUTHENTICATION _____

Sam E. Mousa
Chief Administrative Officer
For: Mayor Lenny Curry
Under Authority of:
Executive Order No. 2015-05

FORM GB 108 Rev. 2015-05

QWS3270X 10/23/2017 2:11 PM
FAML6350 V5.1 ** NW COJ FAMIS PRODUCTION ** 10/23/2017
LINK TO: ACCOUNT SUMMARY INQUIRY 1:39 PM

FISCAL MO/YEAR : 01 2018 CURRENCY CODE :
INDEX CODE : ERCC1L2CP MUNICIPAL CODE COMPLIANCE
SUBOBJECT : 03410 CONTRACTUAL SERVICES
PROJECT :
PROJECT DETAIL :
GRANT :
GRANT DETAIL :
USER CODE :

S	OCT 2017	ANNUAL BALANCE	ALL YEARS BALANCE
ESTIMATED REVENUES	.00	.00	.00
REVENUES	.00	.00	.00
UNREALIZED REVENUES	.00	.00	.00
BUDGET	494,410.00	494,410.00	2,128,692.79
EXPENDITURES	.00	.00	1,040,733.12
ENCUMBRANCES	.00	.00	492,240.41
PRE-ENCUMBRANCES	.00	.00	.00
REMAINING BALANCE	494,410.00	494,410.00	595,719.26

F1-HELP F2-SELECT F4-PRIOR F5-NEXT
F9-LINK F10-PRIOR-MO F11-NEXT-MO
G005 - PRIOR RECORD DISPLAYED